

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21006259/BTF3Q2
Date: 23/06/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900147466
Claimant Vehicle No :	SKZ8243X	Insured Vehicle No :	SKT1806A
Date of Loss:	28/05/2021	Nature of Claim:	TP
		Claim No:	2950243296SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKZ8243X	Engine No:	MR20815082B
Make & Model:	HONDA ACCORD, 1.6 (M)	Chassis No:	JN1JANT32Z0001402
Reg. Date:	04/02/2016 (Man. Year: 2015)	Odometer:	82232 km
Colour:	Red		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/60 R18	Rear Tyre Size:	225/60 R18
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

6/23/2021

Adjuster Report

Date of Assignment: 31/05/2021

Date Inspected: 01/06/2021

Estimated Period of Repair: 5.0 days

Inspected At:

BLK 7 SIN MING IND EST SEC C #01-80
Repairer:Yap Motor Service Pte Ltd (HQ)

Adjuster: Lim Teow Guan

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

6/23/2021

Adjuster Report

MARKET VALUE:\$63,000.00

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH DOOR	Dented	0.00 F	*- F
2	1		*REAR BUMPER	Cut	0.00 F	*- F
3	1		*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
4	1		*REAR RH FENDER	Dented	0.00 F	*- F
5	1		*REAR WHEEL ARCH GARNISH	Cut	0.00 F	*- F
6	1		*REAR SHOCK ABSORBER	Bent	0.00 F	*- F
7	1		*REAR WHEEL BEATING	Jammed	0.00 F	*- F
8	1		*REAR LIGHT SUB FRAME	Repair	0.00 F	*- F

F=Franchise part.

Total Parts (\$)
0.00
0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >