



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref:	CS3/ASM21002912/T1qf3e2-1
8 SHENTON WAY #24-01		Date:	25/06/2021
AXA TOWERSINGAPORE 068811		Code:	ASM
ATTN: TAN JUN HONG			
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)			
Insured Veh.	SHC 1392B	Veh. Inspected	SMT 9516K
Policy No.		Coverage (\$)	0.00
Claim No.	S1M034B3	Excess (\$)	0.00
Assign From	TAN JUN HONG	Assign Date	31/05/2021
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI AVANTE	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	KMHD841CMLU095217	Colour	WHITE
Odometer	8964 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55 R16	KUMHO	7 mm
L/H Front Tyre	205/55 R16	KUMHO	7 mm
R/H Rear Tyre	205/55 R16	KUMHO	7 mm
L/H Rear Tyre	205/55 R16	KUMHO	7 mm
4. Description of Damages			
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.			
REPAIR CONDITION SEE DETAILS.			
5. General Information			
Accident Date	01/03/2021	Inspection Date	02/06/2021
Survey held at	1 KAKI BUKIT AVE 6 #01-27/01-45 SINGAPORE 417883		
Repairer	ALPHA CAR SERVICES PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.			
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		20 Working Days	