

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG21006267/T1QF3E2

**Date:** 03/09/2021

### REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001624024		
<b>Claimant Vehicle No :</b>	SLP1925Z	<b>Insured Vehicle No :</b>	SLV1582Y		
Date of Loss:	30/05/2021	Nature of Claim:	TP	Claim No:	257990

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLP1925Z</b>	Engine No:	27186030024902
Make & Model:	MERCEDES-BENZ C200, 1.8 CGI (A)	Chassis No:	WDD2040482A360383
Reg. Date:	11/05/2010 (Man. Year: 2009)	Odometer:	99532 km
Colour:	Black		
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,438.20	5,752.20	15,686.00	73.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,340.00	960.00	5,380.00	84.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>27,778.20</b>	<b>6,712.20</b>	<b>21,066.00</b>	<b>75.84</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,350.00</b>		
<b>Nett Amount (S\$)</b>	<b>27,778.20</b>	<b>5,350.00</b>	<b>22,428.20</b>	<b>80.74</b>

### INSPECTION

Date of Assignment:	31/05/2021	Xin Yun Auto Pte Ltd (kaki Bukit) (HQ) 8 Kaki Bukit Avenue 4, #05-23 Premier @ Kaki Bukit Singapore 415875
Date Inspected:	01/06/2021 Inspected At:	
Estimated Period of Repair:	4.0 days	

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 03 Sep 2021)
<b>Parts:</b>	143	MERCEDES-BENZ C200 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLP1925Z)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER ASSY	Deformed	1,590.00 F	*1,380.00 FL
2	1		*FRONT BUMPER BRACKET LEFT	Deformed	295.00 F	*76.00 FL
3	1		*FRONT BUMPER SIDE METAL PIECE LEFT	Bent	125.00 F	*125.00 FL
4	1		*FRONT BUMPER REINFORCEMENT	Bent	548.00 F	*300.00 FL
5	1		*INSIDE BUMPER SPONGE	Deformed	195.00 F	*168.00 FL
6	1		*BUMPER LOWER LIP	Deformed	295.00 F	*295.00 FL
7	1		*FRONT BUMPER LOWER GRILLE	Deformed	285.00 F	*135.00 FL
8	1		*FRONT BUMPER LOWER SILVER CHROME BOTH SIDE	Necessary	205.00 F	*205.00 FL
9	1		*FRONT BUMPER TOW COVER	Not Necessary	85.00 F	*- FL
10	2		*FOG LAMP COVER LEFT	Not Necessary	280.00 F	*- FL
11	1		*FOG LAMP INNER BASE CHROME	Not Necessary	150.00 F	*- FL
12	2		*FOG LAMP SILVER LINING	Not Necessary	190.00 F	*- FL
13	1		*FOG LAMP	Not Necessary	285.00 F	*- FL
14	1		*FRONT GRILLE ASSY	Cut	565.00 F	*412.00 FL
15	1		*FRONT GRILL BASE	Cracked	268.00 F	*155.00 FL
16	1		*FRONT GRILL TOP SILVER LINING	Not Necessary	135.00 F	*- FL
17	1		*FRONT EMBLEM	Necessary	98.00 F	*98.00 FL
18	1		*FRONT TOP COVER TRIM	Not Necessary	225.00 F	*- FL
19	1		*FRONT BONNET ASSY	Repair	2,250.00 F	*- FL
20	1		*FRONT BONNET LOCK	Not Necessary	185.00 F	*- FL
21	1		*SENSOR LINE CABLE	Not Necessary	296.00 F	*- FL
22	1		*FRONT SUPPORT PANEL ASSY	Repair	348.00 F	*- FL
23	1		*LOWER COVER	Deformed	323.00 F	*265.00 FL
24	1		*FRONT RIGHT HEADLAMP	Not Necessary	1,590.00 F	*- FL
25	1		*FRONT LEFT HEADLAMP	Cracked	1,590.00 F	*999.00 FL
26	1		*FRONT RIGHT HEADLAMP LOWER BRACKET	Not Necessary	205.00 F	*- FL
27	1		*FRONT LEFT HEADLAMP LOWER BRACKET	Not Necessary	205.00 F	*- FL
28	1		*FRONT RIGHT LAMP CONTROL UNIT	Not Necessary	650.00 F	*- FL
29	1		*INTERCOOLER	Not Necessary	1,415.00 F	-
30	1		*INTERCOOLER FRAME TRIM	Not Necessary	293.00 F	*- FL
31	2		*INTERCOOLER COVER	Deformed	90.00 F	*90.00 FL
32	1		*CONDENSER	Dented	1,452.00 F	*955.00 FL
33	2		*CONDENSER FRAME SUPPORT	Not Necessary	500.00 F	*- FL
34	1		*FANMOTOR	Not Necessary	965.00 F	*- FL
35	2		*WATER PUMP HOSE	Not Necessary	275.20 F	*- FL
36	1		*RADIATOR	Not Necessary	932.00 F	*- FL
37	1		*RADIATOR GRILLE	Not Necessary	850.00 F	*- FL
38	10		*FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
39	6		*FRONT BUMPER LOWER COVER CLIPS	Not Necessary	40.00 FS	*- FS
40	8		*FRONT FENDER CLIPS	Not Necessary	40.00 FS	*- FS
41	6		*INSULATOR CLIPS	Not Necessary	30.00 FS	*- FS
42	6		*BONNET SEAL CLIPS	Not Necessary	50.00 FS	*- FS
43	2		*SENSOR / DISTANCE SENSOR	Not Working	600.00 FS	*450.00 FS
44	8		*FRONT SUPPORT PANEL GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
45	1		*FRONT NO PLATE WITH CASING	Bent	80.00 FS	*45.00 FS
46	1		*LICENSE PLATE HOLDER	Deformed	135.00 FS	*135.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*SEALANT FOR FRONT END PANEL	Not Necessary	60.00 FS	*- FS
48	1		*SEALANT FOR FRONT SIDE PANEL	Not Necessary	60.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					21,438.20	6,318.00
- List Item Discount on L Items 0.00/10.00% (\$\$)					0.00	565.80
Total Parts (\$\$)					21,438.20	5,752.20

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN FRONT AFFECTED AREA AND REPLACE FRONT DAMAGED PARTS, BODY MAIN FRAME AFFECTED	New	2,500.00	400.00
2	TO PUTTY AND SPRAY PAINTING FRONT PORTION	New	2,000.00	400.00
3	TO CHECK WIRING AND FOCUS FRONT HEADLAMP	New	80.00	30.00
4	TO APPLY ANTI RUST PROOFING TO FRONT AFFECTED AREA	New	200.00	0.00
5	TO REMOVE AND INSTALL FRONT UNDERCARRIAGE PARTS	New	150.00	0.00
6	TO BALANCE FRONT RIGHT WHEEL	New	80.00	0.00
7	TO CONDUCT WHEEL ALIGNMENT	New	120.00	0.00
8	TO REMOVE AND INSTALL FRONT BONNET LOCK MECHANISM ASSY	New	100.00	0.00
9	TO CONDUCT CHASSIS ALIGNMENT	New	350.00	0.00
10	TO REMOVE AND INSTALL CONDENSOR AND CHECK LEAKAGE	New	150.00	100.00
11	TO REMOVE AND INSTALL RADIATOR AND CHECK LEAKAGE	New	150.00	0.00
12	TO REMOVE AND INSTALL INTERCOOLER AND MONITOER PERFORMANCE	New	150.00	0.00
13	TO REMOVE AND INSTALL HORN AND CHECK HORN WIRING	New	80.00	0.00
14	TO REMOVE AND INSTALL COMPRESSOR AND MONITOR PERFORMANCE	New	150.00	0.00
15	TO REMOVE AND INSTALL BUMPER SENSOR	New	80.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>6,340.00</b>	<b>960.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >