

ASS. REC. BY: TaufikhREF: CS/MSG 21006267/T1983

## ASSIGNMENT

GE 2029 Sep

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. 30001624024Claims No. 257990

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 462K

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SLP1925ZYr Regn: May, 2010

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Mercedes Benz C200c.c. 1796Colour: Black

A/C: Insured / Std / NI / NA

Sp. Reading: 99532

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WDD2040482A360383

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R17R: 225/45R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. \_\_\_\_\_

D.O.I. 1/6/21 @ 1220pmSurvey held at Xin yun

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time Action / Instruction

04/06/21 @ 5.58pm revised to Nor Azian via merimen.

11/08/21 EMAIL NOR AZIAN, SEEK MANDATE APPROVAL.

01/09/21 NOR AZIAN EMAIL US TO REQUEST SUBMIT REPORT.

Taufikh said submit LS \$5350, 4 days. (Red \$22428.20, 81%)

Date/Time, File Pass to?

☐

: Preli. Report

1) 01/09 Typist

☐

: Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Report Form: MER-TPLump Sum / LS: 5350Days Of Repair: 4Resurvey No. of Trip: 2Add Fee: ☐

: Site Insp (\$ \_\_\_\_\_)

☐

: Interview (\$ \_\_\_\_\_)

☐

: Tech. Invs (\$ \_\_\_\_\_)

☐

: Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + RS: \_\_\_\_\_ SI

Photos \_\_\_\_\_

Others \_\_\_\_\_

TOTAL



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SLP1925Z Mercedes C200

No	Qty	Parts Description	Estimated Parts Price
1	1	Front bumper assy	\$ 1,590.00 <i>del</i>
2	1	Front bumper bracket left	\$ 295.00 <i>del</i>
3	1	Front bumper side metal piece left	\$ 125.00 <i>del</i>
4	1	Front bumper reinforcement	\$ 548.00 <i>del</i>
5	1	Inside bumper sponge	\$ 195.00 <i>del</i>
6	1	Bumper lower lip	\$ 295.00 <i>del</i>
7	1	Front bumper lower grille	\$ 285.00 <i>del</i>
8	1	Front bumper lower silver chrome both side	\$ 205.00 <i>del</i>
9	1	Front bumper tow cover	\$ 85.00 <i>X</i>
10	2	Fog lamp cover left	\$ 280.00 <i>X</i>
11	1	Fog lamp inner base chrome	\$ 150.00 <i>X</i>
12	2	Fog lamp silver lining	\$ 190.00 <i>X</i>
13	1	Fog lamp	\$ 285.00 <i>X</i>
14	1	Front grille assy	\$ 565.00 <i>del</i>
15	1	Front grill base	\$ 268.00 <i>del</i>
16	1	Front grill top silver lining	\$ 135.00 <i>X</i>
17	1	Front emblem	\$ 98.00 <i>del</i>
18	1	Front top cover trim	\$ 225.00 <i>X</i>
19	1	Front bonnet assy	\$ 2,250.00 <i>X</i>
20	1	Front bonnet lock	\$ 185.00 <i>X</i>
21	1	Sensor line cable	\$ 296.00 <i>X</i>
22	1	Front support panel assy	\$ 348.00 <i>del</i>
23	1	Lower end carrier <i>cover</i>	\$ 323.00 <i>del</i>
24	1	Front right headlamp	\$ 1,590.00 <i>X</i>
25	1	Front left headlamp	\$ 1,590.00 <i>del</i>
26	1	Front right headlamp lower bracket	\$ 205.00 <i>X</i>
27	1	Front left headlamp lower bracket	\$ 205.00 <i>X</i>
28	1	Front right lamp control unit	\$ 650.00 <i>X</i>
29	1	Intercooler	\$ 1,415.00 <i>del</i>
30	1	Inercooler frame trim	\$ 293.00 <i>X</i>
31	2	Inintercooler cover	\$ 90.00 <i>del</i>
32	1	Condenser	\$ 1,452.00 <i>del</i>
33	2	Condenser frame support	\$ 500.00 <i>X</i>
34	1	Fanmotor	\$ 965.00 <i>X</i>
35	2	Water pump hose	\$ 275.20 <i>X</i>
36	1	Radiator	\$ 932.00 <i>X</i>
37	1	Radiator grille	\$ 850.00 <i>X</i>
Sub-total			\$ 20,233.20



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SLP1925Z Mercedes C200

No	Qty	Parts Description	Estimated Parts Price
<u>Special Nett Items</u>			
1	10	Front bumper clips	\$ 80.00 <i>3 One ✓</i>
2	6	Front bumper lower cover clips	\$ 40.00 <i>X</i>
3	8	Front fender clips	\$ 40.00 <i>X</i>
4	6	Insulator clips	\$ 30.00 <i>X</i>
5	6	Bonnet seal clips	\$ 50.00 <i>X</i>
6	2	Sensor /distance sensor	\$ 600.00 <i>1w / 400</i>
7	8	Front support panel garnish clips	\$ 30.00 <i>X</i>
8	1	Front no plate with cashing	\$ 80.00 <i>45 b7 ✓</i>
9	1	License plate holder	\$ 135.00 <i>de ✓</i>
10	1	Sealant for front end panel	\$ 60.00 <i>X</i>
11	1	Sealant for front side panel	\$ 60.00 <i>X</i>
<u>Special Nett Items</u>			<u>\$ 1,205.00</u>
<b>Total parts</b>			<b>\$ 21,438.20</b>





Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SLP1925Z Mercedes C200

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front affected area and replace front damaged parts, body main frame affected	\$ 2,500.00 400.
2	To putty and spray painting front portion.	\$ 2,000.00 200400
3	To check wiring and focus front headlamp.	\$ 80.00 30
4	To apply anti rust proofing to front affected area.	\$ 200.00 X
5	To remove and install front undercarriage parts.	\$ 150.00 X
6	To balance front right wheel.	\$ 80.00 X
7	To conduct wheel alignment.	\$ 120.00 X
8	To remove and install front bonnet lock mechanism assy.	\$ 100.00 X
9	To remove and install bumper sensor.	\$ 80.00 30
10	To conduct chassis alignment.	\$ 350.00 X
11	To remove and install condensor and check leakage	\$ 150.00 100.
12	To remove and install radiator and check leakage	\$ 150.00 X
13	To remove and install intercooler and monitoer performance	\$ 150.00 60.
14	To remove and install horn and check horn wiring	\$ 80.00 X
15	To remove and install compressor and monitor performance	\$ 150.00 X
Total labour :		\$ 6,340.00

Total Part 67,348.50  
Total labour : 6,340.00  
Total repair cost : 73,688.50

Tanphin 17495749

'WP' 4/5 Resurvey after repair

1/6/21

tanphin@khauto.com

04 days

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: