

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21006277/DGS3Q2**Date:** 17/01/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100474619
Claimant Vehicle No :	GBK2924P	Insured Vehicle No :	SGK8223E
Date of Loss:	28/05/2021	Nature of Claim:	TP
		Claim No:	4291227391SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBK2924P	Engine No:	1GD8425139
Make & Model:	TOYOTA HIACE, 2.8 D DX (A)	Chassis No:	GDH2012006216
Reg. Date:	20/03/2020 (Man. Year: 2019)	Odometer:	25359 km
Colour:	Silver		
Engine Capacity:	2754 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,236.95	6,762.01	17,474.94	72.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,670.00	2,480.00	3,190.00	56.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,906.95	9,242.01	20,664.94	69.10
Approved Total (Overridden) (S\$)		7,400.00		
(S\$)	29,906.95	7,400.00	22,506.95	75.26
+ GST 7.00/7.00% (S\$)	2,093.49	518.00	1,575.49	75.26
Nett Amount (S\$)	32,000.44	7,918.00	24,082.44	75.26
+ Car Rental (9.0 x S\$85.60/day) (S\$)		770.40		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		8,724.85		
Global Sum Settlement (S\$)		8,700.00		

INSPECTION

Date of Assignment:	31/05/2021	
Date Inspected:	31/05/2021 Inspected At:	JWG International Pte Ltd (HQ) Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK AutoPoint Singapore 568047
Estimated Period of Repair:	7.0 days	

Adjuster: BRYAN TANI**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	2,150.39 FL	*1,650.90 FL
2	1		*TAILGATE LOGO	Necessary	65.29 FL	*65.29 FL
3	1		*TAILGATE TOYOTA EMBLEM	Not fitted	71.82 FL	*- FL
4	1		*TAILGATE HIACE EMBLEM	Necessary	76.92 FL	*76.92 FL
5	1		*TAILGATE INNER BOARD	Not Necessary	441.92 FL	*- FL
6	1		*TAILGATE INNER BOARD HANDLE	Not Necessary	197.00 FL	*- FL
7	1		*TAILGATE CENTER MOULDING	Not Necessary	198.00 FL	*- FL
8	1		*TAILGATE WEATHERSTRIP	Deformed	395.00 FL	*228.50 FL
9	1		*TAILGATE INNER LOCK	Damaged	340.00 FL	*340.00 FL
10	1		*TAILGATE STRIKER LOCK	Serviceable	105.00 FL	*- FL
11	1		*TAILGATE WINDSCREEN MOULDING	Necessary	288.21 FL	*102.40 FL
12	2		*TAILGATE NUMBER PLATE LAMP L+R	Not Necessary	236.00 FL	*- FL
13	2		*TAILGATE HINGE LH/RH	Not Necessary	384.80 FL	*- FL
14	2		*TAILGATE DAMPER LH/RH	Not Necessary	996.20 FL	*- FL
15	1		*TAIL LAMP L+R	N/S Mtg Cracked	1,364.78 FL	*367.80 FL
16	2		*TAIL LAMP PANEL L+R	Dented	1,178.40 FL	*963.80 FL
17	2		*TAIL LAMP LOWER GARNISH L+R	Distorted / Bent	679.60 FL	*209.40 FL
18	2		*TAIL LAMP LOWER GARNISH BRACKET L+R	Serviceable	210.56 FL	*- FL
19	1		*REAR BUMPER CENTER BEAM	Bent	398.00 FL	*285.10 FL
20	2		*REAR BUMPER SIDE RETAINER L+R	Serviceable	116.58 FL	*- FL
21	1		*REAR END PANEL INNER	Dented	1,033.00 FL	*871.40 FL
22	1		*REAR END PANEL OUTER	Dented	1,082.00 FL	*590.30 FL
23	1		*REAR END PANEL TOP GARNISH (CHROME)	Bent	392.81 FL	*156.10 FL
24	1		*REAR FLOOR PANEL EXTENSION	Dented	1,892.39 FL	*898.10 FL
25	1		*REAR FLOOR PANEL TOP BOARD	Bent	1,419.00 FL	*650.00 FL
26	1		*REAR FLOOR PANEL MAT	Not Necessary	1,359.00 FL	*- FL
27	1		*REAR SPARE TYRE HOLDER BRACKET	Not Necessary	380.00 FL	*- FL
28	1		*REAR SPARE TYRE HOLDER BOLT	Not Necessary	60.00 FL	*- FL
29	2		*REAR FENDER L+R	Not Necessary	5,538.20 FL	*- FL
30	2		*REAR FENDER INNER TRIM L+R	Not Necessary	1,782.40 FL	*- FL
31	1		*REAR EXHAUST PIPE	Not Necessary	1,410.00 FL	*- FL
32	1		*REAR EXHAUST MOUNTING	Not Necessary	116.00 FL	*- FL
33	1		*REAR EXHAUST BRACKET	Not Necessary	90.00 FL	*- FL
34	1		*REAR NUMBER PLATE	Not Necessary	100.00 FS	*- FS
35	1		*REAR BUMPER	Dented	2,400.00 FS	*850.00 FS
36	1		*REVERSE CAMERA	Not Necessary	600.00 FS	*- FS
37	1		*REVERSE SENSOR	Damaged	300.00 FS	*200.00 FS
38	1		*70KM STICKER	Necessary	80.00 FS	*20.00 FS
39	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
40	1		*TAILGATE WINDSCREEN DAMPER SEAL	Not Necessary	30.00 FS	*- FS
41	1		*TAILGATE WINDSCREEN INNER SEAL	Not Necessary	50.00 FS	*- FS
42	1		*TAILGATE CENTER MOULDING CLIPS	Not Necessary	50.00 FS	*- FS
43	1		*TAILGATE INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
44	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
45	1		*TAIL LAMP CLIPS	Not Necessary	50.00 FS	*- FS
46	1		*TAIL LAMP PANEL SEALANT	Necessary	160.00 FS	*20.00 FS
47	1		*REAR END PANEL SEALANT	Necessary	150.00 FS	*20.00 FS
48	1		*REAR FLOOR PANEL INSULATION SEAL	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	30,849.27	8,626.01
- List Item Discount on L Items 25.00/25.00% (\$)	6,612.32	1,864.00
Total Parts (\$)	24,236.95	6,762.01

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	400.00	150.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,000.00	1,100.00
3	TO RESPRAY NEW PAINTWORK ALL DAMAGED AREAS	New	2,000.00	900.00
4	TO TUFF COAT AFFECTED AREAS	New	250.00	40.00
5	TO RNR TAILGATE WINDSCREEN TO FACILITATE REPAIRS	New	400.00	120.00
6	TO RNR TAILGATE MECHANISM TO FACILITATE REPAIRS	New	100.00	40.00
7	TO RNR REAR BUMPER REVERSE SENSOR TO FACILITATE REPAIRS	New	120.00	40.00
8	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
9	TO RNR EXHAUST & ATTACHMENT PARTS TO FACILITATE REPAIRS	New	200.00	60.00
Gross Labour Cost (\$\$)			5,670.00	2,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >