

JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6484 1922

E-Mail: jwg.claims@yahoo.com

To: AIG ASIA PACIFIC INSURANCE PTE LTD

Att: Motor Claims Dept

ACCIDENT INVOLVING SGK8223E [YOUR INSURED] & GBK2924P [OUR CLIENT]
ON 28/05/2021.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Date:

ESTIMATED REPAIR COSTS FOR GBK2924P

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>	
1PC	TAILGATE <i>Dented</i>	1650.90	\$ 2,150.39 ✓
1PC	TAILGATE LOGO <i>Hec</i>		\$ 65.29 ✓
1PC	TAILGATE 'TOYOTA' EMBLEM <i>Hec HP</i>		\$ 71.82 <i>and X</i>
1PC	TAILGATE 'HIACE' EMBLEM <i>Hec</i>		\$ 76.92 ✓
1PC	TAILGATE INNER BOARD <i>HH</i>		\$ 441.92 X
1PC	TAILGATE INNER BOARD HANDLE <i>HH</i>		\$ 197.00 X
1PC	TAILGATE CENTER MOULDING <i>HH</i>		\$ 198.00 X
1PC	TAILGATE WEATHER STRIP <i>deformed</i>	228.50	\$ 395.00 ✓
1PC	TAILGATE INNER LOCK <i>Dam</i>		\$ 340.00 ✓
1PC	TAILGATE STRIKER LOCK <i>SVL</i>		\$ 105.00 X
1PC	TAILGATE WINDSCREEN MOULDING <i>Hec</i>	102.40	\$ 288.21 ✓
2PCS	TAILGATE NUMBER PLATE LAMP L+R @ \$118.00 EACH <i>HH</i>		\$ 236.00 X
2PCS	TAILGATE HINGE LH / RH @ \$192.40 EACH <i>HH</i>		\$ 384.80 X
2PCS	TAILGATE DAMPER LH / RH @ \$498.10 EACH <i>HH</i>		\$ 996.20 X
2PCS	TAIL LAMP L+R @ \$682.39 EACH <i>W/S crack mainly o/s HH</i>	367.80	\$ 1,364.78 ✓
2PCS	TAIL LAMP PANEL L+R @ \$589.20 EACH <i>Dented</i>	963.80	\$ 1,178.40 ✓
2PCS	TAIL LAMP LOWER GARNISH L+R @ \$339.80 EACH <i>damaged</i>	209.40	\$ 679.60 ✓
2PCS	TAIL LAMP LOWER GARNISH BRACKET L+R @ \$105.28 EACH <i>SVL</i>		\$ 210.56 X
1PC	REAR BUMPER CENTER BEAM <i>St</i>	285.10	\$ 398.00 ✓
2PCS	REAR BUMPER SIDE RETAINER L+R @ \$58.29 EACH <i>SVL</i>		\$ 116.58 X
1PC	REAR END PANEL INNER <i>Dented</i>	871.40	\$ 1,033.00 ✓
1PC	REAR END PANEL OUTER <i>Dented</i>	590.30	\$ 1,082.00 ✓
1PC	REAR END PANEL TOP GARNISH (chrome) <i>St</i>	156.10	\$ 392.81 ✓
1PC	REAR FLOOR PANEL EXTENSION <i>Dented</i>	898.10 <i>843.40</i>	\$ 1,892.39 ✓
1PC	REAR FLOOR PANEL TOP BOARD <i>St</i>	650.00	\$ 1,419.00 ✓
1PC	REAR FLOOR PANEL MAT <i>HH</i>		\$ 1,359.00 X
1PC	REAR SPARE TYRE HOLDER BRACKET <i>St HH</i>		\$ 380.00 2X
1PC	REAR SPARE TYRE HOLDER BOLT <i>HH</i>		\$ 60.00 X
2PCS	REAR FENDER L+R @ \$2,769.10 EACH <i>HH</i>		\$ 5,538.20 X
2PCS	REAR FENDER INNER TRIM L+R @ \$891.20 EACH <i>HH</i>		\$ 1,782.40 X

1PC	REAR EXHAUST PIPE HH	\$ 1,410.00	X
1PC	REAR EXHAUST MOUNTING HH	\$ 116.00	X
1PC	REAR EXHAUST BRACKET HH	\$ 90.00	X

7456.01

5592.00

PARTS SUM: \$ 26,449.27
 PARTS LESS 25%: \$ 6,612.32
 PARTS TOTAL: \$ 19,836.95

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY REAR NUMBER PLATE HH	\$ 100.00	X
*	TO SUPPLY REAR BUMPER Dented	850.00 \$ 2,400.00	✓
*	TO SUPPLY REVERSE CAMERA HH	\$ 600.00	X
*	TO SUPPLY REVERSE SENSOR Dam	\$ 300.00	200/-
*	TO SUPPLY '70KM' STICKER H/c	\$ 80.00	20/-
*	TO SUPPLY TAILGATE WINDSCREEN SEALANT H/c	\$ 80.00	40/-
*	TO SUPPLY TAILGATE WINDSCREEN DAMPING SEAL HH	\$ 30.00	X
*	TO SUPPLY TAILGATE WINDSCREEN INNER SEAL HH	\$ 50.00	X
*	TO SUPPLY TAILGATE CENTER MOULDING CLIPS HH	\$ 50.00	X
*	TO SUPPLY TAILGATE INNER TRIM CLIPS HH	\$ 50.00	X
*	TO SUPPLY REAR BUMPER CLIPS H/c	\$ 50.00	20/-
*	TO SUPPLY TAIL LAMP CLIPS HH	1170.00 \$ 50.00	X
*	TO SUPPLY TAIL LAMP PANEL SEALANT H/c	\$ 160.00	20/-
*	TO SUPPLY REAR END PANEL SEALANT H/c	\$ 150.00	20/-
*	TO SUPPLY REAR FLOOR PANEL INSULATION SEAL HH	\$ 250.00	X
*	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILITATE REPAIRS	\$ 400.00	150/-
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$ 2,000.00	1100/-
*	TO RESPRAY NEW PAINTWORK ALL DAMAGED AREAS	\$ 2,000.00	800/-
*	TO TUFF COAT AFFECTED AREAS	\$ 250.00	900/-
*	TO RNR TAILGATE WINDSCREEN TO FACILITATE REPAIRS	2480.00 \$ 400.00	40/-
*	TO RNR TAILGATE MECHANISM TO FACILITATE REPAIRS	\$ 100.00	120/-
*	TO RNR REAR BUMPER REVERSE SENSOR TO FACILITATE REPAIRS	\$ 120.00	40/-
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	\$ 200.00	30/-
*	TO RNR EXHAUST & ATTACHEMENT PARTS TO FACILITATE REPAIRS	\$ 200.00	60/-

31/05/2021 c 1730hrs
 H/t Antume

LABOUR & S/N TOTAL: \$ 5,670.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 25,506.95

L/sun 7 days.

T ryan

2kk Auto

9242.00

L/s 7400/-

Check part price