



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2105658

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 12/08/2021
Reference CC6/CTI21006278/Aea3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. XB 4072X
Insured Veh. XE 295E
Claim No. SNM21D203083/C02
Policy No. DMCVSNW00083652000
Accident Date 30/05/2021
Inspection Date 01/06/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21006278/Aea3q2 Date: 12/08/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XE 295E	Veh. Inspected	XB 4072X	
Policy No.	DMCVSNW00083652000	Coverage (\$)	0.00	
Claim No.	SNM21D203083/C02	Excess (\$)	0.00	
Assign From		Assign Date	01/06/2021	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI FUSO	c.c	11945	
Engine No.	HIDDEN	Year of Reg.	2002	
Chassis No.	FV517JA00170	Colour	WHITE	
Odometer	538114 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	295/80 R22.5	LING LONG	6 mm	
L/H Front Tyre	295/80 R22.5	LING LONG	6 mm	
R/H Rear Tyre	295/80 R22.5	GREATWAY	6 mm	
L/H Rear Tyre	295/80 R22.5	GREATWAY	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/05/2021	Inspection Date	01/06/2021	
Survey held at	RYDER AUTO PTE LTD 2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XB 4072X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT O/S CORNER PANEL	DENTED	600.00	600.00
1	FRONT O/S DOOR	DISTORTED	7,200.00	4,283.00
1	FRONT O/S DOOR LAMP	NOT NECESSARY	250.00	-
2	FRONT O/S DOOR HINGES	BENT	480.00	480.00
1	FRONT O/S DOOR CHECKER	NOT NECESSARY	245.00	-
1	FRONT O/S DOOR INNER TRIM	NOT NECESSARY	945.40	-
1	FRONT N/S DOOR WINDOW SEAL	NOT NECESSARY	212.50	-
1	FRONT N/S DOOR WINDOW REGULATOR	NOT NECESSARY	653.20	-
1	FRONT N/S DOOR WINDOW REGULATOR MOTOR	NOT NECESSARY	1,346.50	-
1	FRONT N/S DOOR WINDSCREEN CHANNEL	NOT NECESSARY	310.00	-
1	FRONT N/S DOOR WINDOW CHANNEL BRACKET	NOT NECESSARY	80.00	-
1	FRONT O/S DOOR WEATHERSTRIP	NOT NECESSARY	437.10	-
1	FRONT O/S SIGNAL LAMP	CRACKED	750.50	285.00
	LESS 25% DISCOUNT		-3,377.55	-1,412.00
			10,132.65	4,236.00
1	FRONT O/S SIGNAL LAMP CHROME (SN)	NECESSARY	120.00	50.00
	LESS 25% DISCOUNT		-30.00	-
			90.00	50.00
	<u>SPECIAL NETT ITEMS</u>			
6	FRONT O/S DOOR INNER TRIM CLIPS (SN)	NOT NECESSARY	30.00	-
			30.00	-
	<u>LABOUR</u>			
	TO DISMANTLE DAMAGED PARTS ,STRAIGHTEN & WELDING .		1,400.00	400.00
	TO SPRAY PAINTING.		800.00	400.00
	TO REMOVE & REPLACE O/S DOOR .(FITTINGS)		300.00	100.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RE-SEAL ANTI-RUST.		100.00	30.00
			2,600.00	930.00
GRAND TOTAL			12,852.65	5,216.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,150.00

Report Ref No. CC6/CTI21006278/Aea3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. XB 4072X

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

