

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21006288/ATF3E2

Date: 06/09/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900259567		
Claimant Vehicle No :	FBN7083S	Insured Vehicle No :	GBH1285Y		
Date of Loss:	21/05/2021	Nature of Claim:	TP	Claim No:	8274483170SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBN7083S	Engine No:	HIDDEN
Make & Model:	HONDA CBF 190, 184cc	Chassis No:	LALPJL705J3192943
Reg. Date:	01/11/2018 (Man. Year: 2018)	Odometer:	0 km
Colour:	Black		
Engine Capacity:	184 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110/70 R17	Rear Tyre Size:	140/70 R17
Front Left Side:	Kenda 6 mm	Rear Left Side:	Kenda 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	01/06/2021		
Date Inspected:	01/06/2021	Inspected At:	S1 Motoring (HQ) BLOCK 3006 UBI ROAD 1, #01-366 Singapore 408700
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$9,500.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Necessary	0.00 F	*- F
2	1		*FRONT WINDSHIELD	Cut	0.00 F	*- F
3	1		*HEADLAMP	Cracked	0.00 F	*- F
4	1		*HEADLAMP LOWER GARNISH	Cracked	0.00 F	*- F
5	1		*FRONT WHEEL FENDER	Cracked	0.00 F	*- F
6	1		*FRONT FORK ASSY	Bent	0.00 F	*- F
7	1		*FRONT FORK UNDER BRACKET	Bent	0.00 F	*- F
8	1		*STEERING STEM	Necessary	0.00 F	*- F
9	1		*STEERING CONE AND BEARING	Necessary	0.00 F	*- F
10	1		*FORK OIL	Necessary	0.00 F	*- F
11	1		*FORK OIL SEAL	Necessary	0.00 F	*- F
12	1		*HANDLE BAR	Bent	0.00 F	*- F
13	1		*BALANCER LH	Cut	0.00 F	*- F
14	1		*ENGINE COVER LH	Cut	0.00 F	*- F
15	1		*CLUTCH LEVER	Cut	0.00 F	*- F
16	1		*FOOT CLUTCH LEVER	Cut	0.00 F	*- F
17	1		*FRONT FOOT REST LH	Missing	0.00 F	*- F
18	1		*FRONT LH FOOT REST BRACKET	Cracked	0.00 F	*- F
19	1		*REAR LH FOOT REST	Cut	0.00 F	*- F
20	1		*FRONT LH SIGNAL LAMP	Cut	0.00 F	*- F
21	1		*SIDE COWLING LH	Cracked	0.00 F	*- F
22	1		*SIDE COWLING INNER LH	Cracked	0.00 F	*- F
23	1		*REAR BOX	Cut	0.00 F	*- F
24	1		*STICKERS	Necessary	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
-------------------	------	------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >