| | | ιt | Find Next | | | ~ | 100% | | () | Þ١ | > | Ot 2 / | 1 | < | Id |
|--|--|----|-------------|--|--|---|------|--|----|----|---|--------|---|---|----|
|--|--|----|-------------|--|--|---|------|--|----|----|---|--------|---|---|----|



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

| | | Affiliated to Federation Internation | ale Des Experts En | Automob | ile | | |
|-----|---|--|--------------------|---------|----------------------|--|--|
| | AIG ASIA PACIFIC | INSURANCE PTE LTD | | Ref: | CS3/AIG21006288/Atf3 | | |
| | 78 SHENTON WAY AIG BUILDING SINGAPORE 0791 | | | Date: | 01/06/2021 | | |
| | | | | Code: | AIG | | |
| 1. | | Policy Particulars :- | (THIRD PARTY | CLAIM |) | | |
| | Insured Veh. | GBH 1285Y | Veh. Inspected | | FBN 7083S | | |
| | Policy No. | | Coverage (\$) | | 0.00 | | |
| | Claim No. | | Excess (\$) | | 0.00 | | |
| | Assign From | DIVYASHNI SUBRAMANIAM | Assign Date | | 01/06/2021 | | |
| 2. | | Vehicle Partic | ulars & Conditio | n | | | |
| | Make & Model | | c.c | | 0 | | |
| | Engine No. | HIDDEN | Year of Reg. | | | | |
| | Chassis No. | | Colour | | | | |
| | Odometer | - | Steering | | | | |
| | Brakes | | Modification | | | | |
| | General | | | | | | |
| 3. | | Condition | ons of Tyres | | | | |
| | | Size | Make | | Balance | | |
| | R/H Front Tyre | | | | mm | | |
| | L/H Front Tyre | | | | mm | | |
| | R/H Rear Tyre | | | | mm | | |
| | L/H Rear Tyre | | | | mm | | |
| 4. | | Description of Damages | | | | | |
| | | | | | | | |
| 5. | | | Information | | | | |
| | Accident Date | 21/05/2021 | Inspection Date | 9 | 01/06/2021 | | |
| | Survey held at | S1 MOTORING | | | | | |
| | | BLK 3006 UBI ROAD 1 #01-366 SINGAPORE 408700 | | | | | |
| 5a. | • | Re | marks | | | | |
| | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. | | | | | | |

| | AIG ASIA PACIFIC | INSURANCE PTE LTD | | Ref: | CS3/AIG21006288/Atf3 |
|----|--|-----------------------|------------------|-------|----------------------|
| | 78 SHENTON WAY AIG BUILDING SINGAPORE 0791 | | | Date: | 01/06/2021 |
| | | | | Code: | AIG |
| 1. | | Policy Particulars | - (THIRD PARTY | CLAIM |) |
| | Insured Veh. | GBH 1285Y | Veh. Inspected | i | FBN 7083S |
| | Policy No. | | Coverage (\$) | | 0.00 |
| | Claim No. | | Excess (\$) | | 0.00 |
| | Assign From | DIVYASHNI SUBRAMANIAM | Assign Date | | 01/06/2021 |
| 2. | | Vehicle Parti | culars & Conditi | on | |
| | Make & Model | | c.c | | 0 |
| | Engine No. | HIDDEN | Year of Reg. | | |
| | Chassis No. | | Colour | | |
| | Odometer | = | Steering | | |
| | Brakes | | Modification | | |
| | General | | | | |
| 3. | | Condit | ions of Tyres | | |
| | | Size | Make | | Balance |
| | R/H Front Tyre | | | | mm |
| | L/H Front Tyre | | | | mm |
| | R/H Rear Tyre | | | | mm |
| | L/H Rear Tyre | | | | mm |
| 4. | | Descripti | on of Damages | | |

| | ı | | | | | | | |
|-----|---|--|-----------------|------------|--|--|--|--|
| 5. | General Information | | | | | | | |
| | Accident Date | 21/05/2021 | Inspection Date | 01/06/2021 | | | | |
| | Survey held at | S1 MOTORING | | | | | | |
| | | BLK 3006 UBI ROAD 1 #01-366 SINGAPORE 408700 | | | | | | |
| 5a. | Remarks | | | | | | | |
| | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. | | | | | | | |

6/1/2021