



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMX 8006B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	TO REPAIR SEE LABOUR	1,088.44	-
1	REAR BUMPER R/H SIDE RETAINER	NOT NECESSARY	110.35	-
1	SET REAR BUMPER CLIPS	NOT NECESSARY	35.00	-
1	TAILGATE	TO REPAIR SEE LABOUR	1,806.95	-
			3,040.74	-
LABOUR				
	TO PANEL BEAT AND RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS. INCLUSIVE OF THE REPAIR OF REAR BUMPER AND TAILGATE.		600.00	200.00
	TO APPLY ANTI-RUST.	NOT NECESSARY	100.00	-
	TO PUTTY AND SPRAY-PAINT OF AFFECTED AREAS.		700.00	200.00
			1,400.00	400.00
GRAND TOTAL			4,440.74	400.00
RECOMMENDED COST OF REPAIRS				400.00

Report Ref No. CS3/LPC21005271/Gqf3e2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.