

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21006295/UBA3Q2
Date: 29/07/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SDS5365S	Insured Vehicle No :	SLQ8274S
Date of Loss:	30/05/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0002374

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDS5365S		
Make & Model:	HONDA STEPWAGON, 2.0 GL (A)	Engine No:	K20A2609856
Reg. Date:	23/01/2007 (Man. Year: 2006)	Chassis No:	RG11107858
Colour:	Black	Odometer:	167773 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,999.96	2,556.00	11,443.96	81.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,600.00	1,460.00	2,140.00	59.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,599.96	4,016.00	13,583.96	77.18
Approved Total (Overridden) (S\$)		3,200.00		

Nett Amount (S\$)	17,599.96	3,200.00	14,399.96	81.82
+ Car Rental (4.0 x S\$120.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,687.45		
Global Sum Settlement (S\$)		3,600.00		

INSPECTION

Date of Assignment: 01/06/2021

Date Inspected: 01/06/2021

Inspected At:

Zoom Autowerks Pte Ltd
 BLK 15 KAKI BUKIT ROAD 4, #01-53 BARTLEY BIZ CENTRE
 Singapore 417808

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 14 Jul 2021)	
Parts:	N/A	HONDA STEPWAGON 2.0 GL (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDS5365S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Deformed	1,162.20 FL	*850.00 FL
2	2		*REAR BUMPER SIDE RETAINER LONG	Not Necessary	420.80 FL	*- FL
3	2		*REAR BUMPER SIDE RETAINER SHORT	Not Necessary	308.80 FL	*- FL
4	2		*REAR BUMPER REFLECTOR	Not Necessary	343.60 FL	*- FL
5	1		*REAR BUMPER TOW GARNISH	Not Necessary	186.40 FL	*- FL
6	1		*REAR BUMPER CLIPS	Necessary	60.00 FL	*50.00 FL
7	1		*TAILGATE PANEL	Badly Dented	1,352.20 FL	*1,266.20 FL
8	1		*TAILGATE INNER LOCK	Shorted	692.40 FL	*255.40 FL
9	1		*TAILGATE LOCK CATCH	Not Necessary	165.20 FL	*- FL
10	2		*TAILGATE DAMPER	Not Necessary	760.40 FL	*- FL
11	2		*TAILGATE HINGE	Not Necessary	390.40 FL	*- FL
12	1		*TAILGATE INNER TRIMBOARD	Deformed / Cracked	925.20 FL	*381.20 FL
13	1		*TAILGATE INNER TRIMBOARD CLIPS	Necessary	60.00 FL	*40.00 FL
14	1		*TAILGATE INNER POCKET HANDLE GARNISH	Not Necessary	136.20 FL	*- FL
15	1		*TAILGATE CENTRE GARNISH	Not Necessary	562.20 FL	*- FL
16	2		*TAILGATE NUMBER PLATE LAMP	Not Necessary	184.40 FL	*- FL
17	1		*TAILGATE LOGO	Necessary	112.40 FL	*38.50 FL
18	1		*TAILGATE EMBLEM (STEPWAGON)	Necessary	95.80 FL	*60.00 FL
19	1		*TAILGATE RUBBER	Twisted	420.70 FL	*166.20 FL
20	2		*TAILGATE REFLECTOR LAMP	Not Necessary	1,119.20 FL	*- FL
21	1		*TAILGATE CENTRE REFLECTOR	Not Necessary	625.20 FL	*- FL
22	2		*REAR TAILLAMPS	Not Necessary	1,640.20 FL	*- FL
23	1		*REAR END PANEL	Repair	985.20 FL	*- FL
24	1		*REAR END PANEL TOP GARNISH	Serviceable	562.20 FL	*- FL
25	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	60.00 FL	*- FL
26	1		*REAR COMPARTMENT FLOOR PANEL	Not Necessary	1,652.00 FL	*- FL
27	1		*REAR COMPARTMENT PANEL TOP INSULATION	Not Necessary	465.20 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*REAR COMPARTMENT PANEL TOP COVER BOARD	Not Necessary	795.20 FL	*- FL
29	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
30	1		*REAR SPARE TYRE PANEL SEALANT	Not Necessary	80.00 FS	*- FS
31	1		*REAR SPARE TYRE PANEL INSULATOR	Not Necessary	250.00 FS	*- FS
32	1		*REAR WINDSCREEN GLASS INNER SEAL	Necessary	155.00 FS	*30.00 FS
33	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
34	1		*REVERSE SENSOR	Not fitted	280.00 FS	*- FS
35	1		*REAR NUMBER PLATE W/BASE GARNISH	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	17,248.70	3,177.50
- List Item Discount on L Items 20.00/20.00% (\$)	3,248.74	621.50
Total Parts (\$)	13,999.96	2,556.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,REPAIR & RENEW REAR AFFECTED ACCIDENT AREAS	New	1,200.00	550.00
2	TO PUTTY ,SPRAY PAINT ON AFFECTED ACCIDENT AREAS	New	1,400.00	600.00
3	TO REMOVE & INSTALL REAR WINDSCREEN GLASS	New	150.00	120.00
4	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	20.00
5	TO REMOVE & INSTALL REAR TAILGATE COMPONENTS TRIM & GARNISH	New	150.00	60.00
6	TO REMOVE & INSTALL REAR FENDERS TRIM ,GARNISH ,SPARE TYRE COMPARTMENT	New	150.00	80.00
7	TO RE-POSITION ALIGN REVERSE SENSOR	New	150.00	0.00
8	TO CONDUCT WATER LEAKAGE TEST	New	150.00	0.00
9	TO RUST PROOF AFFECTED AREAS	New	200.00	30.00
Gross Labour Cost (\$\$)			3,600.00	1,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >