

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/III21004349/R1QF3E2-1**Date:** 15/06/2021REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447  
**Claimant Vehicle No :** SKA507U **Insured Vehicle No :** SLP4338Z  
 Date of Loss: 01/04/2021 Nature of Claim: TP Claim No: MFL2021D0001414

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKA507U**  
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 L (A) Engine No: 3ZZ4993090  
 Reg. Date: 18/01/2011 (Man. Year: 2010) Chassis No: MR053ZEE106173231  
 Colour: Grey Odometer: 87032 km  
 Engine Capacity: 1598 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15  
 Front Left Side: ROLIT 6 5 mm Rear Left Side: ROLIT 6 5 mm  
 Front Right Side: ROLIT 6 5 mm Rear Right Side: ROLIT 6 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,256.50	2,931.25	1,325.25	31.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,110.00	1,150.00	1,960.00	63.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,366.50</b>	<b>4,081.25</b>	<b>3,285.25</b>	<b>44.60</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,250.00</b>		
<b>Nett Amount (S\$)</b>	<b>7,366.50</b>	<b>3,250.00</b>	<b>4,116.50</b>	<b>55.88</b>

INSPECTION

Date of Assignment: 01/06/2021  
 Date Inspected: 06/04/2021 Inspected At: Max Motors (HQ)  
 1 Kaki Bukit Ave 6, #01-98 Autobay @ Kaki Bukit  
 Singapore 417883  
 Estimated Period of Repair: 4.0 days

**Adjuster:** MOHD RASUL**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 15 Jun 2021)
<b>Parts:</b>	143	TOYOTA COROLLA ALTIS 1.6 L (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKA507U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed / Cracked	584.00 FL	*584.00 FL
2	1		*FRONT BUMPER TOP RUBBER	Necessary	55.00 FL	*55.00 FL
3	2		*FRONT BUMPER REINTAINER	Serviceable	112.00 FL	*- FL
4	1		*FRONT BUMPER LOWER GRILLE	Cracked	118.00 FL	*118.00 FL
5	1		*FRONT BUMPER REINFORCEMENT	Dented	340.00 FL	*340.00 FL
6	1		*FRONT BUMPER FOG LAMP COVER LH	Cracked	105.00 FL	*105.00 FL
7	1		*FRONT FOG LAMP LH	Cracked	275.00 FL	*275.00 FL
8	1		*FRONT GRILLE	Cracked	371.00 FL	*371.00 FL
9	1		*FRONT GRILLE EMBLEM	Necessary	71.00 FL	*71.00 FL
10	1		*FRONT SUPPORT PANEL	Repair	708.00 FL	*- FL
11	1		*BRACE PANEL	Not Necessary	97.00 FL	*- FL
12	1		*FRONT HEADLAMP LH	Cracked	525.00 FL	*525.00 FL
13	1		*FRONT BONNET	Repair	690.00 FL	*- FL
14	1		*AIRCON CONDENSER	Dented	1,331.00 FL	*1,331.00 FL
15	1		*FRONT NUMBER PLATE	Serviceable	90.00 FS	*- FS
16	1		*SET FRONT BUMPER CLIP	Necessary	40.00 FS	*30.00 FS
17	1		*SET FRONT GRILLE CLIP	Necessary	30.00 FS	*20.00 FS
18	1		*BOT COOLANT	Necessary	60.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>5,602.00</b>	<b>3,875.00</b>
<b>- List Item Discount on L Items 25.00/25.00% (S\$)</b>	1,345.50	943.75
<b>Total Parts (S\$)</b>	<b>4,256.50</b>	<b>2,931.25</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	CHECK FRONT LIGHTNING AND WIRING SYSTEM	New	90.00	30.00
2	REMOVE, RENEW CONDENSER AND TOP UP GAS }	New	150.00	120.00
3	REMOVE, REFIT RADIATOR AND TOP UP COOLANT }	New	150.00	0.00
4	PANEL BEATING AND RENEW DAMAGE PARTS ON AFFECTED AREAS	New	1,200.00	400.00
5	SPRAY PAINTING ON AFFECTED AREAS	New	1,400.00	600.00
6	APPLY ANTI RUST ON AFFECTED AREAS	New	120.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,110.00</b>	<b>1,150.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >