

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21006298/AQF3N2**Date:** 30/08/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00096752000

Claimant Vehicle No : SKK9806U **Insured Vehicle No :** SJP2982A

Date of Loss: 01/06/2021 Nature of Claim: TP Claim No: SNM21D203102/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKK9806U**

Make & Model: TOYOTA COROLLA AXIO, 1.5 X (A) Engine No: 1NZD052125

Reg. Date: 31/12/2008 (Man. Year: 2008) Chassis No: NZE1416082402

Colour: Grey Odometer: 147919 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 186/65 R15 Rear Tyre Size: 186/65 R15

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,395.22	4,155.72	8,239.50	66.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,190.00	2,280.00	3,910.00	63.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,585.22	6,435.72	12,149.50	65.37
Approved Total (Overridden) (S\$)		5,100.00		
Nett Amount (S\$)	18,585.22	5,100.00	13,485.22	72.56

INSPECTION

Date of Assignment: 01/06/2021

Date Inspected: 02/06/2021 Inspected At: Smartone Auto Pte Ltd (HQ)
8 Kaki Bukit Avenue 4, #08-09 Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Aug 2021)
Parts:	143	TOYOTA COROLLA AXIO 1.5 X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKK9806U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*CENTER PILLAR (OUTER) RH	Repair	890.00 FL	*- FL
2	1		*ROCKER PANEL (OUTER) RH	Dented	945.00 FL	*591.00 FL
3	1		*REAR DOOR RH	Distorted	896.00 FL	*896.00 FL
4	1		*REAR DOOR FRAME STEP GARNISH RH	Not Necessary	167.00 FL	*- FL
5	1		*REAR DOOR LOCK CHECKER RH	Not Necessary	88.00 FL	*- FL
6	2		*REAR DOOR HINGE RH	Not Necessary	156.20 FL	*- FL
7	1		*REAR DOOR INNER LOCK RH	Damaged	390.00 FL	*390.00 FL
8	1		*REAR DOOR INNER TRIM RH	Cracked	805.00 FL	*480.00 FL
9	1		*REAR DOOR WEATHER STRIP RH	Not Necessary	132.00 FL	*- FL
10	1		*REAR DOOR POWER WINDOW MOTOR RH	Not Necessary	450.00 FL	*- FL
11	1		*REAR DOOR REGULATOR RH	Damaged	278.00 FL	*278.00 FL
12	1		*REAR DOOR GLASS CHANNEL RH	Not Necessary	102.00 FL	*- FL
13	1		*REAR DOOR OUTER STRIP RH	Not Necessary	87.10 FL	*- FL
14	1		*REAR DOOR LOCK CATCHER RH	Not Necessary	38.00 FL	*- FL
15	1		*REAR DOOR FRAME WEATHER STRIP RH	Not Necessary	126.00 FL	*- FL
16	1		*REAR FENDER RH	Dented	876.10 FL	*876.10 FL
17	1		*REAR FENDER COWLING RH	Not Necessary	211.10 FL	*- FL
18	1		*REAR FENDER ARCH SEAL RH	Not Necessary	65.10 FL	*- FL
19	1		*REAR WINDSCREEN MOULDING	Necessary	108.10 FL	*108.10 FL
20	1		*REAR ABS SENSOR RH	Not Necessary	198.00 FL	*- FL
21	1		*REAR WHEEL HUP WITH BEARING RH	Damaged	498.10 FL	*295.00 FL
22	1		*REAR SHOCK ABSORBER RH	Not Necessary	369.20 FL	*- FL
23	1		*REAR AXLE	Not Necessary	2,625.10 FL	*- FL
24	1		*TAIL LAMP RH	Not Necessary	298.10 FL	*- FL
25	1		*TAIL LAMP LOWER BRACKET RH	Not Necessary	46.00 FL	*- FL
26	1		*REAR BUMPER	Torn	435.10 FL	*435.10 FL
27	1		*REAR BUMPER SIDE BRACKET	O/s Necessary	180.00 FL	*45.00 FL
28	1		*CENTER PILLAR SEALANT (OUTER) RH	Not Necessary	150.00 FS	*- FS
29	1		*ROCKER PANEL SEALANT RH (OUTER)	Not Necessary	150.00 FS	*- FS
30	1		*REAR DOOR SEALANT RH	Not Necessary	150.00 FS	*- FS
31	1		*SET REAR DOOR INNER TRIM CLIP RH	Necessary	80.00 FS	*30.00 FS
32	1		*SET REAR DOOR FRAME STEP GARNISH CLIP RH	Not Necessary	60.00 FS	*- FS
33	1		*REAR DOOR SOUND PROOF RH (SPECIAL TYPE)	Necessary	550.00 FS	*180.00 FS
34	1		*REAR DOOR INNER WEATHERSTRIP RH (SPECIAL TYPE)	Cut	180.00 FS	*100.00 FS
35	1		*REAR FENDER SOUND PROOF RH (SPECIAL TYPE)	Not Necessary	550.00 FS	*- FS
36	1		*REAR FENDER SEALANT RH	Necessary	150.00 FS	*50.00 FS
37	1		*SET REAR FENDER COWLING CLIP RH	Not Necessary	50.00 FS	*- FS
38	1		*REAR WINDSCREEN INNER SEAL	Necessary	60.00 FS	*30.00 FS
39	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
40	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
41	1		*SET TAIL LAMP CLIP RH	Not Necessary	60.00 FS	*- FS
42	1		*REAR WHEEL TYRE RH	Not Necessary	450.00 FS	*- FS
43	1		*REAR WHEEL RIM RH	Cut	850.00 FS	*400.00 FS
44	1		*SET WHEEL CAP	Not Necessary	120.00 FS	*- FS
45	1		*BRAKE OIL	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Sub Total (S\$)	15,260.30	5,254.30
				- List Item Discount on L Items 25.00/25.00% (S\$)	2,865.08	1,098.58
				Total Parts (S\$)	12,395.22	4,155.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,REMOVAL AND REPLACING PARTS	New	1,800.00	1,000.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,800.00	800.00
3	TUFF COAT	New	250.00	100.00
4	WIRING CHECK	New	250.00	30.00
5	REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	350.00	60.00
6	REMOVE AND REFIX REAR UNDERCARRIAGE	New	650.00	80.00
7	FOUR WHEEL ALIGNMENT	New	120.00	80.00
8	TRANSFER REAR DOOR MECHANISM RH	New	80.00	40.00
9	REMOVE & REINSTALL REAR WINDOW GLASS RH	New	80.00	40.00
10	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
11	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
12	RESET ABS LIGHT	New	350.00	0.00
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
14	TO PRESS REAR WHEEL BEARING	New	80.00	0.00
Gross Labour Cost (\$\$)			6,190.00	2,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >