## Note: This document has not been finalised.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909

From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25

> Paya Ubi Industrial Park Singapore 408933

Attn: 27 Aug 2021 Jenny Lew Date:

# **Preliminary Advice**

Insured Vehicle No : SJP2982A

TP Vehicle No : SKK9806U : 01/06/2021 Accident Date Make : TOYOTA COROLLA AXIO Assignment Date : 01/06/2021

Date of Inspection : 02/06/2021 Est. Duration of Repair : 8

Inspection At : SMARTONE AUTO PTE LTD (HQ)

8 KAKI BUKIT AVENUE 4, #08-09 PREMIER @ KAKI BUKIT

SINGAPORE 415875

## Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,585.23
Revised Amount	:S\$	6,435.73
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,435.73
Lump Sum Repair	:S\$	5,100.00

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

#### Remarks

(	)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly
		let us have your authorisation.

(		The vehicle is uneconomical	≀to l	be repaired	. vou are advise	ď	to invite	e tend	ler f	or t	he wrec	:k
١	. ,			bo ropanoa	, you alo aavioo	ч		COLIC		0, ,	110 11100	

Other comments: Please note that the preliminary advice amount (Revised & Check Items) stated are subject ( X ) to consistency check, part prices and labour cost.