

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21006299/ARA3Q2
Date: 05/10/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070130077
Claimant Vehicle No :	SMA3138H	Insured Vehicle No :	SMU9356A
Date of Loss:	16/05/2021	Nature of Claim:	TP
		Claim No:	4529671313SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA3138H		
Make & Model:	OPEL ASTRA ST, 999cc (A)	Engine No:	B1170037HRXX0899
Reg. Date:	25/06/2018 (Man. Year: 2017)	Chassis No:	W0LBE8EA6H8050438
Colour:	Grey	Odometer:	68099 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,072.80	6,275.70	3,797.10	37.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,580.00	2,855.00	2,725.00	48.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,652.80	9,130.70	6,522.10	41.67
+ GST 7.00/7.00% (S\$)	1,095.70	639.15	456.55	41.67

Nett Amount (S\$)	16,748.50	9,769.85	6,978.65	41.67
		+ Loss of Use (4.0 x S\$60.00/day) (S\$)	240.00	
		+ Doc/Search Fee (S\$)	2.00	
		Nett Liability (S\$)	10,011.85	

INSPECTION

Date of Assignment: 31/05/2021

Date Inspected: 31/05/2021

Estimated Period of Repair: 4.0 days

Inspected At: 1st Autoworks Pte Ltd (HQ)
23 Kaki Bukit Ave 4, #04-01
Singapore 415933

Adjuster: ADRIAN LING**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RR BUMPER	Deformed	1,474.00 FL	*1,474.00 FL
2	10		*RR BUMPER CLIPS	Necessary	65.00 FL	*30.00 FL
3	1		*RR BUMPER TOW COVER	Not Necessary	94.00 FL	*- FL
4	1		*RR BUMPER SIDE RETAINER RH (INNER)	Not Necessary	154.00 FL	*- FL
5	1		*RR BUMPER SIDE RETAINER RH (OUTER)	Necessary	164.00 FL	*164.00 FL
6	1		*RR BUMPER CENTER RETAINER	Necessary	160.00 FL	*160.00 FL
7	1		*RR BUMPER SIDE RETAINER LH (INNER)	Not Necessary	154.00 FL	*- FL
8	1		*RR BUMPER SIDE RETAINER LH (OUTER)	Necessary	164.00 FL	*164.00 FL
9	1		*RR BUMPER LOW BRACKET RH	Necessary	86.00 FL	*86.00 FL
10	1		*RR BUMPER LOW BRACKET LH	Necessary	86.00 FL	*86.00 FL
11	1		*RR BUMPER REINFORCEMENT	Bent	537.00 FL	*537.00 FL
12	1		*RR BUMPER LOW GARNISH	Not Necessary	332.00 FL	*- FL
13	2		*RR BUMPER REVERSE SENSOR	Damaged	264.00 FL	*264.00 FL
14	1		*RR BUMPER REVERSE SENSOR RUBBER SEAL	Not Necessary	10.00 FL	*- FL
15	1		*RR BUMPER REVERSE SENSOR WIRE HARNESS	Not Necessary	390.00 FL	*- FL
16	1		*RR BUMPER REFLECTOR RH	Cracked	144.00 FL	*144.00 FL
17	1		*RR BUMPER REFLECTOR LH	Not Necessary	144.00 FL	*- FL
18	1		*RR TAILGATE	Dented	2,196.00 FL	*2,196.00 FL
19	10		*RR TAILGATE TRIM BOARD CLIPS	Not Necessary	65.00 FL	*- FL
20	1		*RR TAILGATE ASTRA EMBLEM	Necessary	174.00 FL	*174.00 FL
21	1		*RR TAILGATE ASTRA LETTERING	Necessary	150.00 FL	*150.00 FL
22	1		*RR TAILGATE ECO LETTERING	Necessary	130.00 FL	*130.00 FL
23	1		*LETTERING	Necessary	120.00 FL	*120.00 FL
24	1		*RR TAILGATE LOCK KEYLESS RECEIVER SENSOR	Cracked	274.00 FL	*274.00 FL
25	1		*RR TAILGATE REFLECTOR RH -T/LAMP FOG	Not Necessary	499.00 FL	*- FL
26	1		*RR TAILGATE REFLECTOR LH -T/LAMP FOG	Not Necessary	499.00 FL	*- FL
27	1		*RR TAILGATE GLASS	Not Necessary	682.00 FL	*- FL
28	1		*RR TAILGATE WEATHERSTRIP	Cut	190.00 FL	*190.00 FL
29	1		*RR END PANEL	Not Necessary	816.00 FL	*- FL
30	1		*RR END PANEL TOP GARNISH	Not Necessary	280.00 FL	*- FL
31	10		*RR END PANEL TOP GARNISH CLIPS	Not Necessary	65.00 FL	*- FL
32	1		*RR BUMPER SPONGE	Cracked	180.00 FL	*180.00 FL
33	1		*RR TAILGATE OPEN MOTIEN SENSOR	Cracked	450.00 FL	*450.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)**11,192.00****6,973.00**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 10.00/10.00% (S\$)					1,119.20	697.30
Total Parts (S\$)					10,072.80	6,275.70
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION ,TO PANEL BEATING ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	2,600.00	1,300.00
2	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA	New	2,200.00	1,100.00
3	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS ,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	130.00	30.00
4	TO REMOVE AND REFIX REVERSE SENSOR AND CONDUCT TEST	New	130.00	50.00
5	TO REMOVE AND REFIX REVERSE CAMERA AND CONDUCT TEST	New	130.00	50.00
6	TO CONDUCT TRANSFER OF PARTS FROM OLD TAILGATE TO NEW TAILGATE	New	195.00	195.00
7	TO CONDUCT WATER LEAKAGE TEST AFTER REPAIRS OF VEHICLE	New	65.00	0.00
8	TO REMOVE AND REFIX REAR TAIL GATE WINDSCREEN	New	130.00	130.00
Gross Labour Cost (S\$)			5,580.00	2,855.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >