

SFA23H. 2015 Oct.
 TPAKA.
 Denise.
 Mercedes Benz C180 1595 cc
 WDD2050402 R101636.

Rees Bumper Deformed	1350 1530 ✓
Rees Bumper Clips. New	50(SN) ✓
Rees Bumper Side Holder x 02 ^{HE NEW}	65x2 = 130 x
Rees Bumper Lower Diffusers ^{Dehd}	365 ✓
Rees Bumper Lower Diffuser Chrome ^{at} Moulding 271	271 ✓
Rees Bumper Tow Cover ^{HE NEW}	55 x
Rees Bumper Reinforcement ^{HE NEW}	685 x
Rees Bumper Reinforcement Cover ^{Guid}	125 ✓
Rees Bumper Centre Guide. ^{Guid}	138 ✓
Rees Bumper Kick Sensor ^{HE NEW}	485 x
Rees Bumper Under Cover LH. ^{HE NEW}	195 x
Rees Bumper Under Cover RH torn	182 ✓
Reverse Sensor x 04. ^{2 pieces} 250x4=1000 500	
Rees End Panel. ^{Reis}	1330 x

SFA23H.

Rear End Panel Top Garnish. ^{2hd}

216. ✓

Taillamp x 02 ^{x4 New}

748 x 2 = 1496. x

Taillamp lower Bracket x 02. ^{NT} _{new}

59 x 2 = 118. x

Panel Beating,

Spray Painting,

Wiring.

To spray tuff coat

To remove reuse sensor

To remove upholstery.

~~800~~ 350

~~600~~ 500

~~50~~ 30

~~150~~ 40

~~100~~ 50

150 x.

Wist: 3147

less 10%: 2832.30

S.N: 50

Labour: 970

total: 3852.30

h/s: 3k.

03 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: