



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |   |  |            |
|--|---|--|------------|
| GREAT AMERICAN INSURANCE COMPANY<br>3 TEMASEK AVENUE<br>#16-01 CENTENNIAL TOWER<br>SINGAPORE 039190                                    |   | Ref: CS/GAI21006302/R1qf3e2<br>Date: 10/06/2021<br><br>Code: GAI |            |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>  |   |  |            |
| Insured Veh.   | YQ 1811J  | Veh. Inspected   | GBF 8196K  |
| Policy No.   |   | Coverage (\$)  | 0.00       |
| Claim No.  | CLMOMVC000004015  | Excess (\$)  | 0.00       |
| Assign From  | SHERY WONG  | Assign Date  | 01/06/2021 |
| <b>2. Vehicle Particulars &amp; Condition</b>  |   |  |            |
| Make & Model   | FIAT DOBLO CARGO MAXI 1.6   | c.c  | 1598       |
| Engine No.   | HIDDEN  | Year of Reg.   | 2017       |
| Chassis No.  | ZFA26300006E83169   | Colour   | WHITE      |
| Odometer   | 104889 KM   | Steering   | IN ORDER   |
| Brakes   | IN ORDER  | Modification   | NIL        |
| General  | FAIR  |  |            |
| <b>3. Conditions of Tyres</b>  |   |  |            |
|  | Size  | Make   | Balance    |
| R/H Front Tyre   | 195/60 R16  | CONTINENTAL  | 6 mm       |
| L/H Front Tyre   | 195/60 R16  | CONTINENTAL  | 6 mm       |
| R/H Rear Tyre  | 195/60 R16  | CONTINENTAL  | 6 mm       |
| L/H Rear Tyre  | 195/60 R16  | CONTINENTAL  | 6 mm       |
| <b>4. Description of Damages</b>   |   |  |            |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.<br>DAMAGES SEE DETAILS.  |   |  |            |
| <b>5. General Information</b>  |   |  |            |
| Accident Date  | 12/05/2021  | Inspection Date  | 01/06/2021 |
| Survey held at   | VENDA ENGINEERING & TRADING PTE LTD<br>174 WESTWOOD CRESCENT WESTVILLE SINGAPORE 648541 |  |            |
| <b>5a. Remarks</b>   |   |  |            |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |  |            |
| <b>5b. Estimate Days of Repair</b>   |   |  |            |
| ESTIMATED NORMAL PERIOD FOR REPAIR:  |   | 3 Working Days   |            |