

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21006306/APS3Q2**Date:** 13/10/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993662
Claimant Vehicle No :	SLA2017S	Insured Vehicle No :	SMQ9627P
Date of Loss:	28/05/2021	Nature of Claim:	TP
		Claim No:	4402705491SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLA2017S	Engine No:	2NR8499848
Make & Model:	TOYOTA COROLLA FIELDER, 1.5 X (A)	Chassis No:	NRE1618001067
Reg. Date:	24/02/2016 (Man. Year: 2015)	Odometer:	164989 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Habilead 6 mm	Rear Left Side:	Habilead 6 mm
Front Right Side:	Habilead 6 mm	Rear Right Side:	Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,442.00	3,432.70	3,009.30	46.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,540.00	1,970.00	1,570.00	44.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,982.00	5,402.70	4,579.30	45.88
Approved Total (Overridden) (S\$)		4,300.00		
Nett Amount (S\$)	9,982.00	4,300.00	5,682.00	56.92
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		4,836.45		
Global Sum Settlement (S\$)		4,830.00		

INSPECTION

Date of Assignment:	01/06/2021	Ace Autolution Pte Ltd (KAKI BUKIT)
Date Inspected:	02/06/2021 Inspected At:	13 Kaki Bukit Road 4, #03-29/30 Bartley Biz Centre
Estimated Period of Repair:	5.0 days	Singapore 417807

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR LH	Dented	1,112.60 FL	*1,112.60 FL
2	1		*FRONT DOOR HANDLE LH	Not Necessary	125.60 FL	*- FL
3	1		*FRONT DOOR INNER TRIM BOARD LH	Not Necessary	859.20 FL	*- FL
4	1		*FRONT DOOR LOCK LH	Not Necessary	235.00 FL	*- FL
5	1		*REAR DOOR LH	Dented	985.90 FL	*985.90 FL
6	1		*REAR DOOR HINGE UPPER LH	Not Necessary	115.40 FL	*- FL
7	1		*REAR DOOR HINGE LOWER LH	Not Necessary	115.40 FL	*- FL
8	1		*REAR DOOR INNER TRIM BOARD LH	Not Necessary	859.20 FL	*- FL
9	1		*REAR DOOR REGULATOR MOTOR LH	Not Necessary	251.00 FL	*- FL
10	1		*REAR DOOR HANDLE LH	Not Necessary	125.60 FL	*- FL
11	1		*REAR DOOR INNER PANEL LH	Not Necessary	435.00 FL	*- FL
12	1		*REAR DOOR LOCK LH	Damaged	235.00 FL	*235.00 FL
13	1		*REAR FENDER LH	Dented	753.20 FL	*753.20 FL
14	1		*REAR FENDER INNER SHIELD LH	Not Necessary	211.00 FL	*- FL
15	1		*REAR BUMPER	Deformed	681.30 FL	*681.30 FL
16	1		*REAR BUMPER SIDE RETAINER LH	Necessary	75.60 FL	*75.60 FL
17	1		*SET REAR DOOR CLIPS	Not Necessary	100.00 FS	*- FS
18	1		*SET REAR DOOR FRAME STICKER	Necessary	150.00 FS	*60.00 FS
19	1		*SET REAR FENDER INNER SHIELD CLIPS	Not Necessary	80.00 FS	*- FS
20	1		*REAR RIM LH	Cut	550.00 FS	*400.00 FS
21	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
22	1		*FRONT DOOR STICKER	Necessary	100.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,236.00	4,393.60
- List Item Discount on L Items 25.00/25.00% (\$)	1,794.00	960.90
Total Parts (\$)	6,442.00	3,432.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIR AND REPLACE DAMAGED PARTS	New	1,600.00	1,000.00
2	TO SUPPLY PAINT MATERIALS EXPANDABLE ITEMS & PUTTY RESPRAY PAINT ON PARTS REPLACED	New	1,400.00	800.00
3	TO REMOVE ,REFIX WIRING SYSTEM AT ACCIDENT DAMAGE AREAS AND CHECK FOR PROPER FUNCTION	New	120.00	30.00
4	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	120.00	60.00
5	TO CONDUCT WHEEL ALIGNMENT TEST	New	150.00	80.00
6	TO REMOVE REAR BOOTLID MECHANISM	New	150.00	0.00
Gross Labour Cost (\$\$)			3,540.00	1,970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >