



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XE 5134D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT SIDE MIRROR ASSY O/S	CRACKED	2,499.51	2,499.51
1	FRONT TOP ARM BRACKET O/S	NOT NECESSARY	162.39	-
1	FRONT BOTTOM ARM BRACKET O/S	NOT NECESSARY	218.64	-
	LESS 10% DISCOUNT		-	-249.96
			2,880.54	2,249.55
	<b><u>LABOUR</u></b>			
	TO REMOVE & REPLACE FRONT DAMAGED PARTS.		280.00	150.00
	TO R & R WIRING FOR FRONT SIDE MIRROR.		80.00	30.00
			360.00	180.00
	<b>GRAND TOTAL</b>		<b>3,240.54</b>	<b>2,429.55</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>2,429.55</b>

Report Ref No. CS/SMR21006309/T1uf3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.