

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21006311/TPA3Q2**Date:** 27/12/2022REFERENCE

|                              |                                      |                             |               |
|------------------------------|--------------------------------------|-----------------------------|---------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 1900007437-02 |
| <b>Claimant Vehicle No :</b> | SFD3663A                             | <b>Insured Vehicle No :</b> | SBA1000P      |
| Date of Loss:                | 30/05/2021                           | Nature of Claim:            | TP            |
|                              |                                      | Claim No:                   | 2420324259SG  |

DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SFD3663A</b>                   | Engine No:  | 27186030483504    |
| Make & Model:               | MERCEDES-BENZ E250, 1.8 (A)       | Chassis No: | WDD2120472A632086 |
| Reg. Date:                  | 23/08/2012 (Man. Year: 2012)      | Odometer:   | 138968 km         |
| Colour:                     | White                             |             |                   |
| Engine Capacity:            | 1796 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (\$\$):         | <b>Market Value/New Car Price</b> |             |                   |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

CONDITION OF TYRES

|                   |             |                  |             |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size:  | 245/35 R19  | Rear Tyre Size:  | 245/35 R19  |
| Front Left Side:  | Dunlop 6 mm | Rear Left Side:  | Dunlop 6 mm |
| Front Right Side: | Dunlop 6 mm | Rear Right Side: | Dunlop 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                                        | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|--------------------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                                        | 28,414.00         | 9,554.90          | 18,859.10         | 66.37         |
| Miscellaneous Items                                          | 0.00              | 0.00              | 0.00              |               |
| Labour                                                       | 6,050.00          | 1,270.00          | 4,780.00          | 79.01         |
| Paintwork Labour                                             | 0.00              | 0.00              | 0.00              |               |
| Towing                                                       | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (\$\$)</b>                         | <b>34,464.00</b>  | <b>10,824.90</b>  | <b>23,639.10</b>  | <b>68.59</b>  |
| <b>Approved Total (Overridden) (\$\$)</b>                    |                   | <b>8,650.00</b>   |                   |               |
| <b>(\$\$)</b>                                                | 34,464.00         | 8,650.00          | 25,814.00         | 74.90         |
| <b>+ GST 7.00/7.00% (\$\$)</b>                               | 2,412.48          | 605.50            | 1,806.98          | 74.90         |
| <b>Nett Amount (\$\$)</b>                                    | <b>36,876.48</b>  | <b>9,255.50</b>   | <b>27,620.98</b>  | <b>74.90</b>  |
| <b>+ Car Rental (5.0 x S\$120.00/day + 7.00% GST) (\$\$)</b> |                   | 642.00            |                   |               |
| <b>+ Doc/Search Fee (\$\$)</b>                               |                   | 7.45              |                   |               |
| <b>Nett Liability (\$\$)</b>                                 |                   | <b>9,904.95</b>   |                   |               |

INSPECTION

|                             |            |               |                                                                                                 |
|-----------------------------|------------|---------------|-------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 01/06/2021 |               |                                                                                                 |
| Date Inspected:             | 02/06/2021 | Inspected At: | AP Automotive Services Pte Ltd (HQ)<br>Blk 9006 Tampines Street 93, #01-202<br>Singapore 528840 |
| Estimated Period of Repair: | 4.0 days   |               |                                                                                                 |

---

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

| No. | Qty | Part No. | Particulars                       | Condition                      | Repairer's | Amount       |
|-----|-----|----------|-----------------------------------|--------------------------------|------------|--------------|
| 1   | 1   |          | *BONNET                           | Bent                           | 2,285.00 F | *2,285.00 FL |
| 2   | 1   |          | *BONNET LOGO -MERCEDES            | Necessary                      | 107.00 F   | *107.00 FL   |
| 3   | 2   |          | *BONNET LOCK                      | Not Necessary                  | 240.00 F   | *- FL        |
| 4   | 2   |          | *BONNET LOCK CATCH                | Not Necessary                  | 69.00 F    | *- FL        |
| 5   | 2   |          | *BONNET HINGE L+R                 | Not Necessary                  | 242.00 F   | *- FL        |
| 6   | 2   |          | *BONNET DAMPER L+R                | Not Necessary                  | 1,340.00 F | *- FL        |
| 7   | 2   |          | *BONNET STOPPER L+R               | Not Necessary                  | 36.00 F    | *- FL        |
| 8   | 1   |          | *HEADLAMP L+R                     | O/S Cracked / N/SNot Necessary | 6,574.00 F | *3,287.00 FL |
| 9   | 1   |          | *HEADLAMP BRACKET L+R             | O/S Cracked / N/SNot Necessary | 218.00 F   | *109.00 FL   |
| 10  | 1   |          | *FRONT GRILLE                     | Not Necessary                  | 1,133.00 F | *- FL        |
| 11  | 1   |          | *FRONT GRILLE BASE                | Not Necessary                  | 525.00 F   | *- FL        |
| 12  | 1   |          | *FRONT BUMPER                     | Deformed                       | 1,598.00 F | *1,598.00 FL |
| 13  | 1   |          | *FRONT BUMPER NOZZLE COVER RH     | Missing                        | 78.00 F    | *78.00 FL    |
| 14  | 1   |          | *FRONT BUMPER TOW COVER RH        | Not Necessary                  | 19.00 F    | *- FL        |
| 15  | 1   |          | *FRONT BUMPER FOG LAMP RH         | Cracked                        | 329.00 F   | *329.00 FL   |
| 16  | 1   |          | *FRONT BUMPER FOG LAMP GARNISH RH | Not Necessary                  | 148.00 F   | *- FL        |
| 17  | 1   |          | *FRONT BUMPER FOG LAMP CHROME RH  | Not Necessary                  | 107.00 F   | *- FL        |
| 18  | 2   |          | *FRONT BUMPER RETAINER L+R        | Not Necessary                  | 296.00 F   | *- FL        |
| 19  | 1   |          | *FRONT BUMPER REINFORCEMENT BAR   | Not Necessary                  | 504.00 F   | *- FL        |
| 20  | 1   |          | *FRONT BUMPER SPONGE              | Not Necessary                  | 108.00 F   | *- FL        |
| 21  | 1   |          | *FRONT BUMPER UNDERCOVER          | Not Necessary                  | 222.00 F   | *- FL        |
| 22  | 1   |          | *FRONT FENDER RH                  | Bent                           | 1,015.00 F | *1,015.00 FL |
| 23  | 1   |          | *FRONT FENDER EMBLEM RH           | Necessary                      | 75.00 F    | *75.00 FL    |
| 24  | 1   |          | *FRONT FENDER SIDE CHROME RH      | Not Necessary                  | 91.00 F    | *- FL        |
| 25  | 1   |          | *FRONT FENDER COWLING FRONT RH    | Not Necessary                  | 222.00 F   | *- FL        |
| 26  | 1   |          | *FRONT FENDER COWLING REAR RH     | Not Necessary                  | 207.00 F   | *- FL        |
| 27  | 1   |          | *FRONT SUPPORT PANEL              | Not Necessary                  | 1,416.00 F | *- FL        |
| 28  | 1   |          | *FRONT SUPPORT PANEL TOP GARNISH  | Not Necessary                  | 219.00 F   | *- FL        |
| 29  | 1   |          | *FRONT ABSORBER RH                | Not Necessary                  | 786.00 F   | *- FL        |
| 30  | 1   |          | *FRONT LOWER ARM RH               | Not Necessary                  | 811.00 F   | *- FL        |
| 31  | 1   |          | *FRONT CONTROL ARM RH             | Not Necessary                  | 749.00 F   | *- FL        |
| 32  | 1   |          | *FRONT STRAIGHT ARM RH            | Not Necessary                  | 766.00 F   | *- FL        |
| 33  | 1   |          | *FRONT UPPER ARM RH               | Not Necessary                  | 604.00 F   | *- FL        |
| 34  | 1   |          | *FRONT KNUCKLE RH                 | Not Necessary                  | 1,240.00 F | *- FL        |
| 35  | 1   |          | *FRONT KNUCKLE BEARING RH         | Not Necessary                  | 725.00 F   | *- FL        |
| 36  | 1   |          | *FRONT BEARING HUB RH (NPA)       | Not Necessary                  | 0.00 F     | *- FL        |
| 37  | 1   |          | *FRONT RIM RH                     | Cut                            | 1,398.00 F | *1,398.00 FL |
| 38  | 1   |          | *FRONT BUMPER CLIPS               | Necessary                      | 100.00 FS  | *30.00 FS    |
| 39  | 1   |          | *FRONT FENDER CLIPS               | Not Necessary                  | 200.00 FS  | *- FS        |
| 40  | 1   |          | *FRONT FENDER COWLING CLIPS       | Necessary                      | 100.00 FS  | *20.00 FS    |
| 41  | 1   |          | *FRONT TYRE RH                    | Not Necessary                  | 800.00 FS  | *- FS        |
| 42  | 1   |          | *HEADLAMP NOZZLE RH               | Cracked                        | 416.00 F   | *120.00 FL   |
| 43  | 1   |          | *FRONT BUMPER INNER BRACKET RH    | Deformed                       | 296.00 F   | *160.00 FL   |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                         |                  |                  |
|---------------------------------------------------------|------------------|------------------|
| <b>Sub Total (\$)</b>                                   | <b>28,414.00</b> | <b>10,611.00</b> |
| <b>- List Item Discount on L Items 0.00/10.00% (\$)</b> | 0.00             | 1,056.10         |
| <b>Total Parts (\$)</b>                                 | <b>28,414.00</b> | <b>9,554.90</b>  |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                            | Particulars                             | Lab.Type | Repairer's      | Amount          |
|-------------------------------|-----------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>           |                                         |          |                 |                 |
| 1                             | PANEL BEATING ON AFFECTED AREAS         | New      | 1,400.00        | 500.00          |
| 2                             | SPRAY PAINT ON AFFECTED AREAS           | New      | 1,200.00        | 600.00          |
| 3                             | TO CHECK WIRING AND HEADLAMP FOCUS }    | New      | 150.00          | 30.00           |
| 4                             | TO CHECK WIRING AND FOG LAMP FUNCTION } | New      | 150.00          | 0.00            |
| 5                             | TO RNR INNER TRIM AND UPHOLSTERY        | New      | 800.00          | 0.00            |
| 6                             | TO CHECK WHEEL ALIGNMENT AND ADJUST     | New      | 250.00          | 80.00           |
| 7                             | TO RNR UNDERCARRIAGE                    | New      | 300.00          | 0.00            |
| 8                             | TO CHECK WHEEL BALANCING                | New      | 250.00          | 30.00           |
| 9                             | TO CHECK WATER LEAK                     | New      | 150.00          | 0.00            |
| 10                            | TO PERFORM DIAGNOSTIC AND CLEAR FAULTS  | New      | 1,000.00        | 0.00            |
| 11                            | TO PERFORM RUST PROOFING                | New      | 400.00          | 30.00           |
| <b>Gross Labour Cost (\$)</b> |                                         |          | <b>6,050.00</b> | <b>1,270.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >