

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:**

CS3/AIG21006315/DGS3Q2

**Date:**

17/06/2021

**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1700080594

**Claimant Vehicle No :** SMU9433K**Insured Vehicle No :**

SKL6658U

Date of Loss: 31/05/2021

Nature of Claim:

TP

Claim No:

8537280503SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SMU9433K**

Make &amp; Model: HONDA VEZEL HYBRID, 1.5 RS (A)

Engine No:

LEB5900646

Reg. Date: 30/09/2016 (Man. Year: 2016)

Chassis No:

RU31200642

Colour: Red

Odometer:

135275 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 235/45 R18

Rear Tyre Size:

235/45 R18

Front Left Side: Falken 5 mm

Rear Left Side:

Falken 5 mm

Front Right Side: Falken 5 mm

Rear Right Side:

Falken 5 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

**INSPECTION**

6/17/2021 Adjuster Report

Date of Assignment:	01/06/2021		
Date Inspected:	01/06/2021	Inspected At:	JWG International Pte Ltd (HQ) Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK AutoPoint Singapore 568047
Estimated Period of Repair:	1.0 days		

---

<b>Adjuster:</b>	BRYAN TANI	<b>Manager:</b>	Chong Pui Lin
------------------	------------	-----------------	---------------

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	0.00 F	*- F
			Total Parts (S\$)		0.00	0.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**