



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBJ 2585P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	TO REPAIR SEE LABOUR	389.20	-
1	FRONT BUMPER REINFORCEMENT	SERVICEABLE	172.10	-
1	FRONT GRILLE	HOLDER TORN	520.10	388.00
1	FRONT GRILLE LOGO	NECESSARY	56.10	56.10
1	LH HEADLAMP (LED)	GRAZED	1,278.00	925.00
1	FRONT PANEL	TO REPAIR SEE LABOUR	1,019.00	-
1	FRONT PANEL EMBLEM 'DYNA'	NECESSARY	65.10	65.10
1	LH CORNER PANEL	HOLDER TORN	168.70	125.00
1	LH CORNER PANEL BRACKET	DENTED	38.10	35.00
1	LH CORNER PANEL SEAL	NECESSARY	25.10	25.10
1	FRONT LH WING MIRROR	GRAZED	145.20	145.20
1	FRONT LH ROUND MIRROR	SERVICEABLE	89.50	-
2	FRONT LH WING MIRROR STAY	SERVICEABLE	405.10	-
1	FRONT LH DOOR	TO REPAIR SEE LABOUR	1,219.10	-
1	FRONT LH DOOR INNER LOCK	SERVICEABLE	411.70	-
1	FRONT LH DOOR INNER RUBBER	SERVICEABLE	201.60	-
1	FRONT LH DOOR REGULATOR	SERVICEABLE	277.10	-
1	FRONT LH DOOR INNER TRIM	SERVICEABLE	679.40	-
1	FRONT LH STEP GARNISH	SERVICEABLE	169.60	-
	LESS 25% DISCOUNT		-1,465.96	-352.90
			5,863.84	1,411.60
<u>SPECIAL NETT ITEMS</u>				
1	SETS FRONT BUMPER CLIPS (SN)	NOT NECESSARY	80.00	-
1	SETS FRONT LH DOOR INNER TRIM CLIPS (SN)	NOT NECESSARY	80.00	-
1	SETS FRONT LH DOOR SEALANT (SN)	NOT NECESSARY	80.00	-
1	SETS FRONT LH DOOR COMPANY BODY LETTERING (SN)	NOT NECESSARY	50.00	-
			290.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO CHECK WIRING SYSTEM.		60.00	30.00
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	NOT NECESSARY	150.00	-
	TO TRANSFER FRONT LH DOOR ATTACHMENTS .	NOT NECESSARY	150.00	-
	TO PANEL BEAT & STRAIGHTEN ON FRONT LH WINDSCREEN PILLAR ,FRONT PANEL.TO R&R REAR BUMPER ,FRONT LH DOOR AND OTHERS ATTACHMENTS.INCLUSIVE OF THE REPAIR OF FRONT BUMPER,FRONT PANEL AND FRONT LH DOOR .		1,500.00	400.00
	TO RESPRAY ON FRONT LH DOOR ,LH CORNER PANEL ,FRONT BUMPER AND ACCIDENT AFFECTED AREA.		1,500.00	700.00
	TO CARRY OUT BODY CAVITY PRESERVATION .	NOT NECESSARY	100.00	-
			3,460.00	1,130.00
	GRAND TOTAL		9,613.84	2,541.60
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,000.00

Report Ref No. CS3/AIG21003888/R1pa3q2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.