



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD			Ref:	CS3/AIG21003888/R1pa3q2-1
78 SHENTON WAY #09-16			Date:	11/06/2021
AIG BUILDING				
SINGAPORE 079120				
ATTN: SALIHA SYED YUSOF			Code:	AIG
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBK 4100L	Veh. Inspected	GBJ 2585P	
Policy No.	0999993682	Coverage (\$)	0.00	
Claim No.	0880585132SG	Excess (\$)	0.00	
Assign From	SALIHA SYED YUSOF	Assign Date	25/03/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA 150 5MT	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JTFAT35Y30K211975	Colour	BLUE	
Odometer	17595 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/75 R15	BRIDGESTONE	7 mm	
L/H Front Tyre	195/75 R15	BRIDGESTONE	7 mm	
R/H Rear Tyre	155 R12C (D)	BRIDGESTONE	5/5 mm	
L/H Rear Tyre	155 R12C (D)	BRIDGESTONE	5/5 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.			
	DAMAGES SEE DETAILS.			
5. General Information				
Accident Date	22/03/2021	Inspection Date	13/04/2021	
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.			
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	