

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/GRB21006317/EBS3Q2
Date: 06/09/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SGF7772U	Insured Vehicle No :	SLM4990E
Date of Loss:	31/05/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0002371

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGF7772U		
Make & Model:	MERCEDES-BENZ GLA180 URBAN (R18 LED), 1.6 (A)	Engine No:	27091031800717
Reg. Date:	26/12/2018 (Man. Year: 2018)	Chassis No:	WDC1569422J578258
Colour:	Grey	Odometer:	13670 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,683.11	5,781.74	2,901.37	33.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,700.00	2,060.00	2,640.00	56.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,383.11	7,841.74	5,541.37	41.41
+ GST 7.00/7.00% (S\$)	936.82	548.92	387.90	41.41

Nett Amount (S\$)	14,319.93	8,390.66	5,929.27	41.41
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		8,698.11		

INSPECTION

Date of Assignment: 01/06/2021

Date Inspected: 09/06/2021

Inspected At:

Cycle & Carriage Industries Pte Ltd (Pandan Loop)
 188 Pandan Loop
 Singapore 128378

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Aug 2021)
Parts:	M1-SUV	MERCEDES-BENZ GLA180 URBAN (R18 LED) 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGF7772U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	15.00 FS	*15.00 FS
2	1		*FRONT BUMPER	Crushed	1,388.72 FS	*1,388.72 FS
3	1		*COVER ,TOWING EYE	Not Necessary	174.94 FS	*- FS
4	1		*IMPACT ABSORBER	Broken	155.41 FS	*155.41 FS
5	4		*SPRING NUT	Necessary	14.08 FS	*14.08 FS
6	1		*CTR FRONT BUMPER -SILVER	Cracked	877.71 FS	*877.71 FS
7	1		*CTR FRT BUMPER LOWER GRILLE	Not Necessary	137.09 FS	*- FS
8	1		*LH FOGLAMP COVER	Cut	61.92 FS	*61.92 FS
9	1		*LEFT FOGLAMP BRACKET BUMPER		64.15 FS	*- FS
10	1		*COMPANY SIGN	Not Necessary	65.69 FS	*- FS
11	2		*GROMMET	Necessary	5.28 FS	*5.28 FS
12	1		*LEFT FRONT BUMPER MOULDING	Crushed	140.45 FS	*140.45 FS
13	1		*LEFT FRONT FENDER	Not Necessary	883.64 FS	*- FS
14	1		*LHF INTERMEDIATE LAYER	Not Necessary	9.49 FS	*- FS
15	1		*LEFT FRT FENDER LINEAR	Not Necessary	186.10 FS	*- FS
16	1		*LH FRT FENDER MOLDING	Cut	218.89 FS	*218.89 FS
17	1		*FRONT SUPPORT CARRIER	Not Necessary	677.13 FS	*- FS
18	1		*LEFT HEADLAMP UNIT	Cut	2,581.32 FS	*2,581.32 FS
19	1		*LIGHT RANGE CONTROL UNIT	Not Necessary	703.14 FS	*- FS
20	1		*ENG LOWER COVER	Broken	305.06 FS	*305.06 FS
21	5		*LOCK	Necessary	17.90 FS	*17.90 FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	8,683.11
						5,781.74

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS	New	380.00	380.00
2	REMOVE & REPLACE HEADLAMP WITH FOCUS ADJUSTMENT	New	120.00	120.00
3	REMOVE & REPLACE ON FRONT BUMPER ,LHF HEADLIGHT LHF FENDER	New	2,400.00	960.00
4	RESPRAY ON FRONT BUMPER LHF FENDER	New	1,800.00	600.00
Gross Labour Cost (\$)			4,700.00	2,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >