

Request for LKK Mechanical Inspection Report

Kamaliah KAMIS (SPF) <Kamaliah_KAMIS@spf.gov.sg>

Tue 1/6/2021 12:07 PM

To: Sherwin Beh (LKK Auto) <SherwinBeh@lkkauto.com>; Naz (LKKAuto) <Naz@lkkauto.com>

Cc: Bryan Ang (LKKAuto) <bryanang@lkkauto.com>; Syed Muhd Isa OMAR ALHABSHEE (SPF) <Syed_Muhd_Isa_Omar_Alhabshee@spf.gov.sg>; Adrian LIM (SPF) <Adrian_LIM@spf.gov.sg>; Thabagesh JEYATHESH (SPF) <Thabagesh_JEYATHESH@spf.gov.sg>

Dear Sirs,

May I seek your assistance to perform a detailed mechanical inspection of the **7 vehicles** below. Those in **red** are deemed to be **urgent**:

a. Case IAFP-IB-20210531 - Motorcycle, FBE5320T (TP/IP/17949/2021)

On 10 April 2021 at about 8.37 p.m., an accident took place where a motorcycle rear ended a motorcar along Jurong East Central. As a result of the accident, the rider was conveyed to hospital with serious injuries. A detailed mechanical inspection is required to eliminate any mechanical fault or any possible defence raised by the defendant and to rule out foul play.

Vehicle to be inspected: FBE5320T - Rider (Potential Defendant)

IO In-Charge: IO Syed Isa

b. Case IAFP-IB-20210531 - Mechanical Inspection of Motorcycle, FBP4495X (TP/IP/24079/2021)

On 16 May 2021 sometime before 3.36 p.m., the Deceased was riding his motorcycle when it suddenly wobbled and veered to the left and collided into the lamp post at the said location. As a result of the accident, the Deceased sustained multiple injuries and was conveyed by AB to the hospital. He succumbed to his injuries and was pronounced dead by Dr Andrew at 4.59pm. A detailed mechanical inspection is required to eliminate any mechanical fault or any possible defence raised by the defendant and to rule out foul play.

Vehicle to be inspected: FBP4495X - Rider (Deceased)

IO In-Charge: SIO Adrian Lim

c. Case IAFP-IB-20210531 - Mechanical Inspection of Motorcar, SJT6426S (TP/IP/25917/2021)

On 2 May 2021 at about 2.45 p.m., the driver of the said motorcar claimed that his vehicle was still in reverse mode when his vehicle surged forward to the opposite direction, mounted the road kerb and went up the slope before colliding onto the wall at the perimeter of China Embassy and rolled backwards into a small drain before coming to a halt. A detailed mechanical inspection is required to eliminate any mechanical fault or any possible defence raised by the defendant and to rule out foul play.

Vehicle to be inspected: SJT6426S - Driver (Potential Defendant)

IO In-Charge: DOC Jeya

e. Case IAFP-IB-20210531 - Mechanical Inspection of Motorcar, SKD2076S (TP/IP/23797/2021)

Vehicles to be inspected: **Power-Assisted Bicycle** - Pedal Cyclist (Deceased)
SKD2076S - Driver (Potential Defendant)

Kamaliah Kamis (Miss)
Senior Investigation Officer | Fatal Accident Investigation Team
Traffic Police Department | Singapore Police Force
DID: (65) 6547 6435 | FAX: (65) 6547 6352



Singapore Police Force **W** police.gov.sg **FB** fb.com/singaporepoliceforce **IG** Instagram.com/singaporepoliceforce

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."