

Otv

LKK Auto Consultants Pte Ltd

Condition

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

Our Adjusted

Estimate By

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBB 937M

Description of Parts

λtλ	Description of Parts	Condition	Workshop (\$))	(\$)
	REPLACEMENT OF PARTS			
1	FRONT LEFT FAIRING (N)	CRACKED	120.00	110.00
1	FRONT RIGHT FAIRING (N)	CUT	120.00	110.00
1	FRONT HEAD FAIRING (N)	CUT	140.00	105.00
1	BRAKE LEVER (N)	CUT	100.00	20.00
1	CLUTCH LEVER (N)	CUT	100.00	20.00
1	SIDE MIRROR (N)	CUT	100.00	45.00
1	FOOTREST BRACKET (N)	BENT	160.00	48.00
1	FOOTREST RUBBER (N)	CUT	80.00	35.00
	LESS 10% DISCOUNT		-92.00	-49.30
			828.00	443.70
			00.00	15.00
	NUMBER PLATE (SN)	CUT	80.00 280.00	a source.
1	TOP BOX (SN)	CUT	-36.00	
	LESS 10% DISCOUNT		324.00	
	LABOUR			
	SPRAY PAINT LABOUR FOR ALL FAIRING.	NOT NECESSARY	480.00	
	LABOUR FEE.		400.00	150.00
	FORK ALIGNMENT.	NOT NECESSARY	380.00	
	RIM ALIGNMENT.	NOT NECESSARY	380.00	
	CHASSIS ALIGNMENT.	NOT NECESSARY	580.00	9
			2,220.00	150.00
	GRAND TOTAL		3,372.00	748.70
	RECOMMENDED COST OF LUMP SUM REPAIRS			600.00

Report Ref No. CS3/III21003423/Gqce2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.