

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21006323/R1VF3E2

Date: 13/08/2021

REFERENCE

Insured/Claimant:	CHEN SIWEI	Policy No:	7210001607		
Date of Loss:	27/04/2021	Nature of Claim:	OD	Claim No:	8434219676SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX7128P		
Make & Model:	AUDI Q3, 1.4 TFSI (A)	Engine No:	CZDC18735
Reg. Date:	12/01/2021 (Man. Year: 2020)	Chassis No:	WAUZZZF36M1044875
Colour:	Black	Odometer:	4805 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$178,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65 R17	Rear Tyre Size:	215/65 R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,289.00	796.00	2,493.00	75.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,752.00	1,602.00	1,150.00	41.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,041.00	2,398.00	3,643.00	60.30
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	5,241.00	1,598.00	3,643.00	69.51
+ GST 7.00/7.00% (S\$)	366.87	111.86	255.01	69.51
Nett Amount (S\$)	5,607.87	1,709.86	3,898.01	69.51

INSPECTION

Date of Assignment: 02/06/2021

Date Inspected: 01/06/2021 Inspected At:

281 Alexandra Road
Repairer: Premium Automobiles Pte Ltd

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,634.00 FS	*- FS
2	1		*REAR BUMPER FIXING PARTS	Serviceable	211.00 FS	*- FS
3	1		*REAR BUMPER SPOILER	Scratched	459.00 FS	*367.20 FS
4	1		*REAR BUMPER SPOILER BRACKET	Serviceable	48.00 FS	*- FS
5	1		*REAR BUMPER COVER - CENTER	Serviceable	97.00 FS	*- FS
6	1		*REAR LIGHT REFLECTOR - LH	Serviceable	41.00 FS	*- FS
7	1		*REAR BUMPER GUIDE SECTION	Serviceable	63.00 FS	*- FS
8	2		*REAR WHEEL COVER - LH / RH	Necessary	536.00 FS	*428.80 FS
9	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					3,289.00	796.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID REAR LID KICK SENSOR	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
3	TO RESPRAY REAR BUMPER	New	1,000.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			2,752.00	1,602.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >