



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJM 6514H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	CUT	745.30	745.30
1	REAR BUMPER REFLECTOR RH	NOT NECESSARY	151.10	-
1	REAR BUMPER SIDE HOLDER RH	NECESSARY	26.70	26.70
1	TAILLAMP LOWER GARNISH	DEFORMED	195.90	195.90
1	REAR RH FENDER ARC GARNISH	CUT	165.80	165.80
	LESS 20% DISCOUNT		-	-226.74
			1,284.80	906.96
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	REVERSE SENSOR (SN)	NOT NECESSARY	280.00	-
1	REAR RH FENDER ARC GARNISH CLIPS (SN)	NECESSARY	20.00	20.00
			330.00	50.00
	<b><u>LABOUR</u></b>			
	PANEL BEATING.		400.00	200.00
	SPRAY PAINTING.		300.00	120.00
	WIRING.		50.00	30.00
	TO REMOVE REVERSE SENSOR.		100.00	60.00
			850.00	410.00
	<b>GRAND TOTAL</b>		<b>2,464.80</b>	<b>1,366.96</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>1,100.00</b>

Report Ref No. CS/TP21006326/Atce2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.