

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBS 8417E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	LED INDICATOR LAMP	CRACKED	100.00	100.00
			100.00	100.00
	<u>LABOUR</u>			
	CONTRACTOR LABOUR.		500.00	500.00
			500.00	500.00
	GRAND TOTAL		600.00	600.00

RECOMMENDED COST OF REPAIRS		600.00
(REPAIR COST NOT CONCLUDE)		

Report Ref No. CS/FCI21006328/T1qf3e2

**MOHAMAD TAUFIKH** 

M.MATAI, AMSAE-A

**ADRIAN LING WAI PING** 

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

**Licensed Appraiser** 

**Automotive Assessor** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.