



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5470H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	BUMPER COVER REAR	BUCKLED / DENTED	852.66	852.66
1	BUMPER LOWER REAR	DENTED	591.41	591.41
1	BUMPER BRACKET CTR REAR	SERVICEABLE	87.29	-
1	BUMPER BRACKET SIDE RH REAR (TAILLAMP LOWER)	SERVICEABLE	104.59	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	34.61	-
1	BUMPER REFLECTOR RH	SERVICEABLE	33.55	-
1	BUMPER BRACKET SIDE LH REAR (TAILLAMP LOWER)	SERVICEABLE	104.59	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	34.61	-
1	BUMPER REFLECTOR LH	SERVICEABLE	33.55	-
1	BUMPER BEAM REAR	BENT	598.09	598.09
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR	173.81	-
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	173.81	-
1	BOOT REAR	TO REPAIR SEE LABOUR	2,209.75	-
1	BOOT FINISHER (MOULDING)	SERVICEABLE	429.90	-
1	BOOT WEATHERSTRUP	SERVICEABLE	248.50	-
1	BOOT REFLECTOR LAMP RH	SERVICEABLE	379.50	-
1	BOOT REFLECTOR LAMP LH	SERVICEABLE	379.50	-
1	BOOT BADGE 'RENAULT'	NOT NECESSARY	173.35	-
1	BOOT BADGE	NOT NECESSARY	173.35	-
1	BOOT STRUT (SPRING)	SERVICEABLE	212.36	-
1	BOOT HINGE LH	TO REPAIR SEE LABOUR	282.96	-
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	282.96	-
1	BOOT INNER TRIM	SERVICEABLE	586.45	-
1	BOOT SWITCH	SERVICEABLE	107.78	-
1	BOOT LOCK	TO REPAIR SEE LABOUR	155.90	-
1	BOOT LOCK CATCH	TO REPAIR SEE LABOUR	72.00	-

Report Ref No. CC3/FCI21006329/Kte2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	LICENCE PLATE LAMP	SERVICEABLE	84.00	-
2	BOOT RUBBER PLUG	SERVICEABLE	170.63	-
1	TAILLAMP RH	SERVICEABLE	425.04	-
1	TAILLAMP LH	SERVICEABLE	425.04	-
1	OUTER PANEL REAR (END PANEL)	TO REPAIR SEE LABOUR	1,132.13	-
1	OUTER PANEL REAR (END PANEL) TRIM	SERVICEABLE	311.20	-
1	EXHAUST REAR	TO REPAIR SEE LABOUR	5,760.00	-
1	EXHAUST CAP REAR	TO REPAIR SEE LABOUR	177.30	-
	LESS 10% DISCOUNT		-1,700.22	-204.22
			15,301.95	1,837.94
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET PARKING AID (SN)	SERVICEABLE	600.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00
1	EXHAUST MOUNTING REAR (SN)	SERVICEABLE	17.82	-
1	SET OUTER PANEL REAR (END PANEL) TRIM CLIP (SN)	NOT NECESSARY	30.00	-
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	24.20	-
1	BOOT STICKER "TRANS-CAB" (SN)	NOT NECESSARY	30.00	-
1	BOOT STICKER "6555-3333" (SN)	NOT NECESSARY	30.00	-
			957.02	165.00
	<b><u>LABOUR</u></b>			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,400.00	220.00

Report Ref No. CC3/FCI21006329/Kte2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BUMPER BEAM BRACKET LH REAR, BUMPER BEAM BRACKET RH REAR, BOOT REAR, BOOT HINGE LH, BOOT HINGE RH, BOOT LOCK, BOOT LOCK CATCH, OUTER PANEL REAR (END PANEL), EXHAUST REAR AND EXHAUST CAP REAR.		1,500.00	200.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
			3,920.00	480.00
<b>GRAND TOTAL</b>			<b>20,178.97</b>	<b>2,482.94</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>2,482.94</b>

Report Ref No. CC3/FCI21006329/Kte2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.