

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21006333/EQCN2**Date:** 25/08/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00026302100	
Claimant Vehicle No :	SLS5955U	Insured Vehicle No :	GBE7280L	
Date of Loss:	30/05/2021	Nature of Claim:	TP	Claim No: SNM21D203125/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS5955U		Engine No:	15605001B48B20B
Make & Model:	BMW 530E, 2.0 LED NAV (A)		Chassis No:	WBAJA520X0WC07536
Reg. Date:	28/09/2017 (Man. Year: 2017)		Odometer:	75550 km
Colour:	White			
Engine Capacity:	1998 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40R19	Rear Tyre Size:	245/40R19
Front Left Side:	Cinturato 5 mm	Rear Left Side:	Cinturato 5 mm
Front Right Side:	Cinturato 5 mm	Rear Right Side:	Cinturato 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,691.55	4,230.60	460.95	9.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,393.00	6,083.00	2,310.00	27.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	13,084.55	10,313.60	2,770.95	21.18
+ GST 7.00/7.00% (\$\$)	915.92	721.95	193.97	21.18
Nett Amount (\$\$)	14,000.47	11,035.55	2,964.92	21.18

INSPECTION

Date of Assignment:	02/06/2021	Performance Motors Limited (Alexandra)
Date Inspected:	22/06/2021 Inspected At:	303 Alexandra Road, Sime Darby Performance Centre
Estimated Period of Repair:	8.0 days	Singapore 159941

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Aug 2021)
Parts:	143	BMW 530E 2.0 LED NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLS5955U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	16		*EXPANDING RIVET	Not Necessary	14.40 FS	*- FS
2	1		*ALLOY RIM FERRICGREY 9JX19 SPK 663	Cut	1,595.80 FS	*1,595.80 FS
3	1		*REAR LH DOOR ALUMINIUM	Dented	1,881.90 FS	*1,881.90 FS
4	1		*RR LH DOOR SIDE WINDOW FIXED GREEN	Not Necessary	425.15 FS	*- FS
5	1		*(S/L) DOOR WEATHERSTRIP	Necessary	175.65 FS	*175.65 FS
6	1		*LH SUPPORTING LEDGE	Not Necessary	21.40 FS	*- FS
7	1		*LH SILL TRIM PRIMED	Broken	427.25 FS	*427.25 FS
8	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
F=Franchise part. S=SpcNett.						
					Total Parts (\$\$)	4,691.55 4,230.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR LEFT DOOR,LEFT SIDE SKIRT,REWORK LEFT REAR SIDE PANEL AND LEFT C PILLAR	New	4,250.00	2,125.00
2	TO RESPRAY LEFT REAR DOOR,LEFT SIDE SKIRT,LEFT REAR SIDE PANEL	New	2,596.00	2,466.00
3	TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING (1X)	New	94.00	90.00
4	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT IN ACCORDANCE WITH BMW SPECIFICATIONS (1X)	New	531.00	504.00
5	TO CONDUCT CHECK ON ALL DOORS AND CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	177.00	168.00
6	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	168.00
7	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	112.00
8	RECOAT CERAMIC COATING REAR DOOR,FENDER AND SIDE SKIRT (OWNER PAID)	New	450.00	450.00
Gross Labour Cost (\$\$)			8,393.00	6,083.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >