

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21006334/UGS3Q2
Date: 01/10/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800021981
Claimant Vehicle No :	SMS6983U	Insured Vehicle No :	S6550CD
Date of Loss:	02/06/2021	Nature of Claim:	TP
		Claim No:	9461607829SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS6983U	Engine No:	G4FGKH747175
Make & Model:	KIA CERATO, 1.6 LX (A)	Chassis No:	KNAF1416MK5051506
Reg. Date:	10/03/2020 (Man. Year: 2019)	Odometer:	110407 km
Colour:	Blue		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Winrun 6 mm	Rear Left Side:	Winrun 6 mm
Front Right Side:	Winrun 6 mm	Rear Right Side:	Winrun 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,212.00	3,721.80	18,490.20	83.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,270.00	2,530.00	2,740.00	51.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	27,482.00	6,251.80	21,230.20	77.25
Approved Total (Overridden) (S\$)		5,000.00		

	(S\$)	27,482.00	5,000.00	22,482.00	81.81
	+ GST 7.00/7.00% (S\$)	1,923.74	350.00	1,573.74	81.81
	Nett Amount (S\$)	29,405.74	5,350.00	24,055.74	81.81
	+ Car Rental (2.0 x S\$100.00/day) (S\$)		200.00		
	+ Doc/Search Fee (S\$)		2.00		
	Nett Liability (S\$)		5,552.00		

INSPECTION

Date of Assignment: 02/06/2021

Date Inspected: 02/06/2021

Inspected At:

Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Repair	1,255.00 F	*- FL
2	1		*BOOTLID REAR LOGO	Necessary	68.00 F	*32.00 FL
3	1		*BOOTLID C&C LOGO	Not fitted	50.00 F	*- FL
4	1		*BOOTLID CERATO EMBLEM	Necessary	52.00 F	*28.00 FL
5	2		*BOOTLID REFLECTORS	Not Necessary	1,640.00 F	*- FL
6	1		*BOOTLID CENTRE REFLECTOR	Not Necessary	900.00 F	*- FL
7	1		*BOOTLID INNER LOCK	Not Necessary	285.00 F	*- FL
8	1		*BOOTLID INNER TRIM	Not Necessary	355.00 F	*- FL
9	1		*SET BOOTLID INNER TRIM CLIPS	Not Necessary	50.00 F	*- FL
10	1		*BOOTLID WEATHERSTRIP	Twisted	282.00 F	*100.00 FL
11	1		*REAR BUMPER	Distorted	885.00 F	*651.00 FL
12	1		*REAR BUMPER LOWER GARNISH	Distorted	300.00 F	*241.00 FL
13	1		*SET REAR BUMPER LOWER SKIRTING	Not fitted	1,800.00 F	*- FL
14	1		*REAR BUMPER LAMPS	N/S Cracked	700.00 F	*181.00 FL
15	1		*REAR BUMPER LAMP GARNISHS	N/S Twisted	210.00 F	*130.00 FL
16	1		*REAR BUMPER REINFORCEMENT	Cracked	485.00 F	*398.00 FL
17	1		*REAR BUMPER REINFORCEMENT BRACKETS	N/S Dented	322.00 F	*138.00 FL
18	1		*REAR BUMPER REINFORCEMEN TOP & LOWER BRACKETS	N/S Twisted	125.00 F	*25.00 FL
19	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	136.00 F	*- FL
20	1		*REAR BUMPER LOWER SIDE GARNISHS	N/S Torn	170.00 F	*85.00 FL
21	1		*REAR LOCK SENSOR ANTENNA	Not Necessary	290.00 F	*- FL
22	1		*REAR BUMPER LOWER SENSOR WIRE	Not Necessary	311.00 F	*- FL
23	1		*REAR END PANEL	Dented	455.00 F	*384.00 FL
24	1		*REAR END PANEL TOP GARNISH	Twisted	282.00 F	*121.00 FL
25	1		*REAR FLOOR PANEL	Repair	1,680.00 F	*- FL
26	1		*REAR FLOOR PANEL TOP BOARD	Warped	680.00 F	*331.00 FL
27	1		*REAR FLOOR PANEL SIDE PANEL O/S	Repair	450.00 F	*- FL
28	1		*TAILLAMPS	N/S Cracked	1,700.00 F	*675.00 FL
29	2		*TAILLAMP HOUSING PANELS	Repair	720.00 F	*- FL
30	1		*REAR FENDERS	Repair	3,600.00 F	*- FL
31	1		*REAR FENDER INNER TRIMS	N/S Torn	844.00 F	*282.00 FL
32	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	300.00 FS	*200.00 FS
33	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
34	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
35	1		*SET REAR FLOOR PANEL INSULATOR	Not Necessary	200.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
36	1		*REAR FENDER GLASS SEALANT O/S	Not Necessary	50.00 FS	*- FS	
37	1		*SET REAR REVERSE CAMERA	Not Necessary	380.00 FS	*- FS	
38	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS	
39	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	50.00 FS	*- FS	
					Sub Total (\$)	22,212.00	4,102.00
					- List Item Discount on L Items 0.00/10.00% (\$)	0.00	380.20
					Total Parts (\$)	22,212.00	3,721.80

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	80.00	20.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX BOOTLID MECHANISM	New	100.00	60.00
4	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	150.00	80.00
5	TO DISMANTLE & RELACED REAR EXHAUST	New	100.00	0.00
6	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	0.00
7	TO DISMANTLE & REPLACED REAR FENDER GLASS O/S	New	100.00	0.00
8	TO DISMANTLE & REFIX FUEL TANK	New	100.00	0.00
9	TO MOUNT VEHICLE ON CAR O-LINER	New	380.00	0.00
10	TO RESET & REPROGRAMME SYSTEM	New	180.00	100.00
11	TO SPRAY RUST PROOFING	New	250.00	40.00
12	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,800.00	1,000.00
13	TO PUTTY & SPRAY PAINTING	New	1,800.00	1,180.00
Gross Labour Cost (S\$)			5,270.00	2,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >