



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. EU 56U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BONNET	BENT	3,400.00	3,400.00
1	FRONT RADIATOR GRILLE	SERVICEABLE	2,550.00	-
1	FRONT RADIATOR GRILLER "EMBLEM"	SERVICEABLE	136.00	-
1	FRONT HEADLAMP LH	BROKEN	9,350.00	9,350.00
1	FRONT HEADLAMP BRACKET LH	CRACKED	236.00	236.00
1	FRONT BUMPER	BUCKLED	2,720.00	2,720.00
1	FRONT BUMPER TOWING COVER	SERVICEABLE	85.00	-
1	FRONT BUMPER RETANNAL LH	CRACKED	59.50	59.50
1	FRONT BUMPER LOWER GARNISH LH	BENT	425.00	425.00
1	FRONT BUMPER NOZZLE COVER LH	SERVICEABLE	59.50	-
1	FRONT BUMPER NOZZLE LEVER LH	CRACKED	187.00	187.00
1	FRONT BUMPER NOZZLE WASHER JET LH	CRACKED	234.00	234.00
1	FRONT BUMPER REFORCEMENT	TO REPAIR SEE LABOUR	935.00	-
1	FRONT BUMPER SPONGE	SERVICEABLE	119.00	-
1	FRONT FENDER LH	BENT	1,360.00	1,360.00
1	FRONT SUPPORT PANAL	CRACKED	935.00	935.00
1	FRONT KNUCKER ARM LH	SERVICEABLE	1,360.00	-
1	FRONT WHEEL HUP LH	SERVICEABLE	510.00	-
1	FRONT WHEEL BEARING LH	NOT NECESSARY	612.00	-
1	FRONT LOWER ARM LH	SERVICEABLE	544.00	-
1	FRONT ABSORBER LH	SERVICEABLE	3,910.00	-
1	FRONT TIE ROD LH	SERVICEABLE	238.00	-
1	FRONT TIE ROD END LH	SERVICEABLE	153.00	-
1	FRONT TORSION BAR LINK	SERVICEABLE	986.00	-
1	FRONT DRIVER SHAFT	TO REPAIR SEE LABOUR	2,890.00	-
1	FRONT FENDER INNER SHIELD FR	TORN	238.00	238.00
1	FRONT FENDER INNER SHIELD RR	CRACKED	204.00	204.00
1	FRONT SENSOR LH	SHORTED	221.00	221.00
1	FRONT SENSOR CORNER LH	SHORTED	221.00	221.00

Report Ref No. CS/UOI21006338/Kqf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT SNESOR WIRE HARNESS CABLE ASSY	TORN	1,125.00	1,125.00
1	FRONT INTERCOOLER PROTECTOR BAR LH	BENT	204.00	204.00
1	FRONT INTERCOOLER INNER AIR DUCT LH	DENTED	238.00	238.00
	LESS 5% DISCOUNT		-	-1,067.88
			36,445.00	20,289.62
	LABOUR			
	TO RECTIFY FRONT BUMPER SENSOR HARNESS WIRING SYSTEM.		200.00	80.00
	TO KNOCKING REMOVE N REFIX FRONT BONNET, SUPPORT PANAL, FENDER LH, FRONT BUMPER. INCLUSIVE OF THE REPAIR OF FRONT BUMPER REFORCEMENT AND FRONT DRIVER SHAFT.		4,000.00	800.00
	TO REMOVE & INSTALL REPLACE RADIATOR, COOLING SYSTEM & ALL REPAIR, INCLUDING PRESSURE TEST, BLEED COOLING SYSTEM & CHECK LEAKS NECESSARY PART TO FACILITATE.	NOT NECESSARY	2,000.00	-
	TO VACUUM SYSTEM AND REFILL GAS.		200.00	100.00
	TO CHECK FOR FUNCTION AND ALIGNMENT HEADLAMP LH & RH.		200.00	30.00
	TO RESPRAY FRONT ACCIDENT PORTION FRONT BONNET, FRONT BUMPER, FRONT FENDER LH.		3,000.00	1,000.00
	TO TOWING ACCIDENT VEHICLE TO WORKSHOP.		200.00	130.00
	TO WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
			9,920.00	2,140.00
GRAND TOTAL			46,365.00	22,429.62

RECOMMENDED COST OF REPAIR SUM			22,000.00
---------------------------------------	--	--	------------------

Report Ref No. CS/UOI21006338/Kqf3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.