Our Ref:



ComfortDelGro Engineering

# 205 Braddell Road S(579701) <u>ACCIDENT REPAIR ESTIMATES</u>

Town of Claim	ГР	Vehicle No.	GBK508X
Type of Claim :		Make & Model	: ISUZU NHR87AUE4AA MT
		Year of Manufacture	2019
		Chassis No.	: JAANHR87EK7E7100274
Ins Company : GREAT	EASTERN	Engine No.	: RZ4E105B87
Excess :		Policy No.	2020-V0114372-VCV
	5.2021	Time of Accident	10:15HRS
Suggested Days of Repair :		In-house Vehicle Asse	essor
Repair Estimates		Case Owner	ROHANI
Parts (a) Cost / List Price Items	\$ 2,218.00	Signature	1
		Contact No	-4i
Plus/Less15%	\$ 332.70	Frt Counter Opera 63837103 – Patrick T	
Total of Cost / List	\$ 1,885.30	PatrickTia@sparkcar 63837730 - Brenda N	
(b) Nett Price Items	\$	BrendaNg@sparkcar	
Less		63837466 - Rohani RohaniM@sparkcard	eare.com
		Workshop Opera	tion
Total of Nett Item		63837656 - Ngo Toh	Wee
(c) Special Nett Items	\$ 245.00	Ngotw@sparkcarcar 63838115 -	e.com
Total Parts Cost (Appendix A)	\$ 2,130.30	63837362 -	Not Nothanh
Labour (Appendix B)	\$ 2,110.00	,	Resurry BERDIN
Total Repair Cost	\$ 4,240.30	•	y spany
The above total will be subjected to 79	% G.S.T.		
		Kennerh	
Name of Surveyor	<u> </u>	LKK	
Company Survey conducted on		7/6/2/ at	-
Survey conducted on	,		
Remarks By Surveyor			
(a) The repair of this vehicle is aut			
(b) Recommended Days of Repair		03 day(s)	
(c) Resurvey	: Required / No	egurea .	
(d) Excess	:\$		7/1/2
(e) Signature of surveyor	:		= 7/8/21

# **Spark Car Care**

## ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax:62844284,62815767

### **Spare Parts**

Vehicle No	:	GBK508X	Case Owner		ROHANI
Make & Model	:	ISUZU NHR87AUE4AA MT	Year Manufacture	1.1	2019
Chassis No	:	JAANHR87EK7E7100274	Engine No	•	RZ4E105B87
Sales Order	:		Supplier	•	
Order By	:		Type of Claim	1	<u>TP</u>

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	LH HEADLAMP	1	CAA	\$ 306.00			
	LH FRONT CORNER PANEL	1	R	\$ 208.00			X
3	LH ARM MIRROR	1	Sm	\$ 63.00			Χ-
4	LH MIRROR ARM	1	sn	\$ 268.00			7
5	LH MIRROR BASE COVER	1	Mil	\$ 22.00			_
6	LH DOOR	1	Ry	\$ 791.00			
7	LH DOOR STICKER	8			M	\$ 225.00	1501a
8	LH DOOR PROTECTOR	1		NA			
9	LH DOOR WHEATHERSTIP	1	In	\$ 159.00			X
10	LH DOOR HINGE	2	n	\$ 190.00			×
11	LH DOOR CHECKER	1	Sn	\$ 62.00			X
12	LH DOOR GLASS OUTER MOULDING	1	<i>s</i> n	\$ 73.00			X
13	LH DOOR GLASS CHANNEL RUBBER	1	Sh	\$ 76.00			X
14	COMPANY STICKER	1			M	\$ 20.00	
15	0	1					
16	om Ulf Signal lang	1	CM	110	_		
7	o 1. h dow Sticker	1	M	27	_		
18	oln Uld Signal lang on h dow Sticker on h h vertical garnis	4 1	mis	29	~		
19	0	1					
20	0	1					
21	0	8					
22	0	1					
23	0	1					
24	0	1					
25	0	1					
	0	1					
	0	1					
28	0	1					
29	0	1					
30		1					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax:62844284,62815767

### <u>Labour</u>

Vehicle No. :	GBK508X	Case Owner	:	ROHANI	
Make & Model:	SUZU NHR87AUE4AA MT	Year of Manufacture	:	2019	

S/No	Labour Description	Esimated	Adjusted
		Price	Price
1	TO KNOCK,STRAIGHTEN AND RENEW ACCIDENT AREA SUCH	\$900.00	5401
	LH FRONT PANEL, LH FRONT DOOR, AND AFFECTED AREA		
2	TO PUTTY AND RESPRAY ON LH FRONT PANEL, LH FRONT BUMPER,	\$900.00	4501
	LH FRONT DOOR AND AFFECTED AREA		
3	TO CHECK WIRING AND INSTALL REVERSE SENSOR	\$30.00	201
4	TRANSFER DOOR PARTS TO NEW DOOR	\$180.00	601
5	TO INSTALL LH DOOR ADVERTISEMENT STICKER	\$100.00	X
	LKK Auto Consultants hence notify	7	
	LKK Auto Consultants hence notify the Repairer of the following:  • To resurvey refore after spray painting  • To display damaged part(s) during resurvey		
	Parts prices are subject to confirmation.		
	Third party survey is on a "Without Prejudice" basis     No illegal modification(s) is allowed.		
	Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company		
	Acknowledged by Repairer		
	Signature: Date:		
	Solo.		

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.