

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI21006342/RQCE2

Date: 16/06/2022

REFERENCE

Insured/Claimant:	RAJ FOOD INDUSTRIES (S) PTE LTD	Policy No:	DMCVSNW00089262000		
Date of Loss:	29/05/2021	Nature of Claim:	OD	Claim No:	SNM21D203109/C01/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YQ1326T	Engine No:	4JJ13W1416
Make & Model:	ISUZU NMR85, 3.0 D (M)	Chassis No:	JAANMR85FJ7100297
Reg. Date:	18/09/2019 (Man. Year: 2018)	Odometer:	0 km
Colour:	White		
Engine Capacity:	2999 cc		
Market Value/New Car Price:	S\$80,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/85 R16	Rear Tyre Size:	195/85 R16 (D)
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7/7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
Approved Total (Overridden) (S\$)		56,000.00		
- Excess (S\$)	0.00	3,900.00	-3,900.00	
(S\$)	0.00	52,100.00	-52,100.00	
+ GST 7.00/7.00% (S\$)	0.00	3,647.00	-3,647.00	
Nett Amount (S\$)	0.00	55,747.00	-55,747.00	

INSPECTION

Date of Assignment:	02/06/2021	Present Location:	Goldbell Engineering Pte Ltd (Tuas)
Date Inspected:	02/06/2021	Inspected At:	10 Tuas Ave 18
Estimated Period of Repair:	10.0 days		Repairer: Vin's Motor Pte Ltd

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

NOTE: AS PER AGREEMENT BETWEEN INSURANCE AND REPAIRER,M/s: VIN'S MOTOR PTE LTD AT
REPAIR COST \$56,000.00.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 16 Jun 2022)	
Parts:	N/A	ISUZU NMR85 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YQ1326T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BEYOND ECONOMY REPAIR		0.00 F	*- F
F=Franchise part.						
Total Parts (\$\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	BEYOND ECONOMY REPAIR	New	0.00	0.00
Gross Labour Cost (\$\$)			0.00	0.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >