

ASS. REC. BY:

Steve

CC4/LPC 21906344/993

ASSIGNMENT

From:

Date:

Estimated Cost:

OD ☒ TP ☒ WS ☒ TP RES ☒ OD RES ☒ EVA ☒ INV ☒ MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☒
N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

PC 8868E

Yr Regn:

14/12/10

Type: M.Car / M.Cycle / ☒ Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

King Long XM9 6900K cc 6700

Colour:

Multi Colour

A/C:

Insured / Std / NI / NA

Sp. Reading

597161

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

LA6R10S89AB239.3

Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModl: Nil / S/Rim / ☒ STD A/Rim or

Tyre Size:

F:

11R22.5

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Dablestar

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

23/4/21

D.O.A.

3/6/21

Survey held at

One time right works

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

F1 LH

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp

(\$

☐

: Interview

(\$

☐

: Tech. Insp

(\$

☐

: Wash + Dry

(\$

Report Format:

Lump Sum / Meters

One Line Motorworks Trading

11, Tuas Bay Close #06-02/06-03

West Star, Singapore 636996

Tel : 62622106

Company Reg No: 53375959E

Email : tricia.onelinemotorworks@gmail.com

12 May 2021

LONPAC INSURANCE BHD

To: Attending Surveyor

Dear Sirs,

THIRD PARTY CLAIM - REPAIR ESTIMATE FOR PC8868E
TRAFFIC ACCIDENT ON 23/04/2021 INVOLVING PC8868E AND GZ1342L ALONG
PIONEER RD

We append below our repair estimate for PC8868E

Repair Estimate

Parts Required :-

1 Pc Front Panel Decorative Lamp / BR	\$ 300.00
1 Pc Front Left Combination Headlight / BR	\$ 450.00
1 Pc Front Wall Exterior Cover Assy (gntk) / BR	\$ 280.00
	\$ 1,030.00
Less 10% trade discount	\$ 103.00
	\$ 927.00

Labour Charges :-

a. To putty and spray painting on all affected accident parts including design painting on same (multi color).	\$ 800.00	700
b. To jack/knock/ straighten all necessary parts including repairing and changing of all damaged parts and align same.	\$ 450.00	350
c. To remove combination headlight and refit new.	\$ 400.00	80
Total repair cost	\$ 2,577.00	

Note :- This estimate is based on visible damage only. Should any hidden parts and/or labour required during works in progress, insurer and/or their surveyor will be notified accordingly.

ONE LINE MOTORWORKS TRADING



Neo Say Pheng (H/P : 97971868)

Neo Swee Tiong (H/P : 97641868)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: