

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE I	PTE LTD	Ref:	CS3/ASM21006345/Vuce2	
	8 SHENTON WAY TOWERSINGAPOR		Date:	17/06/2021	
	ATTN: KUMAR SH	AILENDRA	Code	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	FBP 6682J	Veh. Inspected	SJN 761U	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	S1M03B5W	Excess (\$)	0.00	
	Assign From	KITTY TAN	Assign Date	02/06/2021	
2. Vehicle Particulars & Condition					
	Make & Model	HONDA FREED 1.5G A	c.c	1496	
	Engine No.	HIDDEN	Year of Reg.	2011	
	Chassis No.	GB31004589	Colour	BLUE	
	Odometer	154953 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	185/65 R15	CONTINENTAL	6 mm	
	L/H Front Tyre	185/65 R15	CONTINENTAL	6 mm	
	R/H Rear Tyre	185/65 R15	CONTINENTAL	6 mm	
	L/H Rear Tyre	185/65 R15	CONTINENTAL	6 mm	
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.				
5.	5. General Information				
	Accident Date	28/05/2021	Inspect Date / Time	08/06/2021 ( 12:00 PM )	
	Survey held at TOPMAX AUTO BODYSHOP				
	BLK 3007 UBI ROAD 1 #01-410 SINGAPORE 408701				
5a.	5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000				
5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				

Report Ref No. CS3/ASM21006345/Vuce2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

The

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser