



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. AEW 7988

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR TO SUPPLY LABOUR,TOOLS AND EQUIPMENT TO MANUALLY HACK,DEMOLISH AND DISPOSE OFF SITE THE DAMAGED BOUNDARY WALL BESIDE MAIN ENTRANCE APPROX,6M LONGX2.1M HIGH. } TO RE-CONSTRUCT/REPAIR THE RC BASE,VERTICAL STIFFERNERS AND TOP LINTEL AND CONSTRUCT NEW BRICK WALL AS PER EXISTING DESIGN INCLUDING PLASTERING AND PAINTING WORKS TO BOTH SIDES OF WALL TO MATCH EXISTING. } TO SUPPLY AND INSTALL NEW COMPANY'S SIGNAGE LETTERINGS SIMILAR TO EXISTING. } PROVISION FOR HARD BARRICADE (AT PUBLIC WALKWAY AREA).INSURANCE AND SITE SUPERVISION. }		12,800.00	10,000.00
			-	-
			-	-
			-	-
			12,800.00	10,000.00
	GRAND TOTAL		12,800.00	10,000.00
	RECOMMENDED COST OF REPAIRS			10,000.00

Report Ref No. CS1/LPM21006346/Lvf3e2

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.