

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21006350/T1QCN2**Date:** 20/08/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00075562000
Claimant Vehicle No :	SMX3467L	Insured Vehicle No :	SLK9452U
Date of Loss:	13/05/2021	Nature of Claim:	TP
		Claim No:	SNM21D202789/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX3467L	Engine No:	P520636573
Make & Model:	MAZDA 3, 1.5 (A)	Chassis No:	JM6BP2SAAK1102608
Reg. Date:	07/01/2021 (Man. Year: 2019)	Odometer:	7867 km
Colour:	Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45R18	Rear Tyre Size:	215/45R18
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,448.90	4,078.80	6,370.10	60.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,340.00	6,780.00	4,560.00	40.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	21,788.90	10,858.80	10,930.10	50.16
+ GST 7.00/7.00% (\$\$)	1,525.22	760.12	765.10	50.16
Nett Amount (\$\$)	23,314.12	11,618.92	11,695.20	50.16

INSPECTION

Date of Assignment:	01/06/2021	
Date Inspected:	03/06/2021	Inspected At:
Estimated Period of Repair:	9.0 days	

300A ANG MO KIO AVE 5
SINGAPORE 569883
REPAIRER: TRANS EUROKARS PTE LTD

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$2,388.70 NETT)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Aug 2021)
Parts:	144	MAZDA 3 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMX3467L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER RH	Repair	1,643.60 F	*- F
2	1		*SIDE STEP RH	Cut	757.70 F	*757.70 F
3	6		*CLIP,SIDE STEP	Necessary	60.00 F	*60.00 F
4	1		*CLIP,SIDE STEP (22 Pcs)	Necessary	61.60 F	*61.60 F
5	2		*CLIP,SIDE STEP	Necessary	7.40 F	*7.40 F
6	1		*REAR DOOR RH	Bent	954.10 F	*954.10 F
7	1		*WEATHERSTRIP REAR DOOR RH	*Check	70.70 F	*- F
8	1		*FASTENER,WEATHERSTRIP (22 Pcs)	*Check	52.80 F	*- F
9	1		*HINGE REAR DOOR UPPER	Repair	48.30 F	*- F
10	1		*HINGE REAR DOOR LOWER	Repair	44.80 F	*- F
11	1		*MOULDING REAR DOOR RH	*Check	90.00 F	*- F
12	2		*FASTENER REAR DOOR	*Check	4.80 F	*- F
13	2		*CLIP REAR DOOR	*Check	5.60 F	*- F
14	6		*GROMMET,SCREW REAR DOOR	*Check	14.40 F	*- F
15	2		*CHECKER,REAR DOOR RH	Not Necessary	85.60 F	*- F
16	4		*PLUG,DRAIN	*Check	10.80 F	*- F
17	1		*FRONT RH DOOR	Repair	1,127.50 F	*- F
18	1		*MOULDING FRONT DOOR RH	Not Necessary	80.00 F	*- F
19	1		*WEATHERSTRIP FRONT DOOR RH	*Check	96.60 F	*- F
20	2		*FASTENER FRONT DOOR	*Check	4.80 F	*- F
21	2		*FASTENER FRONT DOOR	*Check	4.80 F	*- F
22	5		*FASTENER WEATHERSTRIP	*Check	17.00 F	*- F
23	1		*FASTENER WEATHERSTRIP (22 Pcs)	*Check	52.80 F	*- F
24	4		*CLIP,GARNISH	*Check	54.80 F	*- F
25	12		*CLIP,GARNISH	*Check	147.60 F	*- F
26	1		*SIDE MIRROR RH	Cut	659.20 F	*659.20 F
27	1		*SIGNAL LAMP SIDE MIRROR	Cracked	124.30 F	*124.30 F
28	1		*HOUSING RH SIDE MIRROR	Cut	75.30 F	*75.30 F
29	1		*GLASS & HOLDER RH SIDE MIRROR	*Check	711.20 F	*- F
30	1		*TRIANGLE SMALL COVER RH FRONT DOOR	Cut	47.50 F	*47.50 F
31	6		*CLIP,TRIANGLE SMALL COVER FRONT DOOR	Necessary	66.00 F	*66.00 F
32	1		*WHEEL,DISC-ALUMI.18X7	Cut (1 Pc only)	2,478.00 F	*1,239.00 F
33	1		*VALVE,AIR WHELL DISC	Cut (1 Pc only)	13.40 F	*6.70 F
34	1		*FRONT FENDER RH	Repair	415.90 F	*- F
35	1		*MUDGUARD FRONT RH	Not Necessary	185.90 F	*- F
36	1		*FASTENER MUDGUARD (22 Pcs)	Not Necessary	66.00 F	*- F
37	3		*PLUG,DRAIN	Not Necessary	8.10 F	*- F
38	1		*SUNDRIES	Necessary	100.00 F	*20.00 F

F=Franchise part.

Total Parts (\$\$) 10,448.90 4,078.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT FRONT & REAR BUMPER AND TO REPLACE FRONT FENDER,FRONT DOOR,REAR DOOR AND REAR FENDER.REPAIR ALL AREAS AFFECTED BY THE ACCIDENT	New	5,280.00	3,300.00
2	TO RESPRAY REAR FENDER,REAR DOOR,FRONT DOOR,FRONT FENDER AND SIDE STEP	New	4,410.00	3,150.00
3	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT *Check	New	560.00	0.00
4	TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING X2 *Check	New	240.00	0.00
5	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	150.00
6	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	350.00	180.00
7	TO CARRY-OUT BODY CAVITY PRESERVATION (INCLUDING NEW PARTS AND CAOUTCHOU)C *Check	New	250.00	0.00
Gross Labour Cost (\$\$)			11,340.00	6,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >