

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21006353/DBS3Q2
Date: 13/08/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SMG198Y	Insured Vehicle No :	SLS7299S
Date of Loss:	01/06/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0002442

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG198Y		
Make & Model:	HONDA SHUTTLE, 1.5 G CVT (A)	Engine No:	LEB7100696
Reg. Date:	14/12/2018 (Man. Year: 2018)	Chassis No:	GP72000432
Colour:	Red	Odometer:	266148 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,364.00	4,564.80	19,799.20	81.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,000.00	1,040.00	4,960.00	82.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,364.00	5,604.80	24,759.20	81.54
Approved Total (Overridden) (S\$)		4,450.00		

(S\$)	30,364.00	4,450.00	25,914.00	85.34
+ GST 7.00/7.00% (S\$)	2,125.48	311.50	1,813.98	85.34
Nett Amount (S\$)	32,489.48	4,761.50	27,727.98	85.34
+ Loss of Use (7.0 x S\$80.00/day) (S\$)		560.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		5,357.95		
Global Sum Settlement (S\$)		5,350.00		

INSPECTION

Date of Assignment: 02/06/2021

Date Inspected: 04/06/2021

Inspected At:

JWG International Pte Ltd (HQ)
 Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK AutoPoint
 Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: BRYAN TANI**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 03 Aug 2021)	
Parts:	N/A	HONDA SHUTTLE 1.5 G CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMG198Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent / Dented	2,398.00 FL	*920.80 FL
2	1		*BONNET INSULATOR	Not Necessary	410.00 FL	*- FL
3	1		*BONNET LOCK	Not Necessary	382.00 FL	*- FL
4	2		*BONNET HINGE LH/RH	Not Necessary	258.00 FL	*- FL
5	1		*BONNET SEAL	Not Necessary	194.00 FL	*- FL
6	1		*FRONT GRILLE	Not Necessary	892.00 FL	*- FL
7	1		*FRONT GRILLE BASE	Deformed / Mtg Cracked	771.00 FL	*395.00 FL
8	1		*FRONT GRILLE CHROME	Cracked	695.00 FL	*302.50 FL
9	1		*FRONT GRILLE LOGO	Necessary	101.00 FL	*23.40 FL
10	1		*HEAD LAMP LH/RH	O/S Cracked / N/S Not Necessary	4,838.00 FL	*1,230.00 FL
11	2		*HEAD LAMP CHROME MOULDING LH/RH	Not Necessary	462.00 FL	*- FL
12	1		*HEAD LAMP LOWER BRACKET LH/RH	O/S Broken / N/S Not Necessary	396.00 FL	*91.60 FL
13	2		*HEAD LAMP CONTROL MODULE LH /RH	Not Necessary	3,658.00 FL	*- FL
14	1		*FRONT BUMPER	Distorted	1,140.00 FL	*1,050.00 FL
15	2		*FRONT BUMPER SIDE RETAINER LH/RH	Not Necessary	170.00 FL	*- FL
16	1		*FRONT BUMPER GRILLE	Deformed	495.00 FL	*224.30 FL
17	2		*FRONT BUMPER FOG LAMP LH/RH	Not Necessary	820.00 FL	*- FL
18	2		*FRONT BUMPER FOG LAMP GARNISH LH/RH	Not Necessary	596.00 FL	*- FL
19	2		*FRONT BUMPER FOG LAMP HOLDER LH/RH	Not Necessary	482.00 FL	*- FL
20	2		*FRONT BUMPER FOG LAMP CHROME LH/RH	Not Necessary	580.00 FL	*- FL
21	1		*FRONT BUMPER TOW HOOK COVER	Not Necessary	94.00 FL	*- FL
22	1		*FRONT BUMPER SPONGE	Not Necessary	324.00 FL	*- FL
23	1		*FRONT REINFORCEMENT BAR	Dented	990.00 FL	*420.90 FL
24	1		*FRONT SUPPORT PANEL	Repair	1,982.00 FL	*- FL
25	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	321.00 FL	*- FL
26	1		*A/C CONDENSOR	Punctured	1,782.00 FL	*985.00 FL
27	1		*A/C CONDENSOR DISCHARGE HOSE	Not Necessary	879.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*A/C CONDENSOR SUCTION HOSE	Not Necessary	375.00 FL	*- FL
29	1		*RADIATOR ASSY	Not Necessary	2,194.00 FL	*- FL
30	1		*RADIATOR FAN MOTOR	Not Necessary	452.00 FL	*- FL
31	1		*RADIATOR FAN BLADE	Not Necessary	198.00 FL	*- FL
32	1		*RADIATOR FAN COWLING	Not Necessary	501.00 FL	*- FL
33	1		*BONNET INSULATOR CLIPS	Not Necessary	50.00 FS	*- FS
34	1		*FRONT GRILLE CLIPS	Necessary	50.00 FS	*15.00 FS
35	1		*HEAD LAMP CLIPS	Not Necessary	50.00 FS	*- FS
36	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
37	1		*FRONT BUMPER GRILLE CLIPS	Necessary	50.00 FS	*15.00 FS
38	1		*FRONT BUMPER FOG LAMP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
39	1		*FRONT NO PLATE & CASING	Serviceable	100.00 FS	*- FS
40	1		*COOLANT	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	30,330.00	5,693.50
- List Item Discount on L Items 20.00/20.00% (\$)	5,966.00	1,128.70
Total Parts (\$)	24,364.00	4,564.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,400.00	500.00
2	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,400.00	400.00
3	TO TUFF COAT DAMAGED AREAS	New	300.00	30.00
4	TO RNR A/C CONDERSOR & REFILL GAS TO FACILITATE REPAIRS	New	200.00	80.00
5	TO RNR RADIATOR & REFILL COOLANT TO FACILITATE REPAIRS	New	200.00	0.00
6	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
7	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
Gross Labour Cost (S\$)			6,000.00	1,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >