

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21006355/UBS3Q2
Date: 06/10/2021**REFERENCE**Handling Insurer: India International Insurance Pte Ltd
Claimant Vehicle No : FBR5097U
Date of Loss: 25/07/2020Policy No:
Insured Vehicle No : GBH6088S
Nature of Claim: TP
Claim No: N/A**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **FBR5097U**
Make & Model: HONDA NSS 300A, 279cc
Reg. Date: 20/07/2020 (Man. Year: 2019)
Colour: Grey
Engine Capacity: 279 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**
Engine No: NF07E2018271
Chassis No: MLHNF0797J5000734
Odometer: 361 km**CONDITION OF VEHICLE AT THE TIME OF SURVEY**General Condition: Steering (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No
Footbrake (Serviceable): Yes
Pre-accident Condition: Yes**CONDITION OF TYRES**Front Tyre Size: 120/70-15
Front Left Side: Pirelli 7 mm
Front Right Side: 0 mm
Rear Tyre Size: 140/70-14
Rear Left Side: Pirelli 7 mm
Rear Right Side: 0 mm*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,566.30	4,427.20	3,139.10	41.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,450.00	810.00	640.00	44.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	9,016.30	5,237.20	3,779.10	41.91
+ Loss of Use (6.0 x S\$30.00/day) (S\$)		180.00		

Nett Liability (S\$)	5,417.20
Global Sum Settlement (S\$)	5,300.00

INSPECTION

Date of Assignment: 31/05/2021

Date Inspected: 31/05/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Erofia Motor Trading Pte Ltd - (kaki Bukit) (HQ)
1 Kaki Bukit Avenue 6, #02-62 AutoBay @ Kaki Bukit
Singapore 417883

Adjuster: MARCUS CHUA

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 14 Sep 2021)	
Parts:	N/A	HONDA NSS 300A 279cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBR5097U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FORK ASSY	Serviceable	960.00 FL	*- FL
2	1		*FORK UNDER BRACKET	Not Necessary	200.00 FL	*- FL
3	1		*FRONT FENDER	Cut	120.00 FL	*120.00 FL
4	1		*FRONT RIM	Not Necessary	600.00 FL	*- FL
5	1		*FRONT BRAKE DISC	Not Necessary	130.00 FL	*- FL
6	1		*FRONT RIM SHAFT	Not Necessary	80.00 FL	*- FL
7	1		*FRONT FENDER REAR (MATT BLACK)	Not Necessary	180.00 FL	*- FL
8	1		*FRONT SIDE COVER -R/L/H (WHITE)	Cracked	380.00 FL	*380.00 FL
9	1		*FRONT SIDE INNER COVER -R/L/H (SILVER)	Cracked	180.00 FL	*140.00 FL
10	1		*FRONT LOWER CENTRE COVER	Cut	245.00 FL	*245.00 FL
11	1		*HANDLE -BAR	Serviceable	160.00 FL	*- FL
12	1		*HANDLE -BAR END (O/S)	Cut	76.00 FL	*30.00 FL
13	1		*SET MIRROR	Cut	180.00 FL	*180.00 FL
14	1		*BRAKE LEVER	Scratched	95.00 FL	*68.00 FL
15	1		*REAR SIDE COVER -R/H	Cut	240.00 FL	*240.00 FL
16	1		*FOOTSTEP PANELS	Distorted	235.00 FL	*235.00 FL
17	1		*FOOTSTEP LOWER PANELS	Distorted	220.00 FL	*220.00 FL
18	1		*EXHAUST PIPE ASSY	Dented / Bent	980.00 FL	*800.00 FL
19	1		*EXHAUST PROTECTOR (MATT BLACK)	Distorted	110.00 FL	*110.00 FL
20	1		*EXHAUST PROTECTOR (CHROME)	Distorted	120.00 FL	*120.00 FL
21	1		*EXHAUST END CAP	Cracked	95.00 FL	*60.00 FL
22	1		*REAR HANDLE	Repair	186.00 FL	*- FL
23	1		*REAR FENDER	Cracked	210.00 FL	*210.00 FL
24	1		*TOP REAR FENDER	Cracked	155.00 FL	*155.00 FL
25	1		*REAR TAILLAMP	Broken	280.00 FL	*245.00 FL
26	1		*REAR NUMBER PLATE LAMP	Broken	95.00 FL	*50.00 FL
27	1		*SET NUMBER PLATE	Rear Bent	28.00 FS	*10.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	2		*FORK OILS	Not Necessary	40.00 FS	*- FS
29	2		*FORK OIL SEALS	Not Necessary	96.00 FS	*- FS
30	1		*SET BEARING CONE	Not Necessary	115.00 FS	*- FS
31	1		*FRONT LOWER SIDE COVER -R/H	Cracked	180.00 FL	*145.00 FL
32	1		*FRONT CENTRE INNER COVER	Cracked	780.00 FL	*620.00 FL
33	1		*REAR SIDE COVER -L/H	Cracked	240.00 FL	*150.00 FL
34	1		*REAR CENTRE COVER	Cracked	105.00 FL	*105.00 FL
35	1		*SEAT COMPARTMENT	Cracked	280.00 FL	*280.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,376.00	4,918.00
- List Item Discount on L Items 10.00/10.00% (\$)	809.70	490.80
Total Parts (\$)	7,566.30	4,427.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PROVIDE TOWING SERVICE (LOD)	New	30.00	30.00
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	120.00	0.00
3	TO PROVIDE PAINT WORK & STRAIGHTEN BODY FRAME	New	800.00	400.00
4	TO PROVIDE LABOUR	New	500.00	380.00
Gross Labour Cost (S\$)			1,450.00	810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >