6/9/2021 Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/AIG21006358/R1TF3Q2

Date:

09/06/2021

REFERENCE

Date of Loss:

Reg. Date:

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

2100281668

Claimant Vehicle No:

SBS3472C 02/05/2021 Insured Vehicle No: Nature of Claim:

SKD4662L ΤP

Claim No:

9602648652SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SBS3472C

Make & Model: MERCEDES-BENZ 200E, 2.0 (A)

02/11/2015 (Man. Year: 2015)

Chassis No: Odometer:

Engine No:

YV3S4P925FA173186

D9194387

335398 km

Colour: Green

Engine Capacity: 9364 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable): Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Left Side:

Front Right Side:

Front Tyre Size:

275/70R22.5

Bridgestone 8 mm

Bridgestone 8 mm

Yes

Rear Tyre Size: Rear Left Side:

275/70R22.5(D) Bridgestone 8/8 mm

Rear Right Side:

Bridgestone 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		0.00	0.00	0.00	
Miscellaneous Items		0.00	0.00	0.00	
Labour		778.00	586.00	192.00	24.68
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Nett Amount (S\$)	778.00	586.00	192.00	24.68

INSPECTION

6/9/2021 Adjuster Report

Date of Assignment: 03/06/2021

Date Inspected: 03/06/2021 Inspected At: SBS Transit Ltd (YCK)

3 Yio Chu Kang Crescent

Singapore 786010

Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	SPRAY PAINT-GREEN;5L;SG BUS	New	36.00	36.00
2	CONTRACTOR LABOUR COST	New	550.00	550.00
3	WORKSHOP ADMIN COST	New	192.00	0.00
		Gross Labour Cost (S\$)	778.00	586.00
	Report wa	s unsubmitted during this print-out.		

< END OF ESTIMATES >