

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMQ 684H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	DEFORMED	934.40	934.40
1	FRONT BUMPER R/H SIDE RETAINER	NECESSARY	121.60	121.60
1	R/H FRONT FENDER	TO REPAIR SEE LABOUR	786.00	-
1	FRONT LOGO EMBLEM	NOT NECESSARY	187.00	-
1	FRONT UPPER GRILLE	NOT NECESSARY	1,056.00	-
1	FRONT GRILLE GARNISH	NOT NECESSARY	1,144.00	-
1	FRONT BOTTOM GRILLE	NOT NECESSARY	209.00	-
1	HEADLAMP	BROKEN	3,882.00	3,001.75
	LESS 25% DISCOUNT		-	-1,014.44
			8,320.00	3,043.31
LABOUR				
	TO PANEL BEAT AND RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS.INCLUSIVE OF THE REPAIR OF R/H FRONT FENDER.		800.00	300.00
	TO CHECK WIRING AND REWIRE. }		80.00	30.00
	TO REALIGN HEADLAMP. }		60.00	-
	TO APPLY ANTI-RUST.	NOT NECESSARY	100.00	-
	TO PUTTY AND SPRAY-PAINT OF AFFECTED AREAS.		800.00	400.00
			1,840.00	730.00
GRAND TOTAL			10,160.00	3,773.31
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,000.00

Report Ref No. CS3/AIG21005238/Gtf3n2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.