

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21006364/EVF3E2

Date: 27/07/2021

REFERENCE

Insured/Claimant:	ASTON LIN HAOMIN	Policy No:	1900164131	
Date of Loss:	02/06/2021	Nature of Claim:	OD	Claim No: 2275561041SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP5790G	Engine No:	G4FGKH747997
Make & Model:	KIA CERATO, 1.6 (A)	Chassis No:	KNAF3416MK5051632
Reg. Date:	01/10/2019 (Man. Year: 2019)	Odometer:	0 km
Colour:	Silver		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$78,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Nexen 5 mm	Rear Left Side:	Nexen 5 mm
Front Right Side:	Nexen 5 mm	Rear Right Side:	Nexen 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,326.60	20,334.20	5,992.40	22.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	21,340.00	13,440.00	7,900.00	37.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	47,666.60	33,774.20	13,892.40	29.14
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	47,366.60	33,474.20	13,892.40	29.33
+ GST 7.00/7.00% (S\$)	3,315.66	2,343.19	972.47	29.33
Nett Amount (S\$)	50,682.26	35,817.39	14,864.87	29.33

INSPECTION

Date of Assignment:	03/06/2021	
Date Inspected:	02/06/2021	Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	23.0 days	

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
2	1		*FRT NUMBER PLATE WITH CASING	Broken	50.00 FS	*50.00 FS
3	1		*RR NUMBER PLATE WITH CASING	Not Necessary	50.00 FS	*- FS
4	1		*REVERSE SENSOR	Shorted	220.00 FS	*220.00 FS
5	1		*SUNDRIES	Necessary	50.00 FS	*30.00 FS
6	1		*COVER-FR BUMPER	Broken	633.00 FL	*633.00 FL
7	1		*CAP-FRONT HOOK	Not Necessary	9.00 FL	*- FL
8	1		*GRILLE-FRONT BUMPER	Cut	262.00 FL	*262.00 FL
9	1		*GRILLE ASSY-RADIATOR	Broken	328.00 FL	*328.00 FL
10	1		*GARNISH-RADIATOR GRILLE	Broken	38.00 FL	*38.00 FL
11	1		*COVER-FR BUMPER FOG LAMP, LH	Broken	15.00 FL	*15.00 FL
12	1		*COVER-FR BUMPER FOG LAMP, RH	Not Necessary	15.00 FL	*- FL
13	1		*LAMP ASSY-FRONT FOG, LH	Not Necessary	303.00 FL	*- FL
14	1		*MOULDING-FRONT BUMPER, LH	Cut	36.00 FL	*36.00 FL
15	1		*MOULDING-FRONT BUMPER, RH	Not Necessary	36.00 FL	*- FL
16	1		*LAMP ASSY-SIDE REPEATER, LH	Cut	143.00 FL	*143.00 FL
17	1		*LAMP ASSY-SIDE REPEATER, RH	Not Necessary	143.00 FL	*- FL
18	1		*AIR DUCT-FR BUMPER, LH	Broken	14.00 FL	*14.00 FL
19	1		*AIR DUCT-FR BUMPER, RH	Not Necessary	14.00 FL	*- FL
20	1		*STIFFNER-FR BPR LWR	Not Necessary	114.00 FL	*- FL
21	1		*BRACKET-FR BUMPER UPR SIDE MTG (LH)	Broken	22.00 FL	*22.00 FL
22	1		*BRACKET-FR BUMPER UPR SIDE MTG (RH)	Not Necessary	22.00 FL	*- FL
23	1		*BEAM COMPLETE-FR BUMPER	Dented	497.00 FL	*497.00 FL
24	1		*CARRIER ASSY-FRONT END MODULE	Broken	675.00 FL	*675.00 FL
25	1		*LAMP ASSY-HEAD, LH	Broken	1,219.00 FL	*1,219.00 FL
26	1		*LAMP ASSY-HEAD, RH	Cut	1,219.00 FL	*1,219.00 FL
27	1		*PANEL ASSY-HOOD	Dented	1,502.00 FL	*1,502.00 FL
28	1		*HINGE ASSY-HOOD, LH	Bent	43.00 FL	*43.00 FL
29	1		*HINGE ASSY-HOOD, RH	Bent	43.00 FL	*43.00 FL
30	1		*PANEL-FENDER, LH	Dented	430.00 FL	*430.00 FL
31	1		*PANEL-FENDER, RH	Dented	430.00 FL	*430.00 FL
32	1		*PAD-HOOD INSULATIONG	Crushed	156.00 FL	*156.00 FL
33	13		*CLIP-HOOD INSULATING PAD MTG	Necessary	13.00 FL	*13.00 FL
34	1		*LATCH ASSY-HOOD	Bent	103.00 FL	*103.00 FL
35	1		*GUARD ASSY-FRONT WHEEL, LH	Broken	95.00 FL	*95.00 FL
36	1		*GUARD ASSY-FRONT WHEEL, RH	Not Necessary	95.00 FL	*- FL
37	1		*ORNAMENT-KIA NO.115	Necessary	32.00 FL	*32.00 FL
38	1		*GLASS-WINDSHIELD	Not Necessary	821.00 FL	*- FL
39	1		*MOULDING-WINDSHIELD GLASS	Not Necessary	56.00 FL	*- FL
40	1		*COVER ASSY-COWL TOP	Broken	247.00 FL	*247.00 FL
41	1		*COVER-AFTER SERVICE, LH	Not Necessary	11.00 FL	*- FL
42	1		*CPVER-AFTER SERVICE, RH	Not Necessary	11.00 FL	*- FL
43	1		*MIRROR ASSY-OUTSIDE RR VIEW, RH	Not Necessary	559.00 FL	*- FL
44	1		*RESERVOIR & PUMP ASSY-WASHER	Not Necessary	146.00 FL	*- FL
45	1		*PANEL ASSY-UNDER COVER	Not Necessary	117.00 FL	*- FL
46	1		*GUARD-AIR, LH	Broken	28.00 FL	*28.00 FL
47	1		*GUARD-AIR, RH	Broken	28.00 FL	*28.00 FL
48	1		*CONDENSER ASSY-COOLER	Dented	687.00 FL	*687.00 FL
49	1		*RADIATOR ASSY	Dented	646.00 FL	*646.00 FL
50	1		*HOSE ASSY-RADIATOR, LWR	Not Necessary	40.00 FL	*- FL
51	1		*HOSE-RADIATOR TO RESERVOIR	Not Necessary	27.00 FL	*- FL
52	1		*CAP ASSY-RADIATOR	Not Necessary	24.00 FL	*- FL
53	1		*FILLER NECK ASSY-RADIATOR	Broken	28.00 FL	*28.00 FL
54	1		*CLAMP-HOSE	Not Necessary	7.00 FL	*- FL
55	1		*HOSE-RADIATOR INLET	Not Necessary	31.00 FL	*- FL

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*HOSE ASSY-RADIATOR, UPR	Not Necessary	27.00 FL	*- FL
57	1		*BLOWER ASSY	Broken	656.00 FL	*656.00 FL
58	1		*DUCT-EXTENSION	Broken	5.00 FL	*5.00 FL
59	1		*SHIELD-AIR INTAKE	Broken	9.00 FL	*9.00 FL
60	1		*DUCT ASSY-AIR	Broken	55.00 FL	*55.00 FL
61	1		*CLEANER ASSY-AIR	Broken	174.00 FL	*174.00 FL
62	1		*HOSE ASSY-AIR INTAKE	Broken	83.00 FL	*83.00 FL
63	1		*DUCT ASSY-EXTENSION	Not Necessary	115.00 FL	*- FL
64	1		*COVER ASSY-ENGINE	Cut	212.00 FL	*212.00 FL
65	1		*MANIFOLD ASSY-INTAKE	Broken	906.00 FL	*906.00 FL
66	1		*HORN ASSY-LOW PITCH	Not Necessary	74.00 FL	*- FL
67	1		*UPR COVER- ENG ROOM BOX	Not Necessary	26.00 FL	*- FL
68	1		*LAMP ASSY-REAR COMB OUTSIDE, LH	Not Necessary	675.00 FL	*- FL
69	1		*LAMP ASSY-REAR COMB OUTSIDE, RH	Cut	675.00 FL	*675.00 FL
70	1		*LAMP ASSY-REAR COMB INSIDE, LH	Not Necessary	608.00 FL	*- FL
71	1		*LAMP ASSY-REAR COMB INSIDE, RH	Cut	608.00 FL	*608.00 FL
72	1		*LAMP ASSY-CENTER GARNISH	Not Necessary	690.00 FL	*- FL
73	1		*PANEL ASSY-TRUNK LID	Dented	1,297.00 FL	*1,297.00 FL
74	1		*HINGE ASSY-TRUNK LID, LH	Not Necessary	97.00 FL	*- FL
75	1		*HINGE ASSY-TRUNK LID, RH	Not Necessary	97.00 FL	*- FL
76	1		*PANEL ASSY-BACK	Dented	324.00 FL	*324.00 FL
77	1		*W/STRIP-TRUNK LID OPNG	Crushed	100.00 FL	*100.00 FL
78	1		*LATCH ASSY-TRUNK LID	Cut	112.00 FL	*112.00 FL
79	1		*STRIKER ASSY-TRUNK LID	Not Necessary	40.00 FL	*- FL
80	1		*TRIM ASSY-RR TRANSVERSE	Cut	41.00 FL	*41.00 FL
81	1		*MAT ASSY-LUGGAGE COVERING	Not Necessary	211.00 FL	*- FL
82	1		*EMBLEM-CERATO	Necessary	28.00 FL	*28.00 FL
83	1		*LOGO ASSY-KIA SUB	Necessary	32.00 FL	*32.00 FL
84	1		*COVER-RR BUMPER	Broken	651.00 FL	*651.00 FL
85	1		*COVER-RR BUMPER LWR	Broken	241.00 FL	*241.00 FL
86	1		*COVER-RR BUMPER UNDER, LH	Broken	33.00 FL	*33.00 FL
87	1		*COVER-RR BUMPER FOG LAMP, LH	Cut	19.00 FL	*19.00 FL
88	1		*COVER-RR BUMPER FOG LAMP, RH	Cut	19.00 FL	*19.00 FL
89	1		*LAMP ASSY-SIDE T/SIGNAL, LH	Cut	181.00 FL	*181.00 FL
90	1		*LAMP ASSY-SIDE T/SIGNAL, RH	Cut	181.00 FL	*181.00 FL
91	1		*EXTN WIRING ASSY-BWS	Broken	207.00 FL	*207.00 FL
92	1		*BEAM-RR BUMPER	Broken	318.00 FL	*318.00 FL
93	1		*STAY-RR BUMPER LH	Bent	65.00 FL	*65.00 FL
94	1		*STAY-RR BUMPER RH	Bent	65.00 FL	*65.00 FL
95	1		*BRACKET-RR BEAM UPR MTG, LH	Broken	9.00 FL	*9.00 FL
96	1		*BRACKET-RR BEAM UPR MTG, RH	Not Necessary	9.00 FL	*- FL
97	1		*BRACKET-RR BEAM LWR, CTR	Broken	6.00 FL	*6.00 FL
98	1		*BRACKET-RR BEAM LWR, MTG	Broken	6.00 FL	*6.00 FL
99	1		*ANTENNA ASSY-SMARTKEY	Not Necessary	46.00 FL	*- FL
100	1		*COVER-RR BUMPER UNDER, RH	Not Necessary	33.00 FL	*- FL
101	1		*BRACKET ASSY-RR BPR SIDE UPR, L	Not Necessary	25.00 FL	*- FL
102	1		*BRACKET ASSY-RR BPR SIDE UPR, R	Not Necessary	31.00 FL	*- FL
103	1		*PANEL ASSY-REAR FLOOR, RR	Dented	219.00 FL	*219.00 FL
104	1		*REINF-RR SPARE TIRE WELL CROSS	Necessary	41.00 FL	*41.00 FL
105	1		*MUFFLER ASSY-REAR	Not Necessary	757.00 FL	*- FL
106	1		*PROTECTOR-HEAT REAR	Not Necessary	136.00 FL	*- FL
107	2		*GASKET-EXHAUST PIPE	Not Necessary	28.00 FL	*- FL
108	1		*MUFFLER COMPLETE-CENTER	Not Necessary	907.00 FL	*- FL
109	1		*BRACKET ASSY-SPARE TIRE MTG	Not Necessary	15.00 FL	*- FL
110	1		*REINF-TOWING HOOK	Not Necessary	14.00 FL	*- FL
111	1		*BRKT ASSY-RR SEAT & MER MTG, LH	Not Necessary	11.00 FL	*- FL
112	1		*REINF-RR FLR SD MBR CTR, LH	Not Necessary	14.00 FL	*- FL
113	1		*TRIM ASSY-TRUNK LID (Supplementary)	Crushed	202.00 FL	*202.00 FL
114	1		*CLAMP-SPARE TIRE (Supplementary)	Broken	6.00 FL	*6.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
115	1		*PANEL ASSY-RR COMB LAMP HSG, LH (Supplementary)	Bent	139.00 FL	*139.00 FL
116	1		*PANEL ASSY-RR COMB LAMP HSG, RH (Supplementary)	Bent	135.00 FL	*135.00 FL
117	1		*SILENCER, FLOOR (Supplementary)	Necessary	13.00 FL	*13.00 FL
118	20		*CLIP (Supplementary)	Necessary	20.00 FL	*20.00 FL
119	1		*COOLANT (4L) (Supplementary)	Necessary	26.00 FL	*26.00 FL
120	1		*ABSORBER-FRONT BUMPER ENERGY (Supplementary)	Broken	84.00 FL	*84.00 FL
121	2		*CLIP-HEAD LAMP MTG (Supplementary)	Broken	8.00 FL	*8.00 FL
122	1		*TRAY ASSY-BATTERY (Supplementary)	Broken	49.00 FL	*49.00 FL
123	1		*INSULATION PAD-BATTERY (Supplementary)	Torn	33.00 FL	*33.00 FL
124	1		*BRACKET ASSY-RADIATOR MTG, UPR (Supplementary)	Broken	29.00 FL	*29.00 FL
125	1		*BUZZER ASSY-PIEZO (Supplementary)	Broken	68.00 FL	*68.00 FL
126	1		*WIRING ASSY-FRT (Supplementary)	Torn	3,825.00 FL	*3,825.00 FL
127	1		*WIRING ASSY-CONTROL (Supplementary)	Torn	966.00 FL	*966.00 FL
128	1		*BODY ASSY-THROTTLE (Supplementary)	Broken	636.00 FL	*636.00 FL
129	1		*HOSE ASSY-VAPOR (Supplementary)	Torn	42.00 FL	*42.00 FL
130	1		*ELECTRONIC CONTROL UNIT (Supplementary)	Broken	1,305.00 FL	*1,305.00 FL
131	1		*HOSE ASSY-WATER A (Supplementary)	Crushed	23.00 FL	*23.00 FL
132	1		*BATTERY-AGM LN2 (DIN55L) (Supplementary)	Broken	195.00 FS	*195.00 FS
133	1		*HOOK-TOWING	Not Necessary	16.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	32,747.00	25,294.00
- List Item Discount on L Items 20.00/20.00% (\$)	6,420.40	4,959.80
Total Parts (\$)	26,326.60	20,334.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW (FR) FR BUMPER, FRT SUPPORT, BONNET, LHF FENDER, RHF FENDER & LHF WHEELHOUSE PNL. REPAIR LHF A PILLAR, RHF A PILLAR, LHF DOOR, RHF DOOR & FR CHASSIS	New	4,000.00	2,000.00
2	RENEW (RR) RR BUMPER, RR END PNL, BOOTLID & RR FLR PNL. REPAIR LHR FENDER, RHR FENDER, RR CHASSIS & BOTH RR WHEELHOUSE	New	4,000.00	2,800.00
3	RENEW AIRCON CONDENSER & RADIATOR	New	100.00	100.00
4	TOP UP AIRCON GAS	New	80.00	80.00
5	REMOVE & REFIT ENGINE & GEARBOX ASSY	New	800.00	0.00
6	REMOVE & REFIT BOOTLID COMPONENT	New	120.00	120.00
7	REMOVE & REFIT FUEL TANK ASSY TO FACILITATE REPAIR	New	200.00	200.00
8	RENEW RR EXHAUST MUFFLER ASSY & MOUNTING	New	200.00	200.00
9	REMOVE & REFIT ALL FLR CARPET, TRIM & SEAT TO FACILITATE REPAIR	New	600.00	400.00
10	CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM	New	50.00	30.00
11	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
12	CONDUCT CHASSIS ALIGNMENT USING CELETTE BENCH	New	1,000.00	500.00
13	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	0.00
14	TO HOIST UP AND CHECK AL LUNDER CARRIAGE FOR POSSIBLE DAMAGED TO ACCIDENT	New	200.00	0.00
15	REMOVE & REFIT FRT WINDSCREEN GLASS	New	240.00	0.00
16	INSTALL FRT WINDSCREEN SOLAR FILM	New	280.00	0.00
17	RENEW REVERSE SENSOR	New	80.00	80.00
18	APPLY ANTI CORROSION ON AFFECTED AREAS	New	240.00	40.00
19	SUPPLY BODY PNL SEALANT	New	120.00	80.00
20	SUPPLY C&C BADGE	New	40.00	40.00
21	RESPARY (FRT) FR BUMPER, BONNET, LHF FENDER, LHF WHEELHOUSE, LHF DOOR, LHF A PILLAR, RHF FENDER, RHF WHEELHOUSE, RHF A PILLAR, RHF DOOR & FR CHASSIS	New	3,850.00	2,450.00
22	RESPRAY (RR) RR BUMPER, RR END PNL, RR FLR PNL, BOOTLID, LHR FENDER, RHR FENDER & RR CHASSIS	New	2,800.00	2,100.00
23	REPAIR WHEEL HOUSING LH / REPLACE LH & RH T/LAMP HOUSING PNL (Supplementary)	New	600.00	600.00
24	SPRAY PAINT WHEEL HOUSING LH, LH & RH T/LAMP HOUSING PANEL (Supplementary)	New	700.00	700.00
25	REMOVE & REFIT DASHBOARD ASSY & AIRCON BLOWER (Supplementary)	New	400.00	400.00
26	REMOVE & REFIT AIR INTAKE MANIFOLD, THROTTLE BODY, WIRE CONTROL AND FRONT WIRE HARNESS (Supplementary)	New	400.00	400.00
Gross Labour Cost (\$\$)			21,340.00	13,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >