

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-

Invoice Name 8 4		621 Ked Mo : WK-0200111-Y
Invoice Name & Address		Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte.	Cust No/Name	LCV11213/ASTON LIN HAOMIN
MOTOR CLAIM DEPARTMENT	Reg No/Reg Date	SMP5790G*ECB1/ 01/10/201
78 SHENTON WAY #09-16	Date In/Mileage	/ 0
ATO BUILDING	Chassis No	Owner Name & Vehicle Info Cust No/Name LCV11213/ASTON LIN HAOMIN Reg No/Reg Date SMP5790G*ECB1/ 01/10/201 Date In/Mileage 0 Chassis No KNAF3416MK5051632 Engine No G4FGKH747997 Make/Model KIA/CERATO 1.6 A EX G333
SINGAPORE 079120	Address Owner Name & Vehicle Info Furance Pte. Cust No/Name LCV11213/ASTON LIN HAOMIN Reg No/Reg Date SMP5790G*ECB1/ 01/10/201 Date In/Mileage 0 Chassis No KNAF3416MK5051632 Engine No G4FGKH747997 Make/Model KIA/CERATO 1.6 A EX G333	
Contact No 64191000	Make/Model	Owner Name & Vehicle Info No/Name
	Colour/Trim	ASS STERY STEVER / WK SATURN BLACK

AX00000 Credit 03/06/2021/ 10.52 PLE 261 / Edito Crico 24100	
34109	
Description of Goods / Services Qty Unit Price Disc	
RENEW (FR) FR BUMPER , FR SUPPORT , BONNET , LHF FENDER , RHF FENDER 5 X 400 & LHF WHEELHOUSE PNL	2000 4000.00
REPAIR LHF A PILLAR , RHF A PILLAR , LHF DOOR , RHF DOOR & FR CHASSIS PNT88000 RENEW (RR) RR BUMPER , RR END PNL , BOOTLID & RR FLR PNL REPAIR LHR, FENDER , RHR, FENDER , RR CHASSIS & BOTH RR WHEELHOUSE PNT88000	2800 4000.00
PNT88000 RENEW AIRCON CONDENSER & RADIATOR	100.00
TOP UP AIRCON GAS A 11900199 REMOVE & REFIT ENGINE & GEARBOX—ASS	80.00 % X 800.00
REMOVE & REFIT ENGINE & GEARBOX ASS	522 IN 150
PNT88000 REMOVE & REFIT BOOTLID COMPONENT	120.00
REMOVE & REFIT FUEL TANK ASSY TO FACILITATE REPAIR (photo)	200.00
RENEW RR EXHUAST MUFFLER ASSY & MOUNTING (photo)	50,000 000
REMOVE & REFIT ALL FLR CARPET, TRIM & SEAT TO FACILITATE REPAIR (photo)	30 50.00
CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM	120.00
10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	La ca
PNT88000 CONDUCT CHASSIS ALIGNMENT USING CELETTE BENCH (photo)	500 1000.00
WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment	1 120.00
TO HOIST UP AND CHECK ALL UNDER CARRIAGE FOR POSSIBLE DAMAGED TO	200.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Page 1 of 6





209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65851240

Co Reg No : 199405410K

FSTIMATE

GST Reg No : MR-8500111-X

co meg no . 133403410K	ESTIMATE	931 Keg No .
Invoice Name & Address		Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Reg No/Reg Date Date In/Mileage Chassis No Engine No Make/Model	LCV11213/ASTON LIN HACMIN SMP5790G*ECB1/ 01/10/201 /

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No			
			BLE	261 / Edwin Ca	ina	34109			
LAX00000	Credit	03/06/2021/ 10:44 Description of Good	4000000		Qty	Unit Price	Disc%	Ar	nount
ACCIDENT		Description of Good	15 / Sel Vice	•		Statistics Statistics			240.00
E PNT88000									240.0
	REFIT F	RT WINDSCREEN GLASS							280.0
M SUNDRY	Tareful Total Total	Language warm							200 120
	FRT WIND	SCREEN SOLAR FILM							80.0
M SUNDRY	RT WINDS	CREEN SEALANT							50.0
M CHNIDDY			00						
SUPPLY F	RT NUMBE	R PLATE WITH CASING	- NK						50.0
M SUNDRY	D NIIMDED	PLATE WITH CAISNG	П		п _				80.0
F PNT88000	K NUMBER	PLATE WITH CALSING	会 结	11000	2750	9			80.0
	VERSE SE	NSOR	2	ime		7			220.0
M SUNDRY		ht-1-1-1	96						
M SUNDRY	REVERSE S	ENSUR - UI					1	40	240.0
APPLY AN	TI CORRO	SION ON AFFECTED ARE	AS					80	120.0
M SUNDRY								0-	
	ODY PNL	SEALANT							40.0
M SUNDRY	&C BADGE							2.0	50.0
M SUNDRY	ac bribac						1	30	30.0
Sundries					12201-01-1120		- 1	21150	3850.0
RESPRAY	(FRT) FR	BUMPER , BONNET , L PILLAR , RHF FENDER	HF ¹ FENDER , RHF WHI	, LHF WHEELHOUSE ELHOUSE , RHF A P	7×3	20		1400	
RHF DOOR	& FR CHA	ASSIS						2100	2800.0
E PNT98000 RESPRAY	(RR) RR	BUMPER , RR END PNL	, RR ¹ FLR I	PNL , BOOTLID ,	6 x 350			4104	200011
LHRI FEND	ER , RHR	FENDER & RK CHASSIS			1.00	633.00	20.00	/	506.4
M COVER-FR M CAP-FRON	ROWNER .	v 10			1.00	9.00	20.00		7.2
	I HOUR	A "I I			1.00	262 00	20.00		209.6

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after mork has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or the course of the course of reserved to the course of reserved. cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.





209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

A STATE OF THE STA		03, 113				
Invoice Name & Address		Owner Name & Vehicle Info				
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Reg No/Reg Date Date In/Mileage Chassis No Engine No Make/Model	LCV11213/ASTON LIN HAOMIN SMP5790G*ECB1/ 01/10/201 /				

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No		
AX00000	Credit	03/06/2021/ 10:44	BLE	261 / Edwin Caina		34109		
	Credit	Description of Goods		201 / 2011	Qty	Unit Price	Disc%	Amount
W 001115 A	2011 5101		7 Services		1.00	328.00	20.00	262.4
M GRILLE A		- 00			1.00	38.00	20.00	30.4
M GARNISH-			OR		1.00	15.00	20.00	12.0
		FOG LAMP, LH	•		1.00	15.00	20.00	12.0
		FOG LAMP, RH X			1.00	303.00	20.00	242.4
M LAMP ASS					1.00	36.00	20.00	28.8
M MOULDING		• •			1.00	36.00	20.00	28.8
		UMPER, RH X 10			1.00	143.00	20.00	114.4
M LAMP ASS	Y-SIDE R	L. L			1.00	143.00		114.4
		LI LINILING.			1.00		20.00	11.2
	-FR BUMP		P	1	1.00		20.00	11.2
	-FR BUMP		~ 12		5.00	114.00		91.2
M STIFFNER	-FR BPR		Paper 1	1100121	1.66	22.00		17.6
M BRACKET-	FR BUMPE		53716	h (Q)	4.60	22.00		17.6
M BRACKET-	FR BUMPE	N OI IN SIDE I			1.00	497.00		397.6
M BEAM CON	IPLETE-FR	BUMPER / 00	BR		1.00	675.00	20.00	540.0
		NT END MODULE	Ø N		1.00	1219.00		975.2
	Y-HEAD,L				1.00	1219.00		975.2
	Y-HEAD, R	_			1.00	1502.00		1201.6
	SY-HOOD				1.00	43.00		34.4
	SY-HOOD,	- 07			1.00		20.00	34.4
	SY-HOOD,	00			1.00	430.00		344.0
	NDER, LH	7 00			1.00	430.00		344.0
M PANEL-FE		, /01			1.00	156.00		124.8
	INSULAT	1110	1		13.00		20.00	10.4
		TING PAD MIG			1.00	103.00		82.4
M LATCH AS					1.00		20.00	76.0
					1.00		20.00	76.0
		- 1919 (1977)			1.00		20.00	25.
	-KIA NO.				1.00	821.00		656.
	NDSHIELD				1.00		20.00	44.8
		20			1.00	247.00		197.0
	SY-COWL				1.00		20.00	8.8
M COVER-AF	TER SERI	VCE,LH (X1)			-,,,,			

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Page 3 of 6





209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

	LOTIMATE	631 Keg 110 1 1111 1	
Invoice Name & Address	Owner Name & Vehicle Info		
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Reg No/Reg Date Date In/Mileage Chassis No Engine No Make/Model	LCV11213/ASTON LIN HAOMIN SMP5790G*ECB1/ 01/10/201 / 0 KNAF3416MK5051632 G4FGKH747997 KIA/CERATO 1.6 A EX G333 4SS SILKY SILVER / WK SATURN BLACK	

Account No	T	Date/Time Printed	CSE	Operator		WIP No		
	Terms		BLE	261 / Edwin Caina		34109		
LAX00000	Credit	03/06/2021/ 10:44	THE RESERVE		Qty	Unit Price	Disc%	Amount
		Description of Good	s / Service	3	1.00	11.00	20.00	8.8
M COVER-AF	TER SERI	VCE,RH ? XAA	A		1.00	559.00		447.2
M MIRROR A	SSY-OUTS	IDE RR VIEW, RH X	-		1.00	146.00	20.00	116.8
M RESERVOI	R & PUMP	ASSY-WASHER X 11	()		1.00	117.00		93.6
M PANEL AS	SY-UNDER	COVER 2 X MI			1.00	28.00		22.4
M GUARD-AI		/ WK			1.00	28.00	20.00	22.4
M GUARD-AI		1 / BR			1.00	687.00	20.00 /	549.6
	R ASSY-C	COOLER / 00			1.00	646.00		516.8
M RADIATOR		^^			1.00	40.00	20.00	32.0
M HOSE ASS	SY-RADAAT	COD LUID 1 X III	V.		1.00	27.00		21.6
M HOSE AS	TATOR TO	RESERVOIR A X			-1.00	24 00	20.00	19.2
M HOSE-RAI	Y-RADIATO	OR X ///	П		74.00	28.00	20.00	22.4
M CAP ASS	MECK ASSI	-RADIATOR OR (255	ima	7 5.80	7 00	20.00	5.6
	nce V	00	511		11:00	31.00	20.00	24.8
M CLAMP-H	DIATOR IN		J (C		4.00	27.00	20.00	21.0
M HOSE-RA	SY-RADIA	TOR UPR 7 X CT			1.00	656.00	20.00	524.8
	VCCA ~					5.00		4.0
	TENSTON	1 / 00			1.00	9.00		7.7
M DUCT-EX	AIR INTA	CE 1 / BR			1.00	55.00		44.0
M SHIELD-	CV ATD	i / BR			1.00	174.00		139.
M DUCT AS	VCCA VII	a np			1.00	83.00	20.00	66.
M CLEANER	ASSY-AI	TAVE / UK			1.00	115.00		92.
M HOSE AS	SY-AIR II	SION 1 X NA			1.00	212.00		169.
M DUCT AS	SY-EXTENS	" CNT			1.00	906.00		724.
M COVER A	SSY-ENGI	0 / 1/4			1.00	74.00		59.
M MANIFOL	D ASSY-II	TOU 1 X nn			1.00	26.00		20.
M HORN AS	SY-LOW P	11011 - 1 1/00			1.00	675.00	20.00	540.
M UPR COV	ER-ENG RO	COMP OUTSIDE LH X	Λη		1.00	675.00		540.
M LAMP AS	SY-REAR	OND COLDIDE PLI	Cut		1.00	6/5.00	20.00	486.
M LAMP AS	SY-REAR (COMB OUTSIDE, RH	11		1.00			/ 486.
M LAMP AS	SY-REAR (CONTO THOTOL, L.	CUT		1.00	608.00	50 459756	552.
M LAMP AS	SY-REAR (COMB INSIDE THE	nn		1.00	690.00	(a) 10.103 [UNISSE] 10.0	/ 1037.
M LAMP AS	SY-CENTER	CAKINISH 'AN	7		1.00	1297.00	20.00	77.
M PANEL A	SSY-TRUN	1 1	11		1.00	97.00	20.00	
M HINGE A	SSY-TRUN	(LID, LH ', X	1					

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered and recorded for mention or replacement. However, should this occur, we would advise you. Please be informed that a any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.





209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd.	Cust No/Name Reg No/Reg Date	LCV11213/ASTON LIN HAOMIN SMP5790G*ECB1/ 01/10/201
MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16	Date In/Mileage	
AIG BUILDING	Engine No	G4FGKH747997
SINGAPORE 079120 Contact No 64191000	Make/Model	KIA/CERATO 1.6 A EX G333
NO 01131000		4SS SILKY SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No		
-AX00000	Credit	03/06/2021/ 10:44	BLE	261 / Edwin (Caina	34109	972	
LAKOOOOO	Credit	Description of Good			Qty	Unit Price		Amount
			us / Services		1.00	97.00	20.00	77.60
M HINGE AS					1.00	324.00	20.00	259.20
M PANEL AS					1.00	100.00	20.00	80.00
M W/STRIP-					1.00	112.00	20.00	89.60
M LATCH AS		-10 0 10			1.00	40.00	20.00	32.00
M STRIKER		NK LIU A PUT			1.00		20.00	32.80
M TRIM ASS		NOVERSE .	٨		1.00	211.00		168.80
		COVERTING	5.4		1.00	28.00		22.40
M EMBLEM-C		- MC			1.00	32.00	20.00	25.60
	Y-KIA SU	B / PC			1.00	651.00	20.00	520.80
M COVER-RE		- BR			-1.00	241.00	20.00	192.80
M COVER-RE	BUMPER	LWR / OR THE	$ \Gamma$			33.00	20.00	26.40
M COVER-RE	BUMPER	UNDER, LH ?	1770	110019	217562	19.00	20.00	15.20
M COVER-RE	BUMPER	FOG LAMP, LH	2011	111 11 11 (011:50		20.00	15.2
M COVER-RE	BUMPER	FOG LAMP, RH			1.00	181.00		144.8
M LAMP ASS	Y-SIDE T	/SIGNAL, LH / CMI			1.00	181.00		144.8
M LAMP ASS	Y-SIDE T	/SIGNAL, RH - (")			1.00	207.00		165.60
M EXTN WIF	RING ASSY	-BWS ! / UK			1.00	318.00		254.4
M BEAM-RR	BUMPER	- GR - OT			1.00	65.00		52.0
M STAY-RR	BUMPER L	H					20.00	52.0
	BUMPER R		00		1.00	00.00	20.00	7.2
M BRACKET-	RR BEAM	UPR MTG, LH	7 v		1.00		20.00	7.2
M BRACKET	RR BEAM	HIPR MILL KH			1.00		20.00	4.8
M BRACKET	RR BEAM	I WR CTR ! / U	R		1.00		20.00	4.8
	RR BEAM	LWR MTG	K		1.00	46.00		36.8
M ANTENNA	ASSY-SMA	RTKEY 7 X 11			1.00		20.00	26.4
	BUMPER		Xnn		1.00			20.0
M BRACKET	ASSY-RR	BPR SIDE UPR,L 1	XNO		1.00		20.00	24.8
M BRACKET	ASSY RR	BPR SIDE UPR,R	~1		1.00		20.00	175.2
M PANEL AS	SY-REAR	FLOOR, RR / 00	• •		1.00	219.00	20.00	
M REINF-RE	SPARE T	THE WELL CROSS ?	1 nec		1.00	41.00	20.00	32.8
M MUFFLER	ASSY-REA	R 1 XM			1.00	757.00	20.00	605.6
	R-HEAT R	1			1.00		20.00	108.8
M GASKET-E		A			2.00	14.00	20.00	22.4

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Page 5 of 6





209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

		usi keg				
Invoice Name & Address		Owner Name & Vehicle Info				
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Reg No/Reg Date Date In/Mileage Chassis No Engine No Make/Model	LCV11213/ASTON LIN HAOMIN SMP5790G*ECB1/ 01/10/201 / 0 KNAF3416MK5051632 G4FGKH747997 KIA/CERATO 1.6 A EX G333 4SS SILKY SILVER / WK SATURN BLACK				

				Colour/Trim 45	2 21 LKT	JILYLK /	AIX CC.	
Account No	Tarma	Date/Time Printed	CSE	Operator		WIP No		
LAXOOOO	Terms		BLE	261 / Edwin Caina		34109		
LAXOUUUU	Credit	Description of Goods			Qty	Unit Price		Amount
N. M. E. E.	CONDI ETE				1.00	907.00		725.60
M MUFFLER					1.00	15.00	20.00	12.00 12.80
M BRACKET	A551-5PA	RE TIRE MTG X	70		1.00	16.00	20.00	11.20
- 회사의	LING POO	v " Y///			1.00	14.00	20.00	8.80
M REINF-TO	V_DD SFA	T & MER MTG, LH . X	\cap \cap		1.00	11.00	20.00	11.20
M REINF-RR	FLR SD	MBR CTR, LH 1 X	00		1.00	14.00	20.00	11.12
			S SI	URVEYOR NAME: Sterength of the state of the	n CLKI	() 3/6/2 1 AC	-	
Confirm & a	painer OI in urvey before/ play damager accepted I	e following: ester spray painting e read(s) during resurvey by n a "Wilnost Projudice" basis ion(s) is allowed in(s) must be resurveyed and ion(s) and them input thee Company			7% GST or		ett .40	39,284.· 2749.·
is \$24	ojest to final a oledged by Re	110			8	Total Payal	ole	42,034.

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered any additional parts or labour which may be required after repairs or replacement. However, should this occur, we would advise you. Please be informed that a after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a discovered are excluding above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a discovered that a started and needed for repairs or repair work has commenced. Occasionally worn or damaged parts are discovered to the started and needed for repairs or repair work has commenced. Occasionally worn or damaged parts are discovered to the started and needed for repairs or repair work has commenced. Occasionally worn or damaged parts are discovered to the started and needed for repa