

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKD 2211T

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			,
1	FRONT LH FENDER	TO REPAIR SEE LABOUR	1,752.30	-
1	FRONT LH SIDE MIRROR ASSY	SERVICEABLE	1,523.80	-
1	LH DOOR ASSY	TO REPAIR SEE LABOUR	3,052.40	-
1	FRONT LH SHOCK ABSORBER	SERVICEABLE	2,352.40	-
1	FRONT LH LOWER ARM	SERVICEABLE	1,425.60	-
1	FRONT LH TRUST ARM	SERVICEABLE	1,189.70	-
1	FRONT LH KNUCKLE ARM	SERVICEABLE	2,576.20	-
1	FRONT LH WHEEL HUB & BEARING	BENT / NOISY	578.00	578.00
1	STEERING RACK & PINION LH TIE ROD	SERVICEABLE	352.40	-
	LESS 10% DISCOUNT		-1,480.28	-57.80
	a a		13,322.52	520.20
	SPECIAL NETT ITEMS		2	
1	SET FRONT BUMPER LOWER CARBON FIBER SKIRTING SET (C/W 1SET) (SN)	SERVICEABLE	1,500.00	-
2	SPORTS RIM (FRONT LH / REAR LH) (SN)	TO REPAIR SEE LABOUR	6,000.00	-
			7,500.00	-
	LABOUR			
	TO REMOVE, JACK OUT, STRAIGHTEN, PANEL BEATING, ALIGN AND RENEW REPLACED PARTS. INCLUSIVE OF THE REPAIR OF FRONT LH FENDER, LH DOOR ASSY AND SPORTS RIM (FRONT LH / REAR LH).		1,200.00	500.00
	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREAS.		1,200.00	800.00
	TO CHECK WIRINGS AND LIGHTINGS.		50.00	30.00
	TO REMOVE, REFIX LH DOOR FITTINGS.	NOT NECESSARY	120.00	-
	TO REMOVE, REFIX FRONT LH UNDER CARRIAGES.		260.00	80.00
	TO CONDUCT COMPUTERISE WHEEL ALIGNMENT TEST.		80.00	60.00
	TO SUPPLIED AND APPLIED PAINT PROTECTION COATING.	NOT NECESSARY	800.00	

Report Ref No. CS1/LAW21006368/Guf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO SUPPLIED AND APPLIED ANTI RUST TREATMENTS.		100.00	60.00
			3,810.00	1,530.00
	GRAND TOTAL		24,632.52	2,050.20

RECOMMENDED COST OF LUMP SUM REPAIRS	1,650.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS1/LAW21006368/Guf3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.