

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21006371/AVCN2**Date:** 07/09/2021**REFERENCE**

Insured/Claimant:	J JEYASEELAN	Policy No:	2070179492	
Date of Loss:	26/05/2021	Nature of Claim:	OD	Claim No: 6407365570SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX2259C		
Make & Model:	AUDI A5, 2.0 SPORTBACK (A)	Engine No:	DEM028588
Reg. Date:	31/12/2020 (Man. Year: 2020)	Chassis No:	WAUZZZF56MA018259
Colour:	Black	Odometer:	8820 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$175,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	255/55R19	Rear Tyre Size:	255/55R19
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,592.00	4,689.52	3,902.48	45.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,872.00	1,722.00	1,150.00	40.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,464.00	6,411.52	5,052.48	44.07
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	10,664.00	5,611.52	5,052.48	47.38
+ GST 7.00/7.00% (S\$)	746.48	392.81	353.67	47.38
Nett Amount (S\$)	11,410.48	6,004.33	5,406.15	47.38

INSPECTION

Date of Assignment:	03/06/2021		
Date Inspected:	02/06/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	2,342.00 FS	*1,873.60 FS
2	1		*FRONT BUMPER GRILLE CENTER	Not Necessary	196.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	Cracked	262.00 FS	*209.20 FS
4	2		*FRONT BUMPER AIR GUIDE GRILLE LH/RH	Not Necessary	270.00 FS	*- FS
5	2		*FRONT BUMPER TRIM LH/RH	Not Necessary	96.00 FS	*- FS
6	1		*FRONT BUMPER TRIM-CENTER	Not Necessary	114.00 FS	*- FS
7	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	262.00 FS	*- FS
8	1		*FOAM FILLER PIECE	Cracked	146.00 FS	*116.40 FS
9	1		*FRONT BUMPER REINFORCEMENT BEAM	Dented	845.00 FS	*675.60 FS
10	1		*FRONT BUMPER TOP COVER	Torn	127.00 FS	*101.60 FS
11	1		*CAUTION STICKER	Necessary	14.00 FS	*10.88 FS
12	1		*AIR COND STICKER	Necessary	8.00 FS	*5.68 FS
13	1		*FRONTAL LOCK CARRIER BRACKET	Cracked	137.00 FS	*109.60 FS
14	2		*LOCK CARRIER SUPPORT LH/RH	Not Necessary	58.00 FS	*- FS
15	1		*RADIATOR GRILLE	Cracked	1,694.00 FS	*1,355.20 FS
16	1		*FRONT CAMERA COVER	Necessary	166.00 FS	*132.80 FS
17	1		*FRONT CAMERA BRACKET	Not Necessary	17.00 FS	*- FS
18	1		*FRONT CAMERA	Not Necessary	1,141.00 FS	*- FS
19	1		*FRONT CAMERA ADAPTER	Not Necessary	198.00 FS	*- FS
20	2		*FRONT PARKING AID SENSOR (Npa)	Not Necessary	0.00 FS	*- FS
21	1		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	14.00 FS	*- FS
22	2		*RADIATOR AIR GUIDE LH/RH	Not Necessary	64.00 FS	*- FS
23	2		*RADIATOR AIR GUIDE LH/RH	Not Necessary	32.00 FS	*- FS
24	2		*RADIATOR AIR GUIDE UPPER/LOWER	Not Necessary	32.00 FS	*- FS
25	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
26	1		*SUNDRIES	Necessary	250.00 FS	*2.56 FS
27	1		*OUTER TEMP,SENSOR BRACKET (Supplementary)	Necessary	19.00 FS	*14.56 FS
28	1		*BONNET IMPACT PROTECTION-CENTRE (Supplementary)	Cracked	28.00 FS	*21.84 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	8,592.00	4,689.52
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
3	TO RESPRAY FRONT BUMPER	New	1,000.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			2,872.00	1,722.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >