

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21006376/DTCN2**Date:** 19/10/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00046282104

Claimant Vehicle No : SMK5982X **Insured Vehicle No :** SLD9094G

Date of Loss: 01/06/2021 Nature of Claim: TP Claim No: SNM21D203139/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMK5982X**

Make & Model: HYUNDAI AVANTE, 1.6 (A) Engine No: G4FGKU124037

Reg. Date: 17/04/2019 (Man. Year: 2019) Chassis No: KMHD841CMKU891188

Colour: Grey Odometer: 34496 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15

Front Left Side: Nexen 5 mm Rear Left Side: Nexen 5 mm

Front Right Side: Nexen 5 mm Rear Right Side: Nexen 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	30,761.28	3,318.20	27,443.08	89.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,120.00	1,270.00	7,850.00	86.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	39,881.28	4,588.20	35,293.08	88.50
Approved Total (Overridden) (\$\$)		3,600.00		
(\$\$)	39,881.28	3,600.00	36,281.28	90.97
+ GST 7.00/7.00% (\$\$)	2,791.69	252.00	2,539.69	90.97
Nett Amount (\$\$)	42,672.97	3,852.00	38,820.97	90.97

INSPECTION

Date of Assignment: 03/06/2021

Date Inspected: 03/06/2021 Inspected At: JWG International Pte Ltd (HQ)
Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK
AutoPoint
Singapore 568047

Estimated Period of Repair: 3.0 days

Adjuster: BRYAN TANI**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Oct 2021)
Parts:	143	HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMK5982X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Necessary	2,498.00 FL	*- FL
2	2		*BONNET HINGE LH/RH	Not Necessary	278.00 FL	*- FL
3	1		*BONNET LOCK	Not Necessary	375.00 FL	*- FL
4	1		*BONNET SEAL	Not Necessary	110.00 FL	*- FL
5	2		*HEAD LAMP LH/RH	Os Mounting Broken/Ns Cracked	7,360.00 FL	*2,397.60 FL
6	2		*HEAD LAMP LOWER BRACKET LH/RH	Not Necessary	580.00 FL	*- FL
7	2		*HEAD LAMP ECU LH/RH	Not Necessary	2,916.00 FL	*- FL
8	1		*FRONT GRILLE	Distorted/Deformed	790.00 FL	*460.20 FL
9	1		*FRONT GRILLE BASE	Not Necessary	618.00 FL	*- FL
10	1		*FRONT GRILLE LOGO	Not Necessary	89.00 FL	*- FL
11	1		*FRONT BUMPER	Repair	1,091.00 FL	*- FL
12	2		*FRONT BUMPER SIDE RETAINER LH/RH	Not Necessary	170.00 FL	*- FL
13	1		*FRONT BUMPER LOWER LID	Not Necessary	692.00 FL	*- FL
14	2		*FRONT BUMPER SIGNAL LAMP LH/RH	Not Necessary	820.00 FL	*- FL
15	2		*FRONT BUMPER SIGNAL LAMP HOLDER LH/RH	Not Necessary	570.00 FL	*- FL
16	1		*FRONT BUMPER SPONGE	Not Necessary	338.00 FL	*- FL
17	1		*FRONT REINFORCEMENT BAR	Not Necessary	980.00 FL	*- FL
18	1		*FRONT SUPPORT PANEL	Repair	1,890.00 FL	*- FL
19	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	342.00 FL	*- FL
20	1		*BOOTLID	Not Necessary	1,982.40 FL	*- FL
21	1		*BOOTLID HYUNDAI LOGO	Not Necessary	196.20 FL	*- FL
22	1		*BOOTLID AVANTE EMBLEM	Not Necessary	61.20 FL	*- FL
23	1		*BOOTLID REVERSE CAMERA	Not Necessary	926.10 FL	*- FL
24	1		*BOOTLID LOCK	Not Necessary	216.20 FL	*- FL
25	1		*BOOTLID INNER TRIM	Not Necessary	246.80 FL	*- FL
26	2		*BOOTLID LAMP L+R	Not Necessary	969.80 FL	*- FL
27	1		*BOOTLID WEATHER STRIP	Not Necessary	292.50 FL	*- FL
28	1		*REAR BUMPER	Mounting Broken	659.40 FL	*498.20 FL
29	1		*REAR BUMPER BRACKET	Not Necessary	178.60 FL	*- FL
30	2		*REAR BUMPER SIDE RETAINER L+R	Not Necessary	118.80 FL	*- FL
31	1		*REAR BUMPER CENTER GARNISH	Distorted/Cut	553.50 FL	*211.00 FL
32	2		*REAR BUMPER CENTER GARNISH REFLECTOR L+R	Not Necessary	603.00 FL	*- FL
33	2		*REAR BUMPER CENTER GARNISH LAMP L+R	Not Necessary	1,599.60 FL	*- FL
34	2		*REAR BUMPER NO PLATE LAMP L+R	Not Necessary	236.40 FL	*- FL
35	2		*TAIL LAMP L+R	Not Necessary	1,270.20 FL	*- FL
36	2		*TAIL LAMP LOWER BRACKET L+R	Not Necessary	586.20 FL	*- FL
37	1		*REAR REINFORCEMENT BAR	Cracked	694.80 FL	*341.50 FL
38	1		*REAR KEYLESS SENSOR	Not Necessary	244.50 FL	*- FL
39	1		*REAR END PANEL	Not Necessary	754.60 FL	*- FL
40	1		*REAR END PANEL TOP GARNISH	Not Necessary	259.80 FL	*- FL
41	1		*SPARE WHEEL PANEL	Not Necessary	1,491.00 FL	*- FL
42	1		*SPARE WHEEL PANEL TOP BOARD	Not Necessary	394.00 FL	*- FL
43	1		*SPARE WHEEL PANEL TOOL BOX	Not Necessary	351.00 FL	*- FL

Report was unsubmitted during this print-out.

10/19/21, 3:18 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*FRONT NUMBER PLATE GARNISH	Cracked	158.00 FL	*158.00 FL
45	1		*BONNET INSULATOR CLIPS	Not Necessary	50.00 FS	*- FS
46	1		*FRONT GRILLE CLIPS	Necessary	50.00 FS	*20.00 FS
47	1		*FRONT BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
48	1		*FRONT BUMPER LOWER LID CLIPS	Not Necessary	50.00 FS	*- FS
49	1		*SET REAR REVERSE SENSOR	Not Necessary	300.00 FS	*- FS
50	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
51	1		*FRONT NUMBER PLATE	Bent	40.00 FS	*25.00 FS
52	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
53	1		*REAR BOOTLID INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$\$)	38,271.60 4,131.50
					- List Item Discount on L Items 20.00/20.00% (\$\$)	7,510.32 813.30
					Total Parts (\$\$)	30,761.28 3,318.20
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILIATE REPAIRS	New	300.00	0.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS (FRONT)	New	1,600.00	500.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS (FRONT)	New	1,600.00	200.00
4	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS (REAR)	New	1,800.00	300.00
5	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS (REAR)	New	1,800.00	200.00
6	TO TUFF COAT DAMAGED AREAS	New	200.00	0.00
7	TO RNR REVERSE CAMERA	New	100.00	0.00
8	TO RNR A/C CONDENSOR & REFILL GAS TO FACILITATE REPAIRS	New	200.00	0.00
9	TO RNR RADIATOR & REFILL COOLANT TO FACILITATE REPAIRS	New	200.00	0.00
10	TO RNR REAR WINDSCREEN TO ASSIST WORK LOAD	New	250.00	0.00
11	TO RNR REAR BOOT MECHANISM TO ASSIST WORK LOAD	New	200.00	0.00
12	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	New	250.00	0.00
13	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
14	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS.RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
15	TO RNR REVERSE SENSOR TO ASSIST WORK LOAD	New	120.00	40.00
Gross Labour Cost (\$\$)			9,120.00	1,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >