

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way #07-16  
Singapore 079120

**Our File No:** CS4/AIG21006377/NVF3E2

**Date:** 16/08/2021

### REFERENCE

Insured/Claimant: ALANTAC INDUSTRIAL SERVICES PTE LTD Policy No: 2070150600  
Date of Loss: 25/05/2021 Nature of Claim: OD Claim No: 1245554867SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **YP4939K**  
Make & Model: MITSUBISHI CANTER, 3.0 D (M) Engine No: 4P10C27076  
Reg. Date: 29/11/2016 (Man. Year: 2016) Chassis No: FEB21EA20782  
Colour: White Odometer: 0 km  
Engine Capacity: 2998 cc  
Market Value/New Car Price: S\$58,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/85R15 Rear Tyre Size: 195/85R15  
Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 5 mm  
Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,455.00	4,455.00	0.00	0.00
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	292.80	250.00	42.80	14.62
Paintwork Labour	165.56	165.56	0.00	0.00
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>4,924.36</b>	<b>4,881.56</b>	<b>42.80</b>	<b>0.87</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>344.71</b>	<b>341.71</b>	<b>3.00</b>	<b>0.87</b>
<b>Nett Amount (S\$)</b>	<b>5,269.07</b>	<b>5,223.27</b>	<b>45.80</b>	<b>0.87</b>

### INSPECTION

Date of Assignment: 03/06/2021 Present Location: Progressive Car Care Pte Ltd (HQ)  
Date Inspected: 07/06/2021 Inspected At: Progressive Car Care Pte Ltd (HQ)  
Estimated Period of Repair: 4.0 days Blk 3022A Ubi Road 1, #01-45/46  
Singapore 408716

**Adjuster:** Muhammad Nazril Bin Abdullah

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*FILTER TUBE (WCP)	Burnt	420.00 F	*420.00 F
2	1	NA	*FRT TANK STRAP (WCP)	Burnt	300.00 F	*300.00 F
3	1	NA	*FUEL PUMP HARNESS (WCP)	Burnt	280.00 F	*280.00 F
4	1	NA	*FUEL TANK (WCP)	Burnt	1,900.00 F	*1,900.00 F
5	1	NA	*FUEL TUBE 1 (WCP)	Burnt	450.00 F	*450.00 F
6	1	NA	*FUEL TUBE 2 (WCP)	Burnt	400.00 F	*400.00 F
7	1	NA	*REAR TANK STRAP (WCP)	Burnt	300.00 F	*300.00 F

F=Franchise part.

Sub Total (S\$)	4,050.00	4,050.00
+ Margin on L,N Items 10.00/10.00% (S\$)	405.00	405.00
Total Parts (S\$)	4,455.00	4,455.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Total Paint Labour	New	124.80	124.80
2	Total Paint Materials	New	40.76	40.76
<u>Labour Items</u>				
3	Total Panel/Mechanical Labour	New	292.80	250.00
Gross Labour Cost (\$\$)			458.36	415.56

Report was unsubmitted during this print-out.

< END OF ESTIMATES >