

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd  
64 Cecil Street, #04-00 IOB Building  
Singapore 049711

**Our File No:** CS/GRB21006378/R1QF3E2

**Date:** 23/06/2021

### REFERENCE

Insured/Claimant:	-	Policy No:	D21MFL0000447		
Date of Loss:	02/06/2021	Nature of Claim:	OD	Claim No:	N/A

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM6425X	Engine No:	HIDDEN
Make & Model:	HYUNDAI KONA, 998cc (A)	Chassis No:	KMHK281GUKU030423
Reg. Date:	08/07/2019 (Man. Year: 2019)	Odometer:	0 km
Colour:	Grey		
Engine Capacity:	0 cc		
Market Value/New Car Price:	S\$113,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/55 ZR17	Rear Tyre Size:	215/55 ZR17
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	32,044.48	8,222.56	23,821.92	74.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,360.00	2,930.00	3,430.00	53.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>38,404.48</b>	<b>11,152.56</b>	<b>27,251.92</b>	<b>70.96</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>2,688.31</b>	<b>780.68</b>	<b>1,907.63</b>	<b>70.96</b>
<b>Nett Amount (S\$)</b>	<b>41,092.79</b>	<b>11,933.24</b>	<b>29,159.55</b>	<b>70.96</b>

### INSPECTION

Date of Assignment:	03/06/2021	
Date Inspected:	04/06/2021 Inspected At:	Pegasus Engineering & Trading Pte Ltd (Kian Teck) 74 Kian Teck Road Singapore 628800
Estimated Period of Repair:	10.0 days	

**Adjuster:** MOHD RASUL

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$22,831.45 NETT)

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 23 Jun 2021)
<b>Parts:</b>	144	HYUNDAI KONA 998cc (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMM6425X)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*MODULE ASSY-AIR BAG CONTROL</b> (WCP)	Activated	276.27 F	*276.27 F
2	1		<b>*AIR GUARD</b> (WCP)	Cracked	24.90 F	*24.90 F
3	1		<b>*BUZZER ASSY-PIEZO</b> (WCP)	Cracked	31.43 F	*31.43 F
4	1		<b>*WIRING ASSY-COMBO CHARGER</b> (WCP)	Cracked	569.61 F	*569.61 F
5	1		<b>*BLOWER ASSY</b> (WCP)	* Check	253.38 F	*- F
6	1		<b>*BONNET</b> (WCP)	Bent	488.09 F	*488.09 F
7	1		<b>*BONNET LOCK</b> (WCP)	Bent	36.11 F	*36.11 F
8	1		<b>*MODULE-CHARGE DOOR</b> (WCP)	Scratched	435.84 F	*435.84 F
9	1		<b>*AIR CON CONDENSER</b> (WCP)	Bent	332.66 F	*332.66 F
10	1		<b>*EPCU ASSY</b> (WCP)	* Check	4,590.74 F	*- F
11	1		<b>*COVER ASSY-COWL TOP</b> (WCP)	Cracked	51.86 F	*51.86 F
12	1		<b>*FRONT BUMPER CTR MOULDING</b> (WCP)	Scratched	51.00 F	*51.00 F
13	1		<b>*PANEL ASSY-C/PAD UPR PASS SIDE</b> (WCP)	* Check	145.01 F	*- F
14	1		<b>*MODULE ASSY-STRG WHEEL AIR BAG</b> (WCP)	Activated	607.13 F	*607.13 F
15	1		<b>*BRACKET-MOTOR MTG SUPPORT</b> (WCP)	* Check	132.77 F	*- F
16	1		<b>*TANK ASSY-RESERVOIR</b> (WCP)	Deformed	37.73 F	*37.73 F
17	1		<b>*FRONT BUMPER LOWER COVER</b> (WCP)	Serviceable	155.19 F	*- F
18	1		<b>*BRACKET-LOGO MTG</b> (WCP)	Cracked	8.48 F	*8.48 F
19	1		<b>*FRONT BUMPER</b> (WCP)	Torn	176.66 F	*176.66 F
20	1		<b>*TRACTION MOTOR ASSY</b> (WCP)	* Check	8,406.48 F	*- F
21	1		<b>*CARRIER ASSY-FRONT END MODULE</b> (WCP)	Cracked	187.83 F	*187.83 F
22	1		<b>*CROSSMEMBER COMPL</b> (WCP)	* Check	291.59 F	*- F
23	1		<b>*BEAM COMPLETE-FRONT BUMPER</b> (WCP)	Bent	302.24 F	*302.24 F
24	1		<b>*CAP-TOWING HOOK</b> (WCP)	Scratched	1.07 F	*1.07 F
25	1		<b>*WIRING HARNESS-FRONT BUMPER</b> (WCP)	Serviceable	79.68 F	*- F
26	1		<b>*BRACKET-REINF</b> (WCP)	* Check	12.69 F	*- F
27	1		<b>*ABSORBER-FRONT BUMPER ENERGY</b> (WCP)	Cracked	12.47 F	*12.47 F

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		<b>*MOULDING-FRT UPR LICENSE PLATE</b> (WCP)	Cracked	7.22 F	*7.22 F
29	1		<b>*GEAR DRIVE UNIT ASSY</b> (WCP)	* Check	1,673.87 F	*- F
30	1		<b>*EMBLEM-SYMBOL MARK</b> (WCP)	Necessary	6.86 F	*6.86 F
31	1		<b>*CRASH PAD ASSY-MAIN</b> (WCP)	* Check	387.92 F	*- F
32	1		<b>*HINGE ASSY-HOOD (LHS)</b> (WCP)	Serviceable	10.91 F	*- F
33	1		<b>*PIECE-FRT BUMPER GUARD LWR (LHS)</b> (WCP)	Necessary	15.06 F	*15.06 F
34	1		<b>*SHAFT ASSY-DRIVE (LHS)</b> (WCP)	* Check	319.52 F	*- F
35	1		<b>*BRACKET ASSY-FRT BUMPER SD UPR</b> (WCP)	* Check	4.26 F	*- F
36	1		<b>*S/BELT ASSY-FR (LHS)</b> (WCP)	Activated	328.16 F	*328.16 F
37	1		<b>*SENSOR ASSY-A TYRE CRASH</b> (WCP)	* Check	26.60 F	*- F
38	1		<b>*S/BELT ASSY-RR (LHS)</b> (WCP)	Activated	237.90 F	*237.90 F
39	1		<b>*LAMP ASSY-HEAD (LHS)</b> (WCP)	Broken	247.25 F	*247.25 F
40	1		<b>*PANEL ASSY-UNDER COVER FRONT</b> (WCP)	* Check	37.53 F	*- F
41	1		<b>*AIR BAG ASSY-PASSENGER</b> (WCP)	Activated	686.19 F	*686.19 F
42	1		<b>*HINGE ASSY-HOOD (RHS)</b> (WCP)	Bent	10.91 F	*10.91 F
43	1		<b>*SHAFT ASSY-DRIVE (RHS)</b> (WCP)	* Check	319.52 F	*- F
44	1		<b>*BRACKET ASSY-FRT BUMPER SD UPR</b> (WCP)	Necessary	4.26 F	*4.26 F
45	1		<b>*S/BELT ASSY-FRT (RHS)</b> (WCP)	Activated	328.16 F	*328.16 F
46	1		<b>*SENSOR ASSY-A TYPE CRASH</b> (WCP)	* Check	26.60 F	*- F
47	1		<b>*MEMBER ASSY-FRONT SIDE (RHS)</b> (WCP)	Serviceable	256.76 F	*- F
48	1		<b>*BRACKET ASSY-CARRIER MTG (RHS)</b> (WCP)	Serviceable	6.98 F	*- F
49	1		<b>*LAMP ASSY-DAY RUNNING LIGHT (RHS)</b> (WCP)	Cracked	193.44 F	*193.44 F
50	1		<b>*S/BELT ASSY-RR (RHS)</b> (WCP)	Activated	237.63 F	*237.63 F
51	1		<b>*RADIATOR ASSY</b> (WCP)	Bent	262.95 F	*262.95 F
52	1		<b>*LAMP ASSY-HEAD (RHS)</b> (WCP)	* Check	247.25 F	*- F
53	1		<b>*STOPPER-RR WINDOW GLASS</b> (WCP)	Serviceable	1.56 F	*- F
54	1		<b>*CONTACT ASSY-CLOCK SPRING</b> (WCP)	* Check	58.58 F	*- F
55	1		<b>*COVER ASSY-RADIATOR GRILLE UPR</b> (WCP)	Cracked	16.70 F	*16.70 F
56	1		<b>*RESERVOIR ASSY-W/SHLD WASHER</b> (WCP)	Not Necessary	24.84 F	*- F
57	1		<b>*GLASS-WINDSHIELD</b> (WCP)	Cracked	568.38 F	*568.38 F
58	1		<b>*MOULDING-WINDSHIELD GLASS</b> (WCP)	Necessary	14.42 F	*14.42 F
59	1		<b>*BRACKET-MOTOR MTG SUPPORT</b> (WCP)	* Check	132.77 F	*- F
60	1		<b>*BRACKET ASSY-RR MTG</b> (WCP)	* Check	48.35 F	*- F
61	1		<b>*BRACKEY ASSY-DECELERATOR MTG</b> (WCP)	* Check	54.12 F	*- F
62	1		<b>*BRACKET ASSY-CARRIER MTG (RHS)</b> (WCP)	Serviceable	6.98 F	*- F
63	1		<b>*BUSHING-CROSSMEMBER MTG</b> (WCP)	* Check	18.54 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
64	1		<b>*BUSHING-CROSSMEMBER MTG</b> (WCP)	* Check	14.16 F	*- F
65	1		<b>*BUSHING-CROSSMEMBER MTG</b> (WCP)	* Check	14.16 F	*- F
66	1		<b>*BRACKET ASSY-CARRIER MTG (RHS)</b> (WCP)	Serviceable	6.98 F	*- F
67	1		<b>*FLAP &amp; DUCT ASSY</b> (WCP)	Cracked	420.00 F	*420.00 F
68	1		<b>*PIPE-SUCTION &amp; LIQUID (SHORT)</b> (WCP)	* Check	225.00 F	*- F
69	1		<b>*CABLE-L.D.C POS</b> (WCP)	* Check	938.00 F	*- F
70	1		<b>*CABLE-L.D.C NEG</b> (WCP)	* Check	71.00 F	*- F
71	1		<b>*BUMPER LOWER STIFFNER-FRT</b> (WCP)	Bent	120.00 F	*120.00 F
72	1		<b>*FENDER-FRT LH</b> (WCP)	Repair	598.00 F	*- F
73	1		<b>*FENDER-FRT RH</b> (WCP)	Repar	598.00 F	*- F
74	1		<b>*FRT CHASSIS (WATING FOR THE PIECE)</b> (NPA)	* Check	0.00 F	*- F
75	1		<b>*FRT LH WHEEL HOUSE PANEL</b> (NPA)	Repair	0.00 F	*- F
76	1		<b>*VESS CONTROL UNIT - FRT</b> (WCP)	* Check	700.00 F	*- F
77	1		<b>*FRT RH WHEEL HOUSE PANEL</b> (NPA)	Repair	0.00 F	*- F
78	1		<b>*INLET 3 WAY VALVE</b> (WCP)	* Check	760.00 F	*- F
79	1		<b>*ERP STICKER</b>	Necessary	12.00 FS	*12.00 FS
80	1		<b>*IU BRACKET</b>	Necessary	15.00 FS	*15.00 FS
81	1		<b>*PHV DECAL</b>	Necessary	20.00 FS	*20.00 FS
82	1		<b>*FRONT NUMBER PLATE AND CASING</b>	Cracked	40.00 FS	*40.00 FS
83	1		<b>*FRONT WINDSCREEN GLASS SEALANT</b>	Necessary	40.00 FS	*40.00 FS
84	1		<b>*COOLANT</b>	Necessary	25.00 FS	*25.00 FS

F=Franchise part. S=SpcNett.

<b>Sub Total (\$\$)</b>	<b>29,145.16</b>	<b>7,488.87</b>
<b>+ Margin on L,N Items 10.00/10.00% (\$\$)</b>	2,899.32	733.69
<b>Total Parts (\$\$)</b>	<b>32,044.48</b>	<b>8,222.56</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TOWING FEE	New	60.00	60.00
2	TO CONNECT & DISCONNECT ELECTRICAL POWER	New	250.00	100.00
3	TO REMOVE AND REPLACE RADIATOR INCLUDNG REFILING COOLANT	New	120.00	80.00
4	TO REMOVE AND REFIX AIR COND CONDENSOR INCLUDING TOP UP AIR COND GAS	New	200.00	100.00
5	TO REMOVE & REFOCUS FRONT HEADLAMP	New	80.00	30.00
6	TO CHECK STEERING GEOMETRY & CONDUCT COMPUTER WHEEL ALIGNMENT	New	120.00	0.00
7	TO MOUNT VEHICLE ONTO WORK BENCH TO CARRIAGE MANUFACTURE SPECIFICATION (* Check)	New	250.00	0.00
8	TO REMOVE & REPLACED FRONT WINDSCREEN GLASS & SEND FOR PHV DECAL STICKER	New	150.00	120.00
9	TO HOIST OUT ENGINE IN ORDER TO FACILITATE REPAIR TO FRONT CHASSIS & REFIT BACK ENGINE BAY. TO WIRING CHECK & RECTIFY WHERE NECESSARY INCLUDING REPLACING ENGINE WIRING HARNESS (* Check)	New	680.00	0.00
10	TO REMOVE & REFIT CAR SEAT AND REPLACED SEAT BELT	New	250.00	200.00
11	TO APPLY RUSTPROOFING & TUFFCOATING TREATMENT ON THE REPLACED PARTS	New	200.00	40.00
12	TO PERFORM SRS SYSTEM CHECK INCLUDING DIAGNOSTIC & CLEARING FAULT CODES	New	250.00	200.00
13	TO REMOVE OUT ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL WHERE NECESSARY	New	2,000.00	800.00
14	TO PUTTY & SPRAY PAINT ON THE FRONT BONNET, FRONT BUMPER, BOTH FRONT FENDER, BOTH FRONT DOOR & LHS REAR DOOR	New	1,300.00	1,000.00
15	TO REMOVE & REPLACED DRIVER & PASSENGER AIR BAG, SRS & DASHBOARD	New	450.00	200.00
<b>Gross Labour Cost (\$\$)</b>			<b>6,360.00</b>	<b>2,930.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >